N521RM

1977 Cessna 421C

Airframe Logbook #8 of 8 2019 - 2024

MSN: 421C-0335



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



AIRFRAME MAINTENANCE RECORDS



AIRFRAME MAINTENANCE RECORDS

Log No. 🖊

| AIRCRAFT REGISTRATION No. N. N. SZIKM | |
|---------------------------------------|--|
| MANUFACTURER CESSWA | |
| Model 4/2/ | |
| SERIAL No. 421C 0335 | |

| | | | | PAGE NO | |
|--|--|---|--|--|--|
| TOTAL TIME IN | | TACH OR RECORDING METER TIME | DESCRIPTION OF WORK PERF | FORMED - IO. OF PERFSON PERFORMING WORK | |
| MODE S/N. 4 REG. WOR | E: Cessna EL: 421C 121C0335 NO N52 K ORDER | 16321 Add Addision, 7 Phone: 972 | o Mechanix Inc. ison Rd. Ste. 150 Fexas 75001 2-250-2403 | DATE: 1/29/2020 A/C TSN: 8746.3 HOBBS: 802.6 | |
| | me Entri | | | | |
| Remo Secu MS2* Retor Comp hours Instal Wipe Comp | oved, CI red L/H 1919WD qued all olied with or 30 d led new d out are olied with | eaned and install & R/H engine ma G23 I heater duct clan h AD 2000-01-16 lay s whichever o fuel probe gaske | nps in nose baggage compartme part b Exhaust visual inspection ccurs later. et on L/H locker tarrk sending unit power pack with inineral spirits, MEB85-1/right side crack curr | ent n (Left & right engine), next due in 50 | |
| DATE | . 1/29/20 | 20 SIGN | ED moreus | Work Order: 7475-12-2019 | |

AIRFRAME LOG ENTRY

J.R AVIATION SERVICES

15790 DOOLEY RD

ADDISON, TEXAS 75001

AIRCRAFT REG: N521RM

DATE: 06/10/2020

MFG: Cessna

MODEL: 421C

SERIAL NO.: 421C0335

HOBBS: 0826.7

Wir G. Cessila

Printed by EBis 3 (datcomedia com)

A.F.T.T.: 8721.9

- Complied with Annual Inspection for Cessna 421C, S/N 421C0335 IAW 14 CFR Part 43, Appendix D.
- Complied with Airworthiness Directive research on Airframe. Current through Bi-weekly 2020-12.

I certify this aircraft, engine, propeller and/or component identified above was repaired and/or inspected in accordance with current F.A.A. regulations and was determined to be in airworthy condition and approved for Return to Service with respect to work performed.

Dated: JUNE 10, 2020 Signed

_Martin J. Sisk A&P 2820585 I.A

AIRFRAME LOG ENTRY

J.R AVIATION SERVICES

15790 DOOLEY RD

ADDISON, TEXAS 75001

AIRCRAFT REG: N521RM

DATE: 06/10/2020

MFG: Cessna

MODEL: 421C

SERIAL NO.: 421C0335

HOBBS: 0826.7

A.F.T.T.+8721.9- \$770.4

- Complied with 100 hrs Inspection for Cessna 421C S/N 421C-0335 IAW 14 CFR Part 43, Appendix D.
- Complied with Airworthiness Directive research on Airframe. Current through 2020-12.
- Complied with AD 2000-01-16 Exhaust IAW part b,c,e by visually inspection ,pressure test and tail pipe inspection on left and right system.
- Complied with AD 2016-17-08 Elevator Trim Push pull hardware replacement IAW Cessna MEB-27-02R1, Repetitive inspection not to exceed 100 hrs TIS or 12 months whichever occurs first.
- Complied with AD 2004-21-05 pressure decay test IAW para.E(1). No defects noted at this time next due in 24 months or 100 heater hours.
- Repaired left engine top cowling with a patch 6x8 using 2024T3 .032 aluminum. Work performed using AC 43.13-18 chapter 4 as reference.
- Complied with chapter 14 CFR part 91.207 (d) ELT P/N C589511-0117 S/N 34096 12 month check .Replace ELT battery P/N BP1020 Next battery due JUN 22
- Replaced vacuum regulator filters .P/N RAB3-5-1
- Performed vacuum manifold valve inspection no discrepancies noted at this time.
- Installed new air-condition hydraulic filter perform leak and operation check good. P/N AN6255-3A
- Weighed and inspected cabin handheld fire extinguisher Model A385,S/N V-732018 no discrepancies noted next inspection 05/30/2021
- Replaced left wing loose rivets as required at lower wing skins in front of gear door AN470-4- series.
- Installed new air box seals at left and right engine top cowlings P/N 5155168-7
- Installed new left engine aft beam upper cap use AC43.13-1B chapter 4 for reference. P/N 5054030-34
- Repaired left engine top cowling middle cross over channel support by installing patch using 2024T3 .032 aluminum.
 AC 43 13 1B chapter 4 as reference.
- Repaired left engine bottom middle bulkhead channel rib with patch 2x3 inches using 2024T3 .032 aluminum metal use AC43.13-1B as Reference.
- · Fabricated new right engine metal drain line using aluminum tubing.
- Fabricate new right engine waste gate drain line using aluminum tubing.
- Repaired left nose steering cable pulley bracket with a patch 2x2 inches using 2024T3 .032 aluminum metal use
 AC43.13-1b as reference.
- Straightened lower cabin door handle and reset step hinge pin back and replace hardware.
- Installed new o rings at right wing fuel bowl drain P/N MS29513-10
- Installed new pressure supply ducts on left wing P/N CM3211-10B9.5, CM3211-10B36.0
- Installed new emergency door seal. P/N R581559
- Cleaned all corrosion under cabin potty floor boards and ribs and treat area and prime use AC 43.13 13-1b chapter 4 as reference.
- Installed new area washer at left outboard engine nacelle skin tall pipe hold down bracket.
- Installed new cherry max rivets on right wing locker side nacelle outboard fairing. P/N CR3213-4-2
- Lubricated both engines alternate air cables and air box sleeves as needed perform operation check good.
- Repaired pilot floor board with a patch 3x5 inches using .032 aluminum metal and install new rive nuts for scuff plates use AC 43.13-1B chapter 4 as reference.
- Replaced aft belly drains P/N CM3575-4
- Repaired right wing aft skin landing gear wheel well edge with patch 3x5 inches using 2024T3 .032 aluminum metal uses AC 43.13-1b chapter 4.
- Resealed right wing fuel tank bottom inboard rivets with AMS-S-8802 B ½ sealant performed leak check good.
- Lubed both ailerons outboard bearings and adjusted stops.



AIRFRAME LOG ENTRY

| 1 | ı R | A\/ 1/ | MOITA | SERV | /ICES |
|---|-----|---------------|-------|------|-------|

15790 DOOLEY RD

ADDISON, TEXAS 75001

- Resealed left wing bottom inboard small fuel tank panel withAMS-S-8802 B1/2 sealants performed leak check good.
- Resealed right main brake caliper and bleed brakes. P/N 101-23200
- Installed washers on left hand side inboard flap scissors to clear rib and remove play. P/N NAS1149F0463P
- Complied with service bulletin MEB85-11 right side crack currently measuring .265, within limits at this time. SB compliances due again in 50 landings.
- Installed new shim washers at left and right main landing gear trunnion to remove play. P/N 0841004-3
- Adjusted left and right main wheel toe in and camber by adding washers in accordance with Cessna
 421C service manual instructions
- Installed new right main tire and inner tube. P/N 650C06-3,M650-010
- Lubed parking brake cable as needed performed operation check good.
- Installed new brake linings on both main wheels. P/N 066-06600
- Installed new inboard and outboard exhaust slip joints pipes. P/N 1001-3
- Installed new right hand engine exhaust wye pipe P/N 9910300-7,2570-1,2570-2
- Repositioned right engine exhaust tail pipes perform leak check good.
- Resized left engine exhaust risers slip joints at cyl#5 and #3 cleaned and lubricate and reinstalled exhaust risers with new gaskets. P/N 628260
- Installed serviceable right engine exhaust riser assembly with new gaskets. P/N 9910295-16,628260
- Repaired left engine top cowling middle cross over support channel fabricate and installed patch using 2024T3 .032 aluminum metal 4x10 inches use AC 43.13 13-1b as reference.
- Replaced engine monitor with new unit G4.P/N1200C-001 S/N 50640.

I certify this aircraft, engine, propeller and/or component identified above was repaired and/or inspected in accordance with current F.A.A. regulations and was determined to be in airworthy condition and approved for Return to Service with respect to work performed.

Return to Service with respect to work performed.

Dated: JUNE 10, 2020 Signed

JUAN MORALES A&P 2840494

SUB-TOTALS THIS PAGE

Hour Meter: 838.4

Date: 07/13/2020

PAGE No. FLITE ELECTRONICS, INC. 4786 AIRPORT PKWY ADDISON, TX 75001-3363 DG2R767K LOG ID# 5320 09-June-2020 WO# 19553/1 REF# 19553 Document# FL13 AC TT 826.0 S/N 421c0335 CESSNA 421c Pg 1 4 DISCREPANCY: Perform FARs.
Model: N/A Part#: N/A Serial#: N/A
ACTION: Removed pilots altimeter p/n 43300-6128 s/n 1243 (task 2), co-pilot altimeter p/n 5934PA-3
A:86 s/n 410691 (task 3), #1 encoder p/n 550120-304-R5232 s/n SRA8720 (task 4), #2 encoder p/n
SSD120-30A s/n A57131 (task 5), #1 transponder p/n U11-00455-60 s/n 84124933 (task 6), and #2
transponder p/n 011-00259-00 s/n 83200686 (task 7) from aircraft for certification. Reinstalled
equipment after certification. Performed 91.411 & 91.412 certification of aircraft. All checks DISCREPANCY: Certify altimeter. Model: EA-801A Part#: 43300-6128 Serial#: 1243 ACTION: Certified altimeter to 35K ft in accordance with FAR 43 Appendix E sub-paragraph (b). All check normal. DISCREPANCY: Certify altimeter.
Model: 5934 Part#: 5934PA-3 A.86 Serial#: 410691
ACTION: Certified altimeter to 35K ft in accordance with FAR 43 Appendix E sub-paragraph (b). All checks normal. DISCREPANCY: Checkk encoder.
Model: SSD-120 Part#: SSD120-30A-RS232 Serial#: SRA-8720
ACTION: Checked encoder to 30K ft. No problems found. All checks normal. DISCREPANCY: Check encoder. FLITE ELECTRONICS, INC. 4786 AIRPORT PKWY ADDISON, TX 75001-3363 DG2R767K LOG ID# 5320 09-June-2020 WO# 19553/1 REF# 19553 Document# FL13 AC TT 826.0 S/N 421c0335 N521RM CESSNA 421c Pg 2/2 Model: SSD-120 Part#: SSD120-30A Serial#: A57131 ACTION: Checked encoder to 30K ft. Found altitude error increasing with altitude. Calibrated encoder. Encoder function check normal. DISCREPANCY: Certify transponder.
Model: GTX-330ES Part#: 011-00455-60 Serial#: 84124933
ACTION: Checked transponder. No problems found. Transponder function check normal. DISCREPANCY: Certify transponder.
Model: GTX-320 Part#: 011-00259-00 Serial#: 83200686
ACTION: Function checked transponder. No problems found. All checks normal. DISCREPANCY: Install customer FlightStream 210.
Model: FLIGHTSTREAM 210 Part#: 011-03257-40 Serial#: 3RE007683
ACTION: Installed FlightStream 210 Bluetooth Gateway coupled to #1 GNS-430W. All equipment installed in accordance with manufacturers instructions and in accordance with AC 43.13-1B/2B. Revised weight, balance and equipment list. FlightStream 210 was installed as per 337 and STC SA01933LA-D. The aircraft identified was repaired and/or inspected in accordance with current Federal Aviation Administration regulations and is hereby approved for return to service with respect to work performed. D628767K Marsh 6-9-2020

PROFESSIONAL AIRCBAFT SERVICE 7929 Karl May Dr. Waco, Texas 76708 CRS No. AK6R541N

1...

Cessna S/N 421C 0335 N521RM

On above referenced aircraft, installed customer supplied insight fuel flow signal converters. Installed new left engine #6 probe P/N 2870 S/N 170983. (See 8130-3. Aircraft approved for return to service for maintenance performed. Pertinent details are of file under work order 5090.

ressions, inc. CKS# AK6R541N

| | | | | | | PAGE No | | |
|---------------------------|---|----------|--|--|--|--|--|--|
| DATE | TOTAL TIME IN SERVIC | E | TACH OR RECORMETER TIME | DING | | OF WORK PERFORMED - CERTIFICATE NO. OF PERFSON PERFORMING WORK | | |
| | | | | | Mid | l-Stream Avionics Solutions | | |
| <u> </u> | | | | | | 121 Airport Ln | | |
| | | | | | | Mena, Arkansas 71953 | | |
| | | | | | | 479-216-9353 | | |
| | | | | N: <u>A</u> | <u> 1521RM</u> Make: <u>Ce</u> | <u>ssna</u> Model: <u>421C</u> S/N: <u>421C0335</u> Date: <u>08/26/2020</u> | | |
| | | | Bank, Ga Custom integra supplied STC SA04 fan and US and App | armin FS210, Garni er supplied Garmi sted to Cessna 800 Avidoyne IFD550 4046CH as an app BB I.A.W IM 100 groval of installed data referenced at | min GTX320, Garmin Ohin G-600 PFD/MFD syste B IFCS Auto-Pilot with v I.A.W STC SA00343B0 roved standby attitude, al -M Rev B Approved by N items, See Weight and Br bove. Post installation grouped to show compliance | s, Aurspeeds, Altmeters, VSI's, Clocks, Standyby CDI's(K1204, K1209), Co-Pilot Turn And M2200, L3 WX950 Head, 2x Trans Cal SSD120 encoders, and Garmin GNS430W Installed mit that includes GDU620, GRS77, GDC74, GMU44, GAD43e LAW STC SA021531A-D retricted and lateral coupling and displaying Flight director information. Installed Customer to as the number one GPS/Nav/COM system Installed Customer Supplied L3 ESI-500 LAW. Initiade, aurspeed, and GPS/Nav/COM system Installed Gustomer Supplied L3 ESI-500 LAW. ORSEE letter given Sept 26,2016. See FAA Form 337 dated Aug 26, 2020 for items removed alance dated 08/26/2020 also contains items removed and installed. All work was performed build be shared by the standard of the standard o | | |
| | | | - | | | Nathan Cine Ar 2900700 | | |
| | | | | | | | | |
| - | Date | Tir I | otal me n vice | | Recording Meter Time 847.1 | RAM Aircraft, Limited Partnership • Waco Regional Airport | | |
| 1 | 0/28/2020 | | | | | | | |
| - fo - m - e - N | Above referenced aircraft installed RAM FAA/PMA 1719-3 synchrophase system. See 337 and attached 8110-3 for approval. Installed new RAM FAA-PMA throttle cables P/N 1220-37 on left engine p/n 1220-38 on right engine, mixture cables P/N1220-39 on left engine p/n 1220-40 on right engine, propeller cables P/N 1220-41 on left engine. Installed prop cable p/n 9910272-48 on right engine. Negligible weight and balance change. Installed new engine. Installed prop cable p/n 9910272-48 on right engine. Negligible weight and s/n 160041. Installed new GEM McCauley propeller governors DCFS290D9/T6 left hand s/n 160038, right hand s/n 160041. Installed new GEM harness p/n 332460 on left and right engine. Aircraft is approved for return to service for the work performed. Pertinent details on file under Project No. 9658. RAM Aircraft, Limited Partnership, P.O. Bex 5219, Waco Texas 76708 CRS VA1R551K | | | | | | | |
| | | | | | | | | |
| | | _ | | | Sup-To | TALS THIS PAGE | | |

Totals - Carry forward to NEXT PAGE

| | | | Page No | |
|----------------------------------|---|--|--|---|
| DATE | TOTAL TIME IN | TACH OR RECORDING METER | DESCRIPTION OF WORK PERFORMED - SIGNATURE & CERTIFICATE NO. OF PERFSON PERFORMING WORK | 1 |
| | Waco, 7 CRS No | arl May Dr. Texas 76708 . AK6R541N | Hour Meter: 860.7 Date: 03/24/2021 Cessna S/N 421C 0335 N521RM | |
| | engine #4 EC | GT probe P/N 28' peturn to service for the ser | establed new bulb for nose downlock light and reset socket. Installed new left 70. Rigged all engine controls and performed set up adjustments. Aircraft r maintenance performed. Pertinent details are on file under work order 5219. | |
| | | | | |
| AIR | MPRESSIONS | | | - |
| | 7929 Karl Ma Waco, Texas 7 CRS No. AK61 | 76708 | Hour Meter: 866.1 Date: 04/01/2021 Cessna S/N 421C 0335 N521RM Aircraft TT 8,8099 | |
| On RA (see engi Pert | above referen | ced aircraft, rem or testing. Instal s). Reinstalled robe, P/N 2870. re on the under v | oved both prop governors and RAM prop sync computer and sent to led 2 ea) new governors, P/N D20741-2, S/Ns 160042 and 160043 prop sync box after no defects found by RAM. Installed new left work order 5227. | |
| | | | | |
| | | | | |
| | | | | |
| | | | SUB-TOTALS THIS PAGE | |



7929 Karl May Dr. Waco, Texas 76708 CRS No. AK6R541N
 Date:
 05/26/2021

 Aircraft HM:
 869.9

 Aircraft TT:
 8813.6

 Heater HM:
 00.0

Cessna S/N 421C-0335 N521RM

On above referenced aircraft, removed all inspection plates and panels for Annual Inspection. Checked all pulleys, bellcranks, cables and fairleads. Checked all flight controls for security and movement. Inspected all wing, tail and landing gear attach points. Inspected all aircraft lighting and electrical. Ran gear retraction test per Cessna Service Manual. Inspected wheels, tires and brakes. Inspected fuel, hydraulic lines and fittings. Installed new gears for right landing light and operational tested. Installed new left elevator mount bearings. (See 8130-3 forms.) Installed new bushing and bolt for rudder trim tab horn. Re-bonded spoiler line supports in flap wells. Installed new hinge pin for left main gear door to eliminate free play. Installed new outboard rod ends for left and right main gear doors. Installed new left main tire. Adjusted vacuum regulators. Saftied crossfeed fuel drains. Inspected right main gear forward Trunnion mount per MEB-85-11 and found crack to be within limits. (Inspect crack length each 50 landings per MEB85-11.) Installed new plenum duet for cabin heater and sealed numerous wire bundles to eliminate pressurization leaks. Installed overhauled heater assembly P/N 13E55-1 S/N 2791119. (See 8130-3.) Installed new "O" time heater hour meter. Installed new right brake caliper shim. Installed new keylock for nose gear actuator rod end and rigged per Service Manual. Removed cherry max rivets from left engine bulkhead top cap and installed solid rivets per Service Manual. CW A.D. 2000-01-16 per paragraphs (b), (c), (d), and (e) inspections. (Paragraph (b) compliance due in 50 hours or 30 days whichever is later.) C/W A.D. 2016-17-08 per inspection of elevator trim tab hardware. (Due each 110 hours or annual.) C/W A.D. 2004-25-16(R1) per inspection of heater fuel regulator. (Due each 100 hours or annual.) Tested ELT unit per FAR 91.207(d) requirements. (Battery next due 6/2022.) All A.D.'s researched through biweekly 2020-10. (See A.D. listing for all current and future compliance times.) All above work done in accordance with Cessna Service Manual and Air Impressions, Inc. 100 Hour/Annual Inspection Checklist. Aircraft approved for return to service. Pertinent details are on file under work order 5237

Air Impressions, Inc. CRS# AK6R541N

| | 7929 Karl May Dr. Waco, Texas 76708 CRS No. AK6R541N | I certify this Aircraft has been inspected in accordance with a Annual Inspection and has been determined to be in an airworthy condition. DATE 05/26/2021 HM 869.9 AIRCRAFT TT 8813.6 WORK ORDER #5237 SIGNED AIR IMPLESSIONS, INC REPAIR STATION # AK6R541N | |
|--|--|---|--|
| | SUB-TOTALS THIS | PAGE | |
| | | FORWARD TO NEXT PAGE | |

2850 Airport Blvd. Abilene TX 79602

Abilene Aero Inc. Registration N521RM Aircraft S/N: 421C0335

Hobbs Time: 897.3

Date: 7/12/2021 W.O. # 22166 /N LDCB1X2-T nts, hardware

|) AT | Installed NGT9000R (D) HW P/N 9029000-40000 S/N LXE14963 as #1 Transponder, GPS Splitter P/N LDCB1X2-T S/N 137682, PIM-9000 P/N 9230-17005-01 S/N 20612, Transponder 1/2 switch and associated mounts, hardware and wiring IAW L3 Install Manual P/N 0040-17001-01 Rev. W, STC# SA02444AK. Ground checked IAW M/M Repaired Ident switch as needed, op checked IAW M/M. | | | | | | | |
|---------|--|--|--|--|---|--|--|--|
| _ | The Dual Pitot / Static, Altimet found to comply IAW PART 43 (ADS-B Out). Systems were to | 3 Appendix E and F, | | 91.413, and Part 91.227 | | | | |
| | Pilots Altimeter S/N:1CM0326 Transponder #1 Model NGT96 | 000R S/N: LXE1496 | Copilots Altimeter S Transponder #2 Mo | /N: 1925 del GTX-330ES S/N: 84124933 | - | | | |
| _ | Encoder Model GDC S/N: 206 | | tent Down | > | | | | |
| _ | | | art Douglas roved for Return to Service | | _ | | | |
| _ | | For A | Abilene Aero Inc. GSTR469E | | - | | | |
| _ | 1 1 | 1 | | - | | | | |
| | | | | | | | | |
| _ | LOG ID# 1341 20-August-20 |)21 WO# 18462 | ourt Road Denton, Texas 76207 | | | | | |
| _ | N521RM S/N 421C0335 | Cessna 421C | | Pg 1 / 1 | _ | | | |
| _ | **** ITEM # 18462-2 LH main DISCREPANCY: LH Main Tire L | n tire leak **** | | | | | | |
| _ | ACTION: Removed Wheel Assembled and | bly. Disassembled am d Repacked Bearings | nd Removed Inner Tube. Replaced with Grease. Reinstalled Wheel | Inner tube PN: Assembly. IAW: Cessna | | | | |
| | 421 Service Manual Section | • | | i i | | | | |
| _ | Signed A&P 3936528 IA Kev | in Roberts | 20 Aug 21 | | | | | |
| _ | I I | I NODEL CS | Date | | | | | |
| - | | | | | _ | | | |
| _ | Aerospace Instrument Support LOG ID# 1437 07-February-20 | , Inc. 1750 Westcou | urt Road Denton, Texas 76207 XI | 7R807J —— | _ | | | |
| _ | | Cessna 421C | | Pg 1 / 2 | _ | | | |
| | **** ITEM # 18927-1 Coms Into | ermittent INOP Xmit | & RCV **** | | | | | |
| | ACTION: Tested and verified. coms. Bench checked both coms. | t to INOP Xmit & RC Testing for frequenc . both coms reading | & RCV **** V cy drift. Found Frequency was of well within tolerance. Removed off in A/C. See Item 2 & 6 for hing Panel **** el | f .08 Khz on both | | | | |
| • | to both coms. #1 Com reading **** ITEM # 18927-2 Remove O DISCREPANCY: Remove Old Unused | good. #2 Com still Id Unused Wiring Bel | off in A/C. See Item 2 & 6 for hing Panel **** | repair. | | | | |
| • | ACTION: After removing center panel that was not tied up or | panel to check for capped and stowed. | lose connections, found old unu Removed Avionics equipment | sed wiring behind | _ | | | |
| | access to wiring. Removed exce properly crimped and making po | ess old wiring. Four oor connections. Rem | nd BNC on NAV, GPS, COM coaxes to moved and replaced 10 BNC Male a | ter panel to gain hat were not ind Female connectors | _ | | | |
| | Found several ground wires mis density pins on several nins | #1 IFD-540 and #2 I sing and shield gro | IFD-440. Removed and replaced BN Dunds not connected. Found 20 AW | C to GTX-330ES. G pinned into high | | | | |
| | Manuals. Found several wires t associated radios. Retied up w | hat had poor routing iring behind panel | ng, reworked wiring and rerouted and reinstalled avionics racks | as needed to | _ | | | |
| | removed avionics. Systems have Associated Install Manuals. AT Appenedix F as required by FAR | been tested IAW AS C #2 Transponder ha | ssociated Install Manuals and fo as been tested and found to comp | und to operated IAW | _ | | | |
| | **** ITEM # 18927-4 Install C DISCREPANCY: Install Customer | UST USB Power Ports USB Power Ports | ling Panel and person of the p | | | | | |
| 1 | NCIION: Installed and wired Cu 201290, 001292 and all associa right sidewall and left sidewa | stomer provided Str ted mounts, hardwar 11. Installed 1 | ratus power ports P/N: 153510-00 re and wiring. Installed 2 aft p lower right of center panel. In | 0169, S/NS: 001225, assenger USB in | | | | |
| | and , and b) dema | Andemired I in | ioner right of center panel. In | stallation and | | | | |
| | | | | | | | | |
| | Ī | ı | | | _ | | | |
| | | | | | _ | | | |
| | | | S THIS PAGE | | _ | | | |

| Aerospace Instrument Support, Inc. 1750 Westcourt Road Denton, Texas 76207 XI7R807J | |
|---|--|
| LOG ID# 1437 07-February-2022 WO# 18927 N521RM S/N 421C0335 Cessna 421C Pg 2/2 | |
| HOBOS: 1038,2 | |
| testing done IAW Stratus Power Pro Install Instructions Doc. No.: 600840-000063. **** ITEM # 18927-5 Pass left sidewall vent repair **** DISCREPANCY: Pass Left Sidewall Vent Repair ACTION: While installing Power Ports in left sidewall, found vent no attatched to sidewall, Made a doubler bracks. | |
| Attached doubler, and re-installed vent. **** ITEM # 18927-6 Install Com Antenna **** DISCREPANCY: Install Com Antenna ACTION: After troubleshooting #2 Com, found IFD-440 was not putting out any power and frequency was being pulled. Traced #2 coax to aft section, uable to locate #2 Com antenna. Install Com Antenna P/N CI-121, S/N 511074. Installed IAW CI-121 Install Drawing and AC-43.13-18 Sect. 6-134. COAX to CI-121. Reinstalled coax to #2 Com. System op checked good IAW IFD-440 Install Manual. | |
| Signed XI7R8 P73 Bobby Faulks Date | |
| | |
| Aerospace Instrument Support, Inc. 1750 Westcourt Road Denton, Texas 76207 XI7R807J | |
| LOG ID# 1515 22-July-2022 WO# 19266 HOBBS 1091.7 N521RM S/N 421C0335 Cessna 421C Pg 1/5 | |
| **** ITEM # 19266-1 annual inspection **** | |
| ACTION: Completed Annual Inspection Aircraft has been inspected and Found in an Airworthy Condition. Discrepancies have been noted and worked in this work order. Completed Scheduled Servicing. Completed Functional Checks of Landing Gear, De-Ice Boots, and Fuel Systems. IAW: Current Cessna 421C Service Manual Section 2 and 14 CFR 43 Appendix D | |
| **** ITEM # 19266-2 RH main gear light bulb burnt out **** ACTION: Removed main gear annunciator and installed new main gear annunciator. Performed Ops check, Ops Check SAT. Work performed IAW current Cessna 421 service manual 4-70-01 | |
| **** ITEM # 19266-3 RH tachometer inop **** ACTION: Removed RH Tach Generator PN: H60-050 SN: 291543, installed overhauled tach generator PN: H60-050, SN: AE50304 IAW current Cessna Model 421C Series AMM Chapter 7. | |
| **** ITEM # 19266-4 standby alttitude battery cal due **** ACTION: Started Standby ATT Battery Cal ESI-500. Battery at 88%, needs to be @ 98% before test can begin. Battery would only charge to 92%, battery calibration failed. Battery needs to be replaced. | |
| **** ITEM # 19266-7 RH #1 EGT inop **** ACTION: Removed and replaced RH engine #1 EGT probe P/N: 2870. Work performed is IAW current Insight Graphic Engine Monitor manual Pg: 96 | |
| **** ITEM # 19266-9 prop de-ice ammeter is too high **** ACTION: Carbon Brushes found to have broken wires and worn beyond limits, see line Slip Ring Brushes | |
| | |
| | |
| | |
| Aerospace Instrument Support, Inc. 1750 Westcourt Road Denton, Texas 76207 XI7R807J | |
| | |
| Line Item | |
| **** ITEM # 19266-10 Nose tire worn **** ACTION: Removed old tire p/n: 606c66-8. Replaced with new tire p/n: 072-314-0 s/n: 1325T00008. Work performed IAW current Cessna 421 maintenance manual 4-41&4-42 | |
| **** ITEM # 19266-11 annunciator test shorted wire **** ACTION: Repaired Shorted Wire | |
| **** ITEM # 19266-14 RH EGT/CHT Wiring Harness Burnt **** ACTION: Replaced engine monitor wiring harness IAW current G4 Insight engine monitor installation manual. | |
| **** ITEM # 19266-15 RH Alternator Capacitor Broken **** ACTION: Found CR7 wire broken during inspection. Repair wiring to to CR7 Diode / Resistor assembly. Tied CR7 up into wiring bundle. Op checked IAW Current Cessna 421 Service Manual. | ************************************* |
| **** ITEM # 19266-16 ELT Battery Expires June 22 - Replace **** ACTION: Removed ELT, removed internal battery P/N: BP-1020 S/N: 34096. Replaced with new battery P/N: BP-1020 S/N: 34096. Expiration AUG 24. Performed Ops check, Ops check good. Reinstalled ELT, Complied with current 14 CFR 91.207(d) | |

**** ITEM # 19266-17 Fuel Leak Under RH Wing ****
ACTION: Defueled Aircraft. Removed Sealant, Removed Incorrect Rivets and Replaced with Correct

| Nerospace Instrument Support, Inc. 1750 Westcourt Road Denton, Texas 76207 XI7R807J LOG ID# 1515 22-July-2022 WO# 19266 HOBBS 1091.7 N521RM S/N 421C0335 Cessna 421C | Pg 3 / 6 |
|--|------------|
| vets. Resealed and Fueled Aircraft. Leak Check Good. IAW: Current Cessna 421C Service Manua | 1 |
| ** ITEM # 19266-18 Replace Nose Avionics Cam Locks **** ITON: Installed new camlocs PN: 2700-35 and 2700-55 with new camloc retainer rings PN: 2600 Irrent Cessna 421C Series MM. | -LW IAW |
| *** ITEM # 19266-19 76-13-07 fork bolts required **** TION: N/a by Model and Serial Number. | |
| ** ITEM # 19266-20 2018-03-03 fuselage required **** TION: Complied with AD: 2018-03-03 by Inspection of Carry Through Spar. IAW: Current SID 57 | -10-14 |
| *** ITEM # 19266-21 2016-17-08 elevator tab control system **** TTION: Complied with AD: 2016-17-08 by Inspection of Elevator Tab Control Push Rod and Hardw NW: Current MEB27-02 Next Due In 100 Hours | |
| *** ITEM # 19266-22 2000-01-16 exhaust system **** CTION: Complied with AD 2000-01-16 by Visual Inspection of Exhaust System. Next Due in 100 H | ours |
| *** ITEM # 19266-23 95-09-13 fuel inlet float valve **** CTION: Complied with AD: 95-09-13 by Operational Check of Fuel Float Valves. IAW: Current ME ext Due in 200 Hours | |
| *** ITEM # 19266-24 RH tire worn to bottom of groove **** | |
| | |
| • | |
| Aerospace Instrument Support, Inc. 1750 Westcourt Road Denton, Texas 76207 XI7R807J LOG ID# 1515 22-July-2022 WO# 19266 HOBBS 1091.7 N521RM S/N 421C0335 Cessna 421C | Pg 4 / 5 |
| SCREPANCY: RH tire worn to bottom of groove, inboard only TION: Removed both LH and RH wheel outboard bearing Timken PN: 07100-20629. Greased and inst w (x2) each Timken bearing PN: 07100-20629. IAW current Cessna 421 maintenance manual 4-41. justed RH main landing gear toe-out IAW current Cessna Model 421C AMM Chapter 4. | alled |
| ** ITEM # 19266-25 LH and RH main wheel linings worn **** TION: Installed new brake linings (x16) each PN: RA066-06600 on both LH & RH brake calipers rrent Cessna Model 421C AMM Chapter 4. | IAW |
| ** ITEM # 19266-29 SR carbon brushes broken wires **** SCREPANCY: slip ring carbon brushes have broken wires on both LH and RH engines TION: Installed all new carbon brush assy (x4) each PN: RAB40012 on both LH and RH engines Irrent Cessna Model 421C AMM Chapter 8-20. | TAW |
| ** ITEM # 19266-30 landing gear down lock indicator **** TION: Removed old down lock indicator and installed new indicator P/N: 9910115-3. Performed leck, ops check SAT. Work performed is IAW current Cessna 421 service manual 4-70-01 | ops |
| ** ITEM # 19266-31 Fire extinguisher cartridges due **** TION: Replaced squibs on both LH and RH engines, RH squib installed P/N: AE13083-5, S/N: 876 WJ). LH squib installed P/N: AE13083-5, S/N: 8762. Exp date 3/1/2032. Work Performed is IAW Brrent Cessna 421 maintenance manual 7-90-04 | 51 |
| ** ITEM # 19266-32 #2 & #6 EGT on RH #5 & #6 on LH EGTS **** | |
| | |
| Nerospace Instrument Support, Inc. 1750 Westcourt Road Denton, Texas 76207 XI7R807J OG ID# 1515 22-July-2022 WO# 19266 HOBBS 1091.7 | |
| 1521RM S/N 421C0335 Cessna 421C | Pg 5 / 5 |

Signed A&P 3936528 TA Kevin Roberts

7/22/2022 Date

SUB-TOTALS THIS PAGE

| wo: WO_20 Airframe · page 1 of 1 | |
|---|------------------|
| Hosss: | |
| 1,29.5 GENERATION JETS - 205 West Louisiana Street suite 201 - McKinney, TX 75070 - 8175643267 | |
| N521RM CESSNA, 421C, S/N: 421C0335 October 07, 2022 | |
| Battery replaced IAW Cessna 421 service manual Chapter 13-21, engine run completed post installation ops check without discrepancy. PN RG24-20 Installed P/N RG24-20 - Battery, Sealed. | |
| With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with GENERATION JETS under work order: WO_20. | |
| Bryan Waldo A&P 3730638 | |
| | 1 |
| | |
| wo: WO_23-07 Airframe · page 1 of | 1 |
| #08%s!], 147.9 | |
| GENERATION JETS - 5318 Airport Drive - Denison, Texas 75020 - 8444436538 | |
| N521RM CESSNA, 421C, S/N: 421C0335 January 26, 2023 | |
| Repacked and resealed RT MLG strut IAW Cessna 421C service manual. Complete full servicing of LT and | ! |
| RT MLG struts. All leak checks good at this time. Installed (2) P/N A2749 - Seal Wiper, Installed (2) P/N MS28776M2-22 - SCRAPER, Installed (2) P/N MS28775-222 - PACKING, Installed (2) P/N MS2875-010 | . — |
| PREFROMED PACKING SEAL O-RING, Installed (4) P/N MS28775-229 - PREFROMED PACKING SEAL O-RING, Installed (4) P/N MS2875-228 - PREFROMED PACKING SEAL O-RING. | - |
| With respect to the work performed, this airframe is approved for return to service. Details of work per- | |
| formed are on file with GENERATION JETS under work order: WO_23-07. | |
| 1/3/1/2 | |
| Bryan Waldo A&P 3730638 | |
| | |
| wo: WO_23-11 Airframe · page 1 o | f 1 |
| Hopes: Lieua | |
| #0135: 1,154.9 GENERATION JETS - 5318 Airport Drive - Denison, Texas 75020 - 8444436538 | |
| N521RM CESSNA, 421C, S/N: 421C0335 February 27, 2023 | |
| Troubleshoot brake system. Found LH brake reservoir low on fluid. Serviced reservoir with W/560 Hyd fluid. leak check and op check good. |)6 |
| Strut inspection completed, found right strut retaining ring partially unseated. Strut deflated, retaining ring reseated, Strut serviced IAW Cessna service manual chapter 4-10, leak and ops check good | n- |
| Troubleshooting completed, found broken fuse holder, seating and panels removed to FOM. Replaced broken fuse holder with spare fuse holder. Ops check good. Panels and seating reinstalled. | e- |
| With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with GENERATION JETS under work order: WO_23-11. | r- |
| 136.61 | |
| Bryan Waldo A&P 3730638 | - |
| wo: WO_23-06 Airframe · page 1 of | 1 |
| no page 1 or | |
| | |
| HOBBS: 1,147.5 GENERATION JETS - 5318 Airport Drive - Denison, Texas 75020 - 8444436538 | |
| HORS: 1,147,5 GENERATION JETS · 5318 Airport Drive · Denison, Texas 75020 · 8444436538 N521RM CESSNA, 421C, S/N: 421C0335 January 17, 2023 | |
| N521RM CESSNA, 421C, S/N: 421C0335 January 17, 2023 1. Compression check completed on #5 cylinder (72). Found spark plug to be bad, checked all plug and found to be bad. Replaced all 24 spark plugs IAW Cessna 421 C service manual. One check | , — |
| N521RM CESSNA, 421C, S/N: 421C0335 January 17, 2023 1. Compression check completed on #5 cylinder (72). Found spark plug to be bad, checked all plug and found to be bad. Replaced all 24 spark plugs IAW Cessna 421 C service manual. Ops chec good Installed (24) P/N RHB32E - SPARK PLUG. 2. Found broken wire and repaired as REQ, removed and replaced CHT probe, further troubleshooting | s k |
| N521RM CESSNA, 421C, S/N: 421C0335 January 17, 2023 1. Compression check completed on #5 cylinder (72). Found spark plug to be bad, checked all plug and found to be bad. Replaced all 24 spark plugs IAW Cessna 421 C service manual. Ops chec good Installed (24) P/N RHB32E - SPARK PLUG. 2. Found broken wire and repaired as REQ, removed and replaced CHT probe, further troubleshootin required. Installed P/N AA86146 - CHT Bayonet RTD. 3. Found ground wire on master avionics switch to be loose. Ground wire tightened and ops checked. | s k g |
| N521RM CESSNA, 421C, S/N: 421C0335 January 17, 2023 1. Compression check completed on #5 cylinder (72). Found spark plug to be bad, checked all plug and found to be bad. Replaced all 24 spark plugs IAW Cessna 421 C service manual. Ops chec good Installed (24) P/N RHB32E - SPARK PLUG. 2. Found broken wire and repaired as REQ, removed and replaced CHT probe, further troubleshootin required. Installed P/N AA86146 - CHT Bayonet RTD. 3. Found ground wire on master avionics switch to be loose. Ground wire tightened and ops chec good. 4. Nose gear serviced with nitrogen IAW Cessna 421C service manual. | s k g k |
| N521RM CESSNA, 421C, S/N: 421C0335 January 17, 2023 1. Compression check completed on #5 cylinder (72). Found spark plug to be bad, checked all plug and found to be bad. Replaced all 24 spark plugs IAW Cessna 421 C service manual. Ops chec good Installed (24) P/N RHB32E - SPARK PLUG. 2. Found broken wire and repaired as REQ, removed and replaced CHT probe, further troubleshootin required. Installed P/N AA86146 - CHT Bayonet RTD. 3. Found ground wire on master avionics switch to be loose. Ground wire tightened and ops chec good. | s k g k |

DATE TOTAL TIME

TACH OR
RECORDING
METER
TIME

DESCRIPTION OF WORK PERFORMED -SIGNATURE & CERTIFICATE NO. OF PERFSON PERFORMING WORK



SERVICE

7929 Karl May Dr. Waco, Texas 76708 CRS No. AK6R541N Aircraft HM; 1165.0
Aircraft TT: 9108.7
Date; 10/02/2023
Heater HM: 9.7

Cessna S/N 421C-0335 N521RM

On above referenced aircraft, removed all inspection plates and panels for Annual Inspection. Checked all pulleys, bellcranks, cables and fairleads. Checked all flight controls for security and movement. Inspected all wing, tail and landing gear attach points. Inspected all aircraft lighting and electrical. Ran gear retraction test per Cessna Service Manual. Inspected wheels, tires and brakes. Inspected fuel, hydraulic lines and fittings. C/W A.D. 2000-01-16 per paragraphs (b), (c), (d), and (e) inspections. (Paragraph (b) next due at 1215.0 HM.) Replaced overboard exhaust and bellows for left engine. Replaced relief tube hose. Replaced inner wire for both cabin warm pressure cables and rigged. Corrected pilot's map light wiring. Corrected wiring for taxi light. Replaced nose RAM air duct and treated area in nose. C/W MEB 00-4 per proper installation of lower rudder mount bracket and set rudder trim travels per service manual. Installed new brake discs and pad lining and corrected wheel alignment and camber per service manual. Rotated main tires on wheel. Installed new battery drain tube fairing. Resealed left brake caliper and bled and serviced system. Replaced rivets at lower left-wing skin to fuselage as needed. Installed new nose gear drag link bearings and hardware. C/W MEB85-11(R4) and found right Trunnion mount in limits. (Re-inspect each 50 landings.) Repaired right main gear door at bracket area. Troubleshot surface deice boot operation and repaired bad supply hose on left engine. Oxygen and nitrogen bottles were hydrostatic tested and reinstalled. (Next due at 10/2028.) Performed test of ELT unit per FAR 91.207(d) requirements. (Battery next due 8/2024.) Installed new main aircraft hydraulic system filters. C/W A.D. 2004-25-16(R1) per MEB01-5. (Next due at 1265.0 HM.) C/W A.D. per inspection and test of heater assembly. (Next due at 109.7 Heater HM or 10/2025.) C/W A.D. 2016-17-24 per new elevator trim hardware installed. (Next due at 1275.0 HM.) Installed new battery box seal. Cleaned and treated wing spar fittings as feasible. Cleaned and treated in lower vertical access area. Installed new co-pilots defrost and heat ducts in nose. Cleaned and treated in AFT wheel well access panel areas. Installed new 9-in pressure duct in inboard right wing. Repaired wiring for flap warning horn. Resealed left brake master cylinder. All A.D.'s researched through bi-weekly 2023-18. (See A.D. listing for all current and future compliance times.) All above work done in accordance with Cessna Service Manual and Air Impressions, Inc. 100 Hour/Annual Inspection Checklist. Aircraft approved for return to service. Pertinent details are on file under work order 5804

Air Impressions, Inc. CRS# AK6R541N



7929 Karl May Dr. Waco, Texas 76708 CRS No. AK6R541N

I certify this Aircraft has been inspected in accordance with a Annual Inspection and has been determined to be in an airworthy condition.

DATE 10/02/2023 HM 1165.0

DATE 10/02/2023 HM
AIRCRAFT TT

WORK ORDER #5804 SIGNED

> AIR IMPRESSIONS, INC REPAIR STATION # AK6R541N

9108.7

| P | AGE | No. | |
|---|-----|-----|--|
| | AGE | | |



7929 Karl May Dr. Waco, Texas 76708 CRS No. AK6R541N Aircraft HM: 1181.0
Aircraft TT: 9124.7
Date: 06/24/2024

Cessna S/N 421C-0335 N521RM

On above referenced aircraft, installed newly overhauled RAM GTSIO-520-L S/N 292177-R engine onto right position of N521RM, S/N 421C-0335. Installed all new or overhauled turbo charger, turbo controller, wastegate, relief valve, fuel regulator, intercooler, throttle and control assembly, (See 8130-3 forms in RAM tag folder.) Installed new right engine shock mounts. Installed new fuel and oil hoses included with Ram kit. Installed new right engine exhaust slip joints. Installed existing right propeller S/N 774212 and left governor S/N 160043 after de-sludge and resealed by Byam Propeller Service. (See 8130-3 forms.) Installed new right exhaust tailpipe P/N A9910300-16 and right bypass elbow P/N A9910300-3. (See 8130-3 forms.) Installed overhauled left engine exhaust wye collector P/N 9910300-7. (See 8130-3. Installed new right turbo mount bracket P/N 2024-2. (FAA-PMA.) (See 8130-3.) C/W A.D. 2000-01-16 per para (b), (c), (d) and (e) inspections, next compliance due in 50 hours or 30 days whichever is later. C/W A.D. 84-26-02 on right engine by installing new air filter supplied by RAM, due each 300 hours. Performed fuel system set-ups to RAM Specs. Performed test flight. Aircraft approved for return to service for maintenance performed. Pertinent details are on file under work order 5997.

Air Impressions, Inc.
CRS4 AKARS41N

| | • |
|--|----------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | SUB-TOTALS THIS PAGE |







