# N5098Q 1972 "Cessna" 340 S#340-0024

## Airframe:

3400/Total Time – Complete Logs Since New - Landing Incident in 1975 – IFR Due: 4/19 – Annual Due: 4/19 ELT Due: 7/19 – Heater Test Due: 7/20 – Oxygen Hydro Due: 7/20

## Engine Specs: TSIO-520-NB Engines – 1600 Hour TBO – 310/H.P.

LH: 200/Hrs. Since Factory Reman (9/00) – 100/Since Signature teardown & Inspection (2008) S#813734-R RH: 200/Hrs. Since Factory Reman (9/00) – 100/Since Signature teardown & Inspection (2008) S#813733-R \*These NB' Engines were on N340WS / Cessna 340A. In 2007 due to a forced landing (see incident NTSB SEA07LA156) due to fuel starvation. The owner purchased these engines and sent off for teardown and inspection to install on N5098Q.\*

<u>Props</u>: McCauley 3- Bladed Sabre Tip Propellers – 2000/Hr. TBO – STC2346SW-D RAM STC LH: 1600/Hrs. Since New (10/99) S/N: 991453 RH: 1600/Hrs. Since New (10/99) S/N: 991456

<u>Avionics</u>: All new metal Panel & All new E.L. Panels surrounding the cockpit! (Being Done Now!) Garmin GMA-345 Audio Panel w/Intercom Garmin GNS-530W TAWS - Nav/Comm/GPS Garmin GNS-430W Nav/Com/GPS Garmin GTX-345 ADS-B / in-out Collins PN-101 Slaved H.S.I. FCS 810 Autopilot / Flight Director coupled (Serviced 2010)

### **Additional Equipment:**

New Cleveland Brakes and Tires JB Air Conditioning Long Range Fuel with one Locker Tank Full Deice (Wing Boots removed but all hardware still connected) Go Around Button Electric Trim Autopilot Disconnect Switch Alcohol Windshield 11 Cubin Feet Oxygen Bottle 100 AMP Alternators Previsions for R.H. Fuel Locker Tank (Not Installed)

<u>Glass</u>: In good condition! However, LH Windshield has light crazing.

### Interior: Rated - 8++

Completed in "Swan" Headliner, "Space-Earth" Curtains and "Heritage" Carpet in 2019!! Seats and Side Panels are all like New and completed in "Savana" in 2000! Nose and Wing Baggage completed in "Antelope"!

Exterior: Rated – 8++ Finished in Matterhorn White, Blake Velvet and Titanium in 2003! Completely Renewed and Professionally Touched-up in 2019! **History**: Aircraft had a Gear collapse in 1975 Complete and well-read Logs since 1972 Maintenance Highlights (Below – 3/15) Completed the replacement of both L&R Engines Beas with New RAM Engine Beams Completed the replacement of Canted Bulkheads with New RAM Canted Bulkheads Installed Blanket Service Kits from Cessna and all four Engine Beams Stainless steel Fuel Lines behind L&R Engine compartments **Heater overhauled** Completed eddy current testing of L&R ailerons Hinges Completed eddy current on Landing Gear Torque Tube assembly Completed eddy current L&R Main Gear Actuator Collar **Completed eddy current Nose Landing Gear Forks Repaired Altitude Controller Overhauled L&R Exhaust Overhauled Turbo Waste Gates** Landing Gear Struts overhauled **Shimmy Dampener overhauled** Landing Gear Linkages overhauled All new Brakes Squat Switches replace with new **Fuel Flow Gauges overhauled Installed new Engine Hoses** Installed new Strobe Lights **New Wheel Bearing** New RAM Exhaust Slip Joint Hardware Kit **New Landing Gear Motor** 

**COMMENTS:** This Aircraft is in Annual Now!

Aircraft specifications are subject to change at any time. This specification sheet is intended as preliminary information and is subject to verification by the purchaser RidgeAire, Inc. 903-586-1521.

