N23DT 1975 Cessna 421B

RH Prop Logbook SPOH2017 - 2024

MSN: 421B-0852



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

Right Prop Loopour # 2

N: <u>N1953G</u> MAKE/MODEL:<u>Cessna 421B</u> S/N:<u>421B0852</u>

PROPELLER MAINTENANCE RECORDS



SimsAir Aviation Services PROPELLER MAINTENANCE RECORDS

Log No.__2

Aircraft Registration No. N19536

Aircraft Mfg. Cessna Model. 421B Serial No. 42/80852

Propeller Mfg. Mc Cauley

Blade Design No. <u>9&LFB-&</u>

Hub Serial No. 043067

Blade Serial No's.

1	UJ	16082	
		1686	
	UJ		
4.			
5			

Pitch Range: High_____20.2___ Low____<u>/6.4</u> Feather___<u>84.5</u>___ Reverse__<u>N/A</u>____

Governor Mfg._____Model No_____ Serial No._____

Date installed on aircraft 11/05/04

Time Between Overhauls (TBO) 2,000 hours 6 years

If used on a multi-engine aircraft:

Left	¢.	Right
Front		Rear

R

DAT	E		L TIME RVICE	TOTAL T SINCE OVERHA	- F	ACH OR IOUR TER TIME	DESCRIPTION OF WO CERTIFICATE NO. O	DRK PERFORM F PERSON PEF	IED - SIGNATUR
							TOTALS brought forw	ard from previ	ious page
		a la	Alis		Avi	ation	Services	RIGHT PRO RECORD	
Re	J. No. N1953G		SimsAir, LLC			Hour Meter	4,011.1		
		el No. C421B			190	0 Cardiff	Rd, Hangar 103-C	Prop TT	1,113.0
_	rial N			3-0852	н	ouston E	Executive Airport ire, TX 77423	L	
	op M/	and the second division of the second divisio		7C516 3067	Phone (71	3) 294-79	994 - Fax (832) 218-3890	PAGE ²	1 OF 1
The	3. 4.	FORM INSTAL PERFO	8130-3 LED PRC DRMED EN	PELLER (SA NGINE RUN-U entified abov	ME AS REMO JP. NO LEAKS e was maint	VED) IAW	ED	rent Federal Aviat	tion Regulation
SYS	tems v	were res	stored and	functionally	to service for tested in acco	the work p rdance with	erformed. Current maintenance h mfg's instructions. Pertinent de	etails of the repair a	are on file under
- Wo	tems v	were res der: 170	stored and 10919530 /0/17	Authori	to service for tested in acco zed Signatu	rdance with	h mfg's instructions. Pertinent de	SA Zachary R. Bishop	are on file under
- Wo	ork Ord	were res der: 170	stored and 10919530 /0/17	Authori Authori I Prope this da MPCS Under THE II R&D I 2528 FAA C	Iller S/N: 003 ate: 2/20/20 500; BOM10	ance with rdance with are: 3067 has 3067 has 307 l/A/M 30; SPM10 622. The N MUST rvice, LLO Pearlance 59C	been overhauled on V/manual(s): 00 Mechanic making C/W 14 cfr Part 43.9.	SA Zachary R. Bishop	are on file under

DATE		L TIME RVICE	TOTAL TIM SINCE OVERHAUL	HOUR	DESCRIPTION OF W CERTIFICATE NO.		
				•	TOTALS brought for	ward from prev	ious page
	C	2		Silvi Aviation	Services	RIGHT PRO RECORD	
Reg. No		N110	953G	Sim	sAir, LLC	Hour Meter	4,021.0
Model N				1900 Cardiff Rd, Hangar 103-C		Prop TT	1,122.9
	Serial No. 421B-08 Prop M/N 3AF37C5			Houston Executive Airport			
Prop M			P			PAGE 1 OF 1	
Prop S/	'N	003	3067				
91.4/J9(# systems Work C	1635 71 SI 1635 7 SI 1635 7 SI	:s approve to red and 7171953G	functionally teste	ervice for the work peed in accordance with	erformed. Current maintenance mfg's instructions. Pertinent of	e manuals were used details of the repair ar SA Zachary R Bishop,	re on file under
					71 - Sur	781	
		the second s	in the second se				
	A 100						······································
viation s	ervice	s Ca		Prop	eller 2 Log		· · · · · · · · · · · · · · · · · · ·
viation S Since	ervice 1996			Prop McCauley - 3	eller 2 Log 8AF37C516 - 003067		
viation S Since 4,048.0 AC	ervice 1996 TT: 6,336.6	/	·: 1,667.6	McCauley - 3 W/O:	eller 2 Log 8AF37C516 - 003067 1801091953G	Peer 4 and	
viation S Since 4,048.0 AC Al	ervice 1996 TT: 6,336.0 FL:	E1TT E1C		McCauley - 3 W/O: 2TT: 1,340.6 E3TT: Exc.	8AF37C516 - 003067 1801091953G	Page 1 of 1	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	E1TT E1C 100 Hr. II		McCauley - 3 W/O: 277: 1,340.6 E3TT: E2C: E3C:	8AF37C516 - 003067 1801091953G	PITT: 24437	P3TT: APU P4TT:
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	E1TT E1C 100 Hr. II		McCauley - 3 W/O: 277: 1,340.6 E3TT: E2C: E3C:	8AF37C516 - 003067 1801091953G	PITT: 24437	P3TT: APU P4TT:
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: Ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: Stion Checklist. gulation FAR 91.409(A)(1) of the Fill systems were restored and functional Zachary Fill Sthire, TX 77423 - (713) 294-7994 - www	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat ly tested in accordance wit R. Bishop, A&P 374 v.simsair.com	
Viation Survey Since 4,048.0 AC 4,048.0 AC AI 0: 5 -	Ervice 1996 TT: 6,336.6 FL: C/W 50 8	5 E1TT E1C & 100 Hr. Ji above was m mmed. Curren n file with Sin	nspection IAW A aintained or altered in the maintenance manu- maAir, LLC. Authorized Si	McCauley - 3 W/O: 2TT: 1,340.6 E3TT: E2C: E3C: MM Servicing & Inspect accordance with current re als were used. All disrupted	8AF37C516 - 003067 1801091953G E4TT: E4C: ction Checklist. gulation FAR 91.409(A)(1) of the Fi systems were restored and functional	P1TT: 2,443.7 P2TT: 1,149.9 ederal Aviation Administrat ly tested in accordance wit R. Bishop, A&P 374 v.simsair.com	

,

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR HOUR METER TIME	DESCRIPTION OF WORK PERFORMED - SIGNATURE 8 CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
		3G Cessna C421B Prop Logbook		McCauley Prop Model 3AF37C516 S/N 003067 4117.0 TTP 1218.9 SPOH 105.9
	bulkhead for cra remove any sma date and compl	acks. Inspect de-i all nicks. Engine g ied with as noted	ce prop boots f ground run with d in AD Summa	letails of FAR 43 Appendix D. Inspect spinner/spinner for condition. Apply Corrosion X to hub. File blades to a operation of prop cycle normal. AD's checked thru this ry Listing. I certify that this Propeller has been inspected as determined to be in an Airworthy condition on this
	date.			
	AIR PROFESSIO	NALS		RANDY WAHLBERG A&P 3563642IA
	PEARLAND REG (281) 992-3484	IONAL AIRPORT		Endy Wihlly
			A	
		53G Cessna C 421 t Prop Logbook	1B S/N 421B089 Hobbs 4	52 McCauley Prop Model 3AF37C516 S/N 003067 135.3 TTP 1237.2 SPOH 124.2
	bulkhead for c to hub and bla normal. AD's c	racks. Inspect pro des. File blades t hecked thru this	op de-ice boots o remove smal date and comp	details of FAR 43 Appendix D. Inspect spinner/spinner for condition and operation. Apply Corrosion X Spray I nicks. Engine ground run with operations of prop cycle lied with as noted. I certify that this Propeller has been ction and was determined to be in an Airworthy condition
	AIR PROFESSIC	NALS		RANDY WAHLBERG A&P 3563642IA
	PEARLAND REG (281) 992-3484	GIONAL AIRPORT		Bandy Wahle
	+	[1.	SUB-TOTAL this page

	RIGHT PROP LO		Mesquite, Texas 75181	-
lesquite Aircraft Sales & Services	1350 Airport	RIAD	Hobbs: 4164.4	U
GISTRATION: N1953G AFSN: 42	18-0852	DATE: 11-11-2022		'C
		OP S/N: 003067	PTSN: 1266.3 PTSO: 153.3	ſ
	a la sea model 3	AF37C516 S/N 003067 in	accordance with FAR Part 43, appendix D.	i
Complied with 100 hr. inspection on N	toCauley prop model 3/		- (1) CCC2502 01018X S/N	-
 Complied with A.D. research on Props 	the Propeller heat load	meter. Removed prop	heat load meter P/N C662503-0101RX, S/N Propeller heat load meter as needed.	
Checked the wiring and installation of OK109 Sent out for inspection and pe	ossible repair if needed	. Repaired wiring to the	Propeller heat load meter as needed. turn from inspection and testing.	
Reinstalled the propeller heat load me	eter P/N Coo2505 0101	in a state of this	time	1
Reinstalled the propeller heat load me Performed function check of the prop	eller heat system with i	www.ap and High temper	rature RTV so as to prevent further chafing	
				Ī
	ce brush blocks retainin	ng screws and secured w	vith safety wire.	
Removed non heating deicer boot from	m one blade of the righ	t propener and instance	I new deicer boot P/N 6592SW, S/N 88682	
in accordance with Goodrich deicer in	stallation manual. Fund	cuon check good.		-
I certify this aircraft, engine, propeller	and/or component i	dentified above was	repaired and/or inspected in	-
accordance with current F.A.A. regulat	ions and was detern	nined to be in airwort	hy condition and approved for Return	Ì
to Service with respect to work perform	med. A			1
	far He		Steven P. Adams A&P 2713403	-
ated; November 11, 2022 Signed				
	· · · · · · · · · · · · · · · · · · ·	4 . 5	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	. –
		and a state of the	and the state of the	
A	RIGHT PROP I	.OG ENTRY		-
Mesquite Aircraft Sales & Services	1350 Airpoi	rt Blvd		
EGISTRATION: N23DT AFSN: 42			Mesquite, Texas 75181	<u> </u>
000 11000		DATE: 12-30-2023	Hobbs: 4193.6	
ROP MANUF: McCAULEY PROP MODEL	: 3AF37C516 PF	ROP S/N: 003067	PTSN: 1205 5 PTC -	:
 Complied with 100 hr. inspection on M 			PTSN: 1295.5 PTSO: 182.5	
 Complied with A.D. research on Props 	thru 2023-26.	AF37C516 S/N 003067 ir	n accordance with FAR Part 43, appendix D.	1
-ocosos also perform	ned maintenance.			!
ertify this aircraft engine and it				
ertify this aircraft, engine, propeller and/or rrent F.A.A. regulations and was determine work performed.	d to be in signation	ed above was repaire	d and/or inspected in accordance with	_
work performed.	- to be in airworthy	condition and approv	ved for Return to Service with respect	
	1.01	-	with respect	
ited; December 30, 2023 Signed	at the	-		<u> </u>
			Steven P. Adams A&P 2713403	
			and a party of the second seco	
		· · · · · · · · · · · · · · · · · · ·		

The day A Venality

ì

١.

4

and an a second state of the second

ter and a subscription of a

i,

R.

- -

SIMSAIR AVIATION SERVICES 1904 CARDIFF RD, HANGAR HC-103-C BROOKSHIRE, TX 77423