


N3910A

1970 Beechcraft V35B

Airworthiness Directives

MSN: D-9093




Prepared by the worldwide aviation specialists at RidgeAire, Inc.

AIRFRAME

Company The H Company
Manufacturer BEECH AIRCRAFT CORP.
Model V35B
Serial # D-9093
A/C Cert. Date 1970

Tach Time Tach 242.7
Total Time ACTT 4685.2

Tail Number N3910A

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
71-24-10 08/01/73	SECURITY OF CONTROL WHEEL/	2-1-72 ACTT 435.0	PCW by installation of P/N 98-524029-150 Control wheel adapter	X		N/A	
72-11-02 05/20/72	PLACARDS - BAFFLED MAIN FUEL CELLS AND CHECK VALVES/	3-9-72	PCW by installation off SI0491-281	X		N/A	
73-14-03 07/08/73	LANDING GEAR SHOCK STRUT PISTON/		N/A DUE TO AIRCRAFT S/N	X		N/A	
74-03-02 02/05/74	LANDING GEAR SHOCK STRUT PISTON/		N/A DUE TO AIRCRAFT S/N	X		N/A	
74-24-03 11/22/74	PLACARD - ELECTRICAL BONDING OF STROBE LIGHTS/		N/A DUE TO AIRCRAFT S/N	X		N/A	
75-01-07 01/13/75	EXHAUST SYSTEM FAILURES/		N/A STC not installed	X		N/A	
*75-05-02 02/21/75	AIR OIL SEPARATOR FILTRATOR ASSEMBLY/		N/A No air/oil seperator installed		X	N/A	
76-22-02 08/02/77	"Y" TYPE SHOULDER HARNESS/		N/A DUE TO AIRCRAFT S/N	X		N/A	
79-01-01 01/08/79	ATTACHMENT SCREWS IN FLIGHT CONTROL SYSTEM/		N/A DUE TO AIRCRAFT S/N	X		N/A	
84-09-01 05/25/84	WINDOW EMERGENCY EGRESS PROVISIONS/		N/A seats less than 5 occupants	X		N/A	
87-18-06 R1 02/05/88	SEAT RECLINE ACTUATOR HANDLE/		N/A DUE TO AIRCRAFT S/N	X		N/A	
88-21-02 10/31/88	SEAT TRACKS/		N/A DUE TO AIRCRAFT S/N	X		N/A	
91-20-08 10/31/91	FRESH AIR BLOWER HOUSING/		N/A Fresh air option not installed	X		N/A	
92-17-01 09/11/92	FUEL METERING UNIT/		N/A TSIO-520D engine not installed	X		N/A	
*94-20-04 R2 06/27/03	V-TAIL INSPECTION/	8/21/2024 Tach 242.2	Complied with by visual inspection of all V-tail assembly structures		X	Tach 342.2	AP487354347A 

Airworthiness Directive Compliance Record

N3910A

Page 2 of 2

*95-04-03 04/07/95	WING FRONT SPAR INSPECTION/		N/A DUE TO AIRCRAFT S/N		X	N/A	
97-06-11 05/16/97	RUDDERVATOR DIFFERENTIAL TAIL CONTROL ROD ASSEMBLY/	10/3/1997 tach 3709	PCW		X	N/A	
97-14-15 09/02/97	CABIN SIDE DOOR/	6/21/2024 Tach 242.2	Complied with ny functional check of cabin door latching mechanism		X	N/A	AP4673543471A <i>Ken Griffitt</i>
*01-08-08 06/07/01	V-BAND EXHAUST CLAMP/		N/A V-band clamps not installed		X	N/A	
01-23-10 12/13/01	FLAP FLEX SHAFT ASSEMBLIES AND ACTUATORS/		N/A flap flex cables never replaced		X	N/A	
*07-08-08 05/25/07	MAIN LANDING GEAR UPLOCK ROLLERS/	6/21/2024 Tach 242.2	C/W AD by lubrication and inspection of uplock rollers		X	Tach 342.2	AP4673543471A <i>Ken Griffitt</i>
08-13-17 08/06/08	CIRCUIT BREAKER TOGGLE SWITCHES/		N/A affected circuit breaker switches not installed		X	N/A	
09-25-01 01/08/10	PILOT AND CO-PILOT SHOULDER HARNESS GUIDE RETAINING WASHERS/		N/A DUE TO AIRCRAFT S/N		X	N/A	
*18-06-11 05/03/18	EXHAUST TAILPIPE V-BAND COUPLING INADVERTENT DETACHMENT/		N/A TSIO-S20D engine not installed		X	N/A	
19-23-10 11/22/19	RIGHT AILERON FLIGHT CONTROL CABLE TERMINAL FITTINGS INTEGRITY/		N/A DUE TO AIRCRAFT S/N		X	N/A	
*23-09-09 07/17/23	FAILURES OF SPOT-WELDED, MULTI-SEGMENT V-BAND COUPLINGS/		N/A engine not turbo charged		X	N/A	

KEN GRIFFITT

6/21/24

ENGINE –

Company The H Company
Manufacturer TELEDYNE CONTINENTAL MOTORS
Model IO-520-BA
Location
Serial # 241371R
TSMOH 62.1 TTSMOH
Total Time 1637.5 TTIS

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
70-14-07 11/22/74	FUEL INJECTION PUMP/		N/A due to engine model number	X		N/A	
*72-24-03 11/15/72	OIL FILTER ADAPTER/		N/A no oil filter adapter installed		X	N/A	
*77-05-04 03/11/77	MAIN BEARING AND GOVERNOR OIL TRANSFER COLLAR/		N/A due to engine model number		X	N/A	
*77-13-22 07/22/77	[R1] CRANKCASE INSPECTION CRACK CRITERIA/		N/A due to engine S/N		X	N/A	
79-05-09 03/12/79	OIL PRESSURE RELIEF VALVE PLUNGER AND SCREW/		N/A due to engine S/N	X		N/A	
80-01-04 01/25/80	CYLINDER HOLDDOWN FLANGES/		N/A cylinders not re-barrelled by Airmotive engineering Corporation	X		N/A	
*81-24-06 11/23/81	ENGINE DRIVEN FUEL PUMP THROUGH BOLTS/		N/A due to date of engine overhaul		X	N/A	
*86-13-04 R3 02/24/88	CYLINDER BARREL CRACKING/		N/A due to engine S/N		X	N/A	
87-14-02 10/05/87	STARTER ADAPTER SHAFTS/		N/A freon compressor not installed	X		N/A	
88-03-06 04/15/88	TCM PRO-TECH ENGINE OIL FILTER/		N/A TCM Pro-Tech engine oil filter not installed	X		N/A	
88-17-03 08/10/88	STARTER ADAPTER DRIVE SHAFT/		N/A freon compressor not installed	X		N/A	
91-19-03 09/29/91	CHAMPION ENGINE OIL FILTER/		N/A due to date code on filter installed	X		N/A	
93-08-17 08/23/93	OIL PICK-UP TUBE INSPECTION/		N/A engine model and S/N not listed in TCM SB M91-10	X		N/A	
93-10-02 08/12/93	CYLINDER VALVE RETAINER KEY/		N/A due to date of engine MFGR/re-build	X		N/A	
93-16-15 12/14/93	FUEL PUMP DRIVE SHAFT COUPLING/		N/A engine serial number is below those listed in TCM MSB 93-9.	X		N/A	

Airworthiness Directive Compliance Record

IO-520-BA

Page 2 of 2

*95-03-14 03/13/95	INSPECTION OF ENGINE MOUNT BRACKETS/		N/A due to engine model number		X	N/A
95-21-15 11/28/95	ENGINE TEARDOWN AND INSPECTION/		N/A due to aircraft registration number	X		N/A
*96-12-22 07/31/96	OIL FILTER ADAPTER ASSEMBLY NUT/		N/A Cessna oil filter adapter not installed		X	N/A
*97-26-17 01/23/98	AIRMELT CRANKSHAFT/		N/A engine S/N lower than those listed in TCM CSB 98-8		X	N/A
98-01-08 12/23/97	EXHAUST ROLLER BEARING ROCKER ARMS/		N/A exhaust roller rocker arms not installed	X		N/A
98-17-11 10/19/98	CRANKSHAFT CRACKS/		N/A crankshaft not repaired by Nelson Ballancing Services	X		N/A
99-19-01 09/30/99	CRANKSHAFT CHEEK CRACKS/		N/A due to date of engine overhaul	X		N/A
00-23-21 12/12/00	CRANKSHAFT CONNECTING ROD JOURNAL/		N/A engine not listed in TCM MSB 00-5C	X		N/A
04-08-10 05/05/04	ENGINE COMPONENTS, INC. STC'D CYLINDERS/		N/A STC not installed	X		N/A
07-04-19 R1 05/07/07	SUPERIOR AIR PARTS, INC. CAST CYLINDER ASSEMBLIES/		N/A Superior cylinders not installed	X		N/A
*09-19-07 10/07/09	EQ3 CYLINDER HEAD ASSEMBLIES/		N/A EQ3 Cylinders not installed		X	N/A
10-11-04 08/16/10	HYDRAULIC VALVE LIFTERS/		N/A lifters have not been changed since 2009	X		N/A
12-03-06 02/24/12	AFS FUEL SERVO DIAPHRAGM/		N/A fuel injector servo not listed in Avstar SB AFS-SB6	X		N/A
*14-05-29 04/25/14	SUPERIOR AIR PARTS INVESTMENT CAST CYLINDER ASSEMBLIES/		N/A Superior cylinders installed		X	N/A
16-16-12 09/15/16	ECI CLASS 71 OR CLASS 76 CYLINDER ASSEMBLY FAILURES/		N/A ECI Class 71 or Class 76 cylinders not installed	X		N/A
22-16-03 08/15/22	S-1200 SERIES MAGNETOS ROLLER BEARINGS IMPROPER LUBRICATION/		N/A due to magneto serial numbers installed	X		N/A
23-02-12 02/17/23	INTAKE VALVE FAILURES/		N/A no cylinders replaced during affected period	X		N/A
23-05-16 03/15/23	IMPROPER INSTALLATION OF COUNTERWEIGHT RETAINING RINGS/		N/A engine S/N not listed in TCM MSB-23-01A	X		N/A
*23-09-09 07/17/23	FAILURES OF SPOT-WELDED, MULTI-SEGMENT V-BAND COUPLINGS/		N/A spot welded multi-segment clamps not installed		X	N/A
23-17-04 10/26/23	STC F&M OR STRATUS OIL FILTER ADAPTER FIBER GASKET OIL LOSS/		N/A STC not installed	X		N/A

* indicates possible recurring inspections © 1995 - 2007 - Tdata, Inc. (Tdata.com)

Prepared by

Ken Griffith

Date

6/19/24

PROPELLER -

Company The H Company
Manufacturer HARTZELL
Model PHC-C3YF-1RF/F8068
Location
Tail # N3910A **Blade** TSMOH **TTIS** 62.5
Serial # QG1233B **Total Time** TTIS 62.5 **Tail Number** N3910A

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
*94-17-13 09/15/94	EDDY CURRENT INSPECTION/		N/A due to propeller S/N		X	N/A	
01-07-03 08/04/01	PROPELLERS RETURNED TO SERVICE BY BASCO/		N/A propeller not returned to service by Basco	X		N/A	
03-13-17 07/18/03	MAINTENANCE REPAIR BY T AND W PROPELLERS, INC./		N/A no maintenance repairs by T and W Propellers	X		N/A	
05-14-11 08/17/05	MAINTENANCE AND REPAIR BY SOUTHERN CALIFORNIA PROPELLER SERVICE/		N/A no maintenance and/or repair by Southern California Propeller	X		N/A	
06-24-07 01/03/07	INSPECTIONS AND REPAIRS BY CSE AVIATION/		N/A no inspections and repairs by CSE Aviation	X		N/A	
07-26-09 01/30/08	PLACARD, PROPELLER BLADE SHANK REWORK/		Complied with at prop MFGR	X		N/A	
*08-13-28 07/17/08	PROPELLER HUB LUBRICATION HOLES/		Complied with at propeller manufacture		X	N/A	