N100BG 1975 Cessna T210L

Airworthiness Directives

MSN: 21060633



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

Triton Aviation Data Corp. The AD Resource System DataBases updated May 8, 2019: As of Biweekly 2019-09/-10

Display Reports in MS-Word

Return to Search Selections

Search within the listed ADs for:

search

122 hv 3172 hv 5-13-19

Manufacturer: Cessna Aircraft Co. (Textron Aviation) TC No.: <u>3A21</u> Airworthiness Directives for Model: T210L Rec (Yes); Indicates a Recurring AD.

tec (Ves); Indicates a Recurring AD. Number of ADs: 3				
AD Number	PDF	Rec	Subject	Effectiv
1- <u>09-07 R1</u>	PDF	Yes	Exhaust manifold heat exchanger	11/26/86
-1-21-01	PDF	No	Superseded by 72-07-09	01/01/71
-2-07-09	PDF	Yes	Cracks and loose bolts in fin & rudder NA/645/N	10/17/74
-04-03	PDF	Yes	ARC PA-500A actuators	02/26/76
-7-06-02	PDF	No	Superseded by 78-07-01	01/01/77
	PDF	No	External elec. ground power recep	06/27/77
	PDF	No	Fuel selector valve	08/11/77
-8-07-01	PDF	No	Engine oil pump	04/06/78
-8-26-09	PDF	No	Superseded by 79-10-14 R1	01/01/78
79-08-03	PDF	No	Electrical system	06/06/79
79-10-14 R1	PDF	No	Fuel tank venting	05/30/88
- <u>9-15-01</u>	PDF	No	Fuel flow distribution	07/26/79
-9-19-06	PDF	No	Fuel flow system per STC SA3835WE	09/17/79
-9-25-07	PDF	No	Alternator ground	12/13/79
80-07-01	PDF	No	Oil pressure	03/28/80
80-21-03	PDF	No	Roll axis flight control	10/02/80
82-06-10	PDF	No	Vacuum driven attitude instruments	04/15/82
85-02-07	PDF	No	Fuel selector	03/06/85
86-19-11	PDF	No	Contaminated fuel	10/04/86
86-24-07	PDF	No	Engine controls installation	01/07/87
87-20-03 R2	PDF	Yes	Superseded by 2011-10-09	09/24/90
88-22-07	PDF	No	Hose assemblies	11/24/88
88-25-04	PDF	Yes	AFM/POH changes-magneto	12/26/88
91-22-01	PDF	No	Electrical wires	11/04/91
9 <u>2-26-04 S</u>	PDF	No	Superseded by 94-12-08	01/22/93
93-13-09	PDF	No	Air induction hose	08/13/93
4-12-08	PDF	No	Fuel loss and servicing	07/22/94
000-06-01	PDF	No	Fuel strainer standpipe assembly	05/05/00
002-07-01	PDF	No	Horiz. Stab. attachment reinforcement brackets	05/13/02
008-10-02			Superseded by 2008-26-10	05/12/08
008-26-10			Corrected by 2008-10-02 C1	01/05/09
008-26-10 C1			Alternate static air source selector valve	11/16/10
) <u>11-10-09</u>			Seat rail & seat rail holes; seat pin; seat rollers, etc.	06/17/1
)12-10-04			Cracks - wing lower main spar caps	06/05/1

The Following ADs apply to Accessories that could be installed on the T210L (See Explanation) No. of ADs: 8

74-13-06	PDF	Yes	Wheel flange attaching bolts	06/24/74	

1.10						
	28-14-03	PDF	No	Modification: AlliedSignal KT 76A ATC transponders		
	<u>98-21-21 R1</u>	PDF	No	Overheating: electric to a ATC transponders	08/16/98	
	2002-26-03	PDF	No	Overheating: electric door seal inflation systems	05/01/00	
	2005-01-19	PDF	No	Brackett Aircraft Co. single screen air filter assembly, P/N BA-2410; STC No. SA71GL	02/18/03	
	2005-18-20	PDF	Yes	Garmin GTX 33, GTX 33D, GTX 330, GTX 330D Mode S Transponders		
			100	Goodrich De-icing & Specialty Syst. "FASTprop" Propeller Replacement: Hastard Device and the second		
	2012-10-52	PDF	No	Replacement: Hartzell Engine Technologies turbochargers, P/Ns 406610-0005 or 406610-	10/14/05	
Ì	2019-01-02	DDD		9005 9005 9005 9005 9005 9005 9005 9005	06/26/12	
			No	Disable Automatic Dependent Surveillance D		
	ADs that address	s non-T	pe C	Disable Automatic Dependent Surveillance-Broadcast due to repeat resetting; AFM change	02/07/19	
	Use your Browse	T's "D.	int D.	Bright Starting (Garmin, Bendix, etc.) can be C		

ADs that address non-Type Certificate holders (Garmin, Bendix, etc.) can be found in the <u>Appliance/Accessory Index</u>. Use your Browser's "Print Page" function to print this Summary, and/or use "Save As" to save it to disk. Change the file name before clicking on "Save".

