N100BG 1975 Cessna 210L

Airworthiness Directives

MSN: 21060633



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

Triton Aviation Data Corp.

The AD Resource System DataBases updated May 8, 2019: As of Biweekly 2019-09/-10

Display Reports in MS-Word

Return to Search Selections

Search within the listed ADs for:

search

122 hv

5-13-19

Manufacturer: Cessna Aircraft Co. (Textron Aviation) TC No.: 3A21 Airworthiness Directives for Model: T210L

Rec (Yes); Indicates a Recurring AD

Rec (Yes); Indicates a Recurring AD.				f ADs: 34	
AD Number	PDF	Rec	Subject	Effective	
-1-09-07 R1	PDF	Yes	Exhaust manifold heat exchanger	11/26/86	
71-21-01	PDF	No	Superseded by 72-07-09	01/01/71	
~2- <u>07-09</u>	PDF	Yes	Cracks and loose bolts in fin & rudder Da/by 5/N	10/17/74	
~6-04-03	PDF	Yes	ARC PA-500A actuators	02/26/76	
7-06-02	PDF	No	Superseded by 78-07-01	01/01/77	
<u>12-08</u>	PDF	No	External elec. ground power recep	06/27/77	
16-05	PDF	No	Fuel selector valve	08/11/77	
-8- <u>07-01</u>	PDF	No	Engine oil pump	04/06/78	
78-26-09	PDF	No	Superseded by <u>79-10-14 R1</u>	01/01/78	
79-08-03	PDF	No	Electrical system	06/06/79	
79-10-14 R1	PDF	No	Fuel tank venting	05/30/88	
~ <u>9-15-01</u>	PDF	No	Fuel flow distribution	07/26/79	
~9 <u>-19-06</u>	PDF	No	Fuel flow system per STC SA3835WE	09/17/79	
79-25-07	PDF	No	Alternator ground	12/13/79	
<u>80-07-01</u>	PDF	No	Oil pressure	03/28/80	
80-21-03	PDF	No	Roll axis flight control	10/02/80	
82-06-10	PDF	No	Vacuum driven attitude instruments	04/15/82	
85-02-07	PDF	No	Fuel selector	03/06/85	
86-19-11	PDF	No	Contaminated fuel	10/04/86	
86-24-07	PDF	No	Engine controls installation	01/07/87	
87-20-03 R2	PDF	Yes	Superseded by 2011-10-09	09/24/90	
88-22-07	PDF	No	Hose assemblies	11/24/88	
88-25-04	PDF	Yes	AFM/POH changes-magneto	12/26/88	
91-22-01	PDF	No	Electrical wires	11/04/91	
92-26-04 S	PDF	No	Superseded by 94-12-08	01/22/93	
9 <u>3-13-09</u>	PDF	No	Air induction hose	08/13/93	
9 <u>4-12-08</u>	PDF	No	Fuel loss and servicing	07/22/94	
2000-06-01	PDF	No	Fuel strainer standpipe assembly	05/05/00	
2002-07-01	PDF	No	Horiz. Stab. attachment reinforcement brackets	05/13/02	
2008-10-02	PDF	No	Superseded by 2008-26-10	05/12/08	
2008-26-10	PDF	No	Corrected by 2008-10-02 C1	01/05/09	
008-26-10 C1	PDF	No	Alternate static air source selector valve	11/16/10	
011-10-09	PDF	Yes	Seat rail & seat rail holes; seat pin; seat rollers, etc.	06/17/11	
012-10-04		No	Cracks - wing lower main spar caps	06/05/12	

The Following ADs apply to Accessories that could be installed on the T210L (See Explanation) No. of ADs: 8

The Following					
74-13-06	PDF	Yes	Wheel flange attaching bolts	06/24/74	

250				_				
	28-14-03	PDF	No	Modification: AlliedSignal KT 76A ATC transponders				
	98-21-21 R1	PDF	No	Overheating: electric 4	08/16/98			
	2002-26-03	PDF	No	Overheating: electric door seal inflation systems Brackett Aircraft Co. sixth No. 100 A TC transponders	05/01/00			
		PDF	No	Brackett Aircraft Co. single screen air filter assembly, P/N BA-2410; STC No. SA71GL	02/18/03			
	2005-18-20	PDF	Yes	Garmin GTX 33, GTX 33D, GTX 330, GTX 330D Mode S Transponders Goodrich De-icing & Specialty Syst. "FAST."	02/23/05			
ı	2012-10-52	PDF	No	Goodrich De-icing & Specialty Syst. "FASTprop" Propeller Replacement: Hartzell Engine Technologies turbochargers, P/Ns 406610-0005 or 406610-	10/14/05			
ŀ	2010		140	9005 realized Engine Technologies turbochargers, P/Ns 406610 processor	24.004.112			
			No	Disable Automatic Dependent S	06/26/12			
	ADs that address	non-T	vne C	Disable Automatic Dependent Surveillance-Broadcast due to repeat resetting; AFM change	02/07/19			
	Use your Browsor's "Desire B. Colleges (Garmin, Bendix, etc.) and bendix of the second							

ADs that address non-Type Certificate holders (Garmin, Bendix, etc.) can be found in the Appliance/Accessory Index. Use your Browser's "Print Page" function to print this Summary, and/or use "Save As" to save it to disk. Change the file name before clicking on "Save".