N8442H 1981 Piper PA-32-301

Airworthiness Directives

MSN: 32-8106098



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

AIRFRAME

Company

Cherryhill Aviation

Manufacturer Model Serial #

A/C Cert. Date

PIPER AIRCRAFT CORP.

PA-32-301 32-8106098

1981

Tach Time Total Time 2070.6 6009.2

Tail Number N8442H

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	0	R	Next Comp @ Hrs/Date	Authorized Signature & Number
67-20-04 09/27/67	MAIN LANDING GEAR TORQUE LINK/		NA new style of torque link installed	Х		N/A	AND HAVE
80-14-03 07/01/80	BENDIX, KING OR NARCO TRANSMITTERS/		NA by serial number	Х		N/A	a de la companya della companya della companya de la companya della companya dell
86-17-01 08/21/86	AMMETER REPLACEMENT/		NA by serial number	Х		N/A	37/1/
* 95-26-13 02/05/96	OIL COOLER HOSE ASSEMBLIES/		Superceded by AD 17-14-04		Х	N/A	3/1/
96-10-03 05/29/96	FLAP LEVER HANDLE AND BOLT/	5-30-1996 Tach: 490.4	PCW by replacement of new bushing, clevis bolt, washer, nut, and cotter pin	Х		N/A	
99-05-09 03/19/99	INDUCTION AIR FILTER/		NA affected parts not installed	Х		N/A	1
10-15-10 08/31/10	CONTROL WHEEL COLUMN SHAFTS/	8-19-2012 Tasch: 1252.6	PCW by inspection	х		N/A	
*13-02-13 03/11/13	HORIZONTAL STABILATOR CONTROL CABLES/	8-10-2022 Tach: 2059.0	PCW by inspection per AD and SB 1245A (1-10)		X	2000 hours or 7 years whichever occurs first Next Due: tach: 4059.0/August 2029	3621331 A&P
* 17-14-04 08/15/17	OIL COOLER HOSE ASSEMBLY TSO REQUIREMENTS/	8-27-2023 tach: 2070.6	Type D hose previously installed. Replacement times terminated. Inspected for condition		X	N/A	3621331 A&P

ENGINE – Front

Company Manufacturer

Cherryhill Aviation Lycoming Engines

Model Location Serial #

10-540-K1G5 Front

L30652-48A

TSMOH Total Time 214.1 2323.1

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	0	R	Next Comp @ Hrs/Date	Authorized Signature & Number
*63-14-03 07/06/63	OIL PUMP DRIVE SHAFT/		NA by engine serial number		×	N/A	/
64-16-05 07/10/64	OIL SEAL FAILURE/		PCW at engine overhaul	×		N/A	
66-20-04 08/27/66	OIL FILTER ADAPTER GASKET/		PCW at overhaul	×		N/A	
73-23-01 01/13/77	[R4] PISTON PIN/		PCW at overhaul	×		N/A	
75-08-09 08/18/77	[R3] OIL PUMP DRIVE SHAFT/		PCW at overhaul	×	,	N/A	3
76-09-15 04/30/75	FUEL INJECTOR FLOW DIVIDER COVER/		PCW at overhaul	X		N/A	. / 65
78-23-08 11/07/78	FUEL INJECTOR TUBE ELBOW/		PCW at overhaul	×		N/A	7 / 20
78-23-10 11/07/78	FUEL INJECTOR CENTER BODY BELLOWS SEAL/		PCW at overhau!	X		N/A	4/1/
79-04-05 02/26/79	[R1] FUEL INJECTOR REGULATOR DIAPHRAGM/		PCW at overhaul	×		N/A	3 ¹ / //
81-03-05 02/11/81	MIXTURE CONTROL SHAFT ASSEMBLY/		PCW at overhaul	×		N/A	
83-22-04 11/04/83	FUEL INJECTOR DIAPHRAGM STEM/		PCW at overhaul	×		N/A	
92-12-05 07/10/92	PISTON PIN RECALL/		NA by date of overhaul	X		N/A	
93-11-11 06/21/93	LOW PRESSURE DIAPHRAGM FUEL PUMP/		NA affected parts not installed	X		N/A	
95-07-01 03/17/95	CONNECTING ROD BOLTS/		PCW at overhaul	X		N/A	
95-26-02 01/24/96	LOW OCTANE ENGINE DAMAGE/		NA by N number and overhaul date	×		N/A	1

Prepared by Dakota Grantick

96-09-10 07/15/96	ENGINE OIL PUMP IMPELLER/		PCW at overhaul	X		N/A	
96-23-03 10/28/96	HIGH PRESSURE DIAPHRAGM FUEL PUMP/		PCW at overhaul	Х		N/A	
97-15-11 08/12/97	PISTON PIN RECALL/		PCW at overhaul	X		N/A	
98-17-11 10/19/98	CRANKSHAFT CRACKS/		PCW at overhaul	×		N/A	
* 99-04-04 02/25/99	MAGNETO IMPULSE COUPLING/		NA bendix magnetos installed		Х	N/A	
02-19-03 09/20/02	CRANKSHAFT MATERIAL TEST/		NA STC not installed	×		N/A	
04-05-24 03/30/04	CRANKSHAFT GEAR RETAINING BOLT/		PCW at overhaul	X		N/A	
*04-10-14 C1 06/25/04	CRANKSHAFT GEAR AND GEAR RETAINING BOLT/	9-1-2023 Tach: 2070.6	NA no propeller strike this date		X	Propeller strike or sudden stoppage	3621331 A&P
05-19-11 10/21/05	300 HORSEPOWER OR LOWER CRANKSHAFTS/		PCW at overhaul	X		N/A	/ 2 //
*11-26-04 01/25/12	EXTERNAL FUEL INJECTOR LINES/		Superceded by AD 15-19-07		Х	N/A	S A M
12-03-06 02/24/12	AFS FUEL SERVO DIAPHRAGM/		NA affected parts not installed	X		N/A	
12-19-01 10/24/12	CRANKSHAFT RETIREMENT/		PCW at overhaul	X		N/A	
* 15-02-07 03/11/15	PROPELLER GOVERNOR IDLER SHAFT SET SCREW/		PCW at overhaul		Х	N/A	
*15-19-07 11/03/15	EXTERNAL FUEL INJECTOR LINES/	9-1-2023 Tach: 2070.6	CW per AD and MSB 342G		X	110 hours or work done of injector lines	3621331 A&P
17-16-11 08/15/17	ENGINE CONNECTING ROD ASSEMBLIES INTEGRITY/		NA by overhaul date	X	1	N/A	/
22-16-03 08/15/22	S-1200 SERIES MAGNETOS ROLLER BEARINGS IMPROPER LUBRICATION/	9-1-2023 Tach: 2070.6	NA by serial number of magnetos L:F18KA222R R: F18JA043R	X		N/A	3621331 A&P
* 23-09-09 07/17/23	FAILURES OF SPOT-WELDED, MULTI- SEGMENT V-BAND COUPLINGS/	9-1-2023 Tach: 2070.6	NA No turbo or segmented clamp installed	1 121	Х	N/A	3621331 A&P

PROPELLER - Front

Company

Cherryhill Aviation

Manufacturer

MCCAULEY INDUSTRIAL CORP.

Model

B3D36C SERIES

Location Tail # Front N8442H Blade TSMOH 3 Blade 770.6

Serial #

040819

Total Time

6009.2

Tail Number N8442H

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	0	R	Next Comp @ Hrs/Date	Authorized Signature & Number
05-14-11 08/17/05	MAINTENANCE AND REPAIR BY SOUTHERN CALIFORNIA PROPELLER SERVICE/		NA no work done	X		N/A	- field
08-24-07 01/03/07	INSPECTIONS AND REPAIRS BY CSE AVIATION/		NA no work done	×		N/A	JEN 331 AND