N8442H 1981 Piper PA-32-301

Airframe Logbook #2 of 3 2003 - 2010

MSN: 32-8106098




Prepared by the worldwide aviation specialists at RidgeAire, Inc.



	· · · · · · · · · · · · · · · · · · ·			
Aircraft Record Gene	ral Information	·	brote	R venue betetaler
Nanufacturer PA- 3	12-301	Model SMR	ATOga	all all the
serial 32-81060	98	Registration Num	ber <u>N8442</u>	н
pate of Manufacture		*853034		and the second
Engine(s) currently install Wanufacturer <u>Lycom</u>		-540-KIG5	Serial	
Manufacturer	Model	Presevo II	Serial	
Propeller(s) currently inst Wanufacturer		Model HC-	CZYK-IBF	averable
HUB Model	Serial	From	Serial	1002
Blade Model	Serial	Serial	Seri	al
^{Blade} Model	Serial	Serial	Seri	al

.

Description of Inspections, Tests, Repairs and Alterations YEAR: RECORDING TODAY'S TOTAL Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TACH FLIGHT TIME IN TIME SERVICE Facility. (See back pages for other specific entries.) DATE C/W 100 hour Inspection Per South caster Avialy's Insp Guide + SAroro GA maintenany 1965.L manual C/WAD'S 76.07-12 Bendin Surley and. 99-05-09 Induction ani Filter By Replacement AD'S checked Thrue 2003-12. TESTED EXT JIAIN FAR: 91.207 d. Replaced Rf main fire & tube Repland INDUCTION Air Filter. Lules Aircraft INSpectED ALC Lakle Runs. Service Batter, Ecentify This Airney HAS been INSPECTED FIALU A 100 hour Inspection + WAS Determined to be in AN Arrwerthy itin At This fime Neutr APZSZ863688



RONIG AIR SERVICEAFTT:3004.0115A Airport RD.HOBBS:3004.0Newnan, GA 30263DATE: 08/21/03

1.Replaced left brake caliper PN/061-01800, installed new fittings, serviced brake system ops check ok.

- 2. Adjusted door for proper clearance.
- I certify this aircraft, engine or component has been inspected or repaired in
- accordance with current Federal Aviation Regulation and has been determined to be in airworthy condition.
- RICKY RONIG AP259294464IA-----

YEAR: 2004 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
1-14-04	3128.9	1	3128.9	INStalled Need BELT AK-450 per
1. 22	" and the	175	Serie .	750- C914, RTCA DO-183 and DO-160c
	She in part	1.55	Land	control test module Battery change Date
177	N 14 Ste	1 mil	icitien i	MARCH 2007, MAIN UNIT D'CELL battery
1 de	e).		Deres .	change Due MARCH 2006 337 FILED
	65	Section	to boun	Serviced BRAKE fluid MIL 5606, AD 76-07-12
V	NR OT	bylin	- SA in	Bendy switch complied with. BUT condition and
1	T.A.	2701	19891920	operation checked as per 91-2010.
1	• <u>}</u>	10.4	Contrast,	I CREATIFY THES AIRCRAFT HAS been
	1			inspected the a 100 hour inspector and
	1		3ª	ie Arcogetty Asof this Date
1	1		3	40 for 1 AD 1786035

No. of Concession, Name


RECORDING TODAY'S TOTAL YEAR: **Description of Inspections, Tests, Repairs and Alterations** FLIGHT TIME IN TACH Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TIME SERVICE Facility. (See back pages for other specific entries.) DATE Lowe Aviation Co. Macon, GA. FAA R/S ETER699D Lowe Aviation Company- Macon, GA Altimeter P/N \$934PA-1 S/N 06827 Date 12-4-03 N# 84424 Model KING KZ - 76A Serial # 28158 The Altimeter and Static System test required by F.A.R. Part 91.411 has been performed this date 4 Dec 03. Altimeter(s) tested in compliance with Appendix "E", Part 43 F.A.R. to 35000 ft. on date 4 Dec 03 I certify this transponder has been tested and inspected and found to comply with FAR 91.413. No Signature of Author Person Signature of Authorized Person

Description of Inspections, Tests, Repairs and Alterations YEAR: RECORDING **TODAY'S** TOTAL Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TACH FLIGHT TIME IN 2004 TIME SERVICE Facility. (See back pages for other specific entries.) DATE Made Fiberglass Repairs To Wheel Fairings. Replaced Nose Cowling Mounted Ldg. Light Retainer * Repaired Wiring. Aircraft Returned To Service. - - J Vaughe AAP 1970200 IT MAND FIRE 600-6 conclor rolupool botcisidy ok for service etuan Afp 1786035 -15 3180.0 3180.0

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-28	3231.3	4.	3231.3	Replaced RT MAIN time 600-6 CONDOR.
				Braile pads ou for service-
				Justehim Agp 1786035 IA
				a gran the council would star from harmon the
34	3262.8	123.	3262.8	C.W. AD 95-26-13 by metallation of
	8	Salet	SMIT.HOAT_	All New Eugene hoses too C53a next clinge
		MICIE	334814-14338	Due 7.29.2012 - INSTAlled New "O" Ring seals
	The second	SAW O	A ANA	Aurs bracke pade both MLG positions - since
		MUIT	JNUJATITAU	Grade fund with MIL 5606, served battery
		Adrin adrin	A LENGTRAL	aspected condition and checked operation of
	6			ELT TAW 91,2070 ELT BATT Due MARCH 2006
	See. 1		P 1	Bet moderne batt Due moret 2007 (cont. Next page)

Description of Inspections, Tests, Repairs and Alterations YEAR: RECORDING TODAY'S TOTAL Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TACH FLIGHT TIME IN 2004 TIME SERVICE Facility. (See back pages for other specific entries.) DATE see At compleed with 3262.9 B262.8 8-914719 a Trate of Lacarte 10. in S 32.62.8 NU 930 NC REG. # N8442H TOTAL A/G, TIME 3262, SHRS. _ TACH. TIME 3262.8 -I CERTIFY THAT THIS A/C HAS BEEN SPECTED IN Auna ACCORDANCE WITH AN IGIRCLE ON CANNUAL DO HR INSPECTION AS PERPIPER MM 18.53.32 Sam - AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. 1.225.25 231 AD (786035 JA S ANATURE CERTIFICATE NO TYPE MADO TRAFT 200 0110 I TALL CELT MEDELANT. PARTE DILO MARCELEZCO

RECORDING **TODAY'S** TOTAL YEAR: **Description of Inspections, Tests, Repairs and Alterations** TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair 100 TIME SERVICE Facility. (See back pages for other specific entries.) DATE Installed new tire 600.6 LT side 3308.Z 9-11 3308.2 inspited broke pade offer service serviced brokeflind mul 5606 - no looks noted, second NLG sluping champher stop bolts. AD 1786035 IN stalled strid seal ucit IMPMSL PTMIG 9.25 3318.D 3318.0 strut serviced Both MAM struts with Mil 5606 and nutrogen to M.M. Limits, Deplaced tAIL Light Bulle and Lens- Jay m AP 178603555



	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
4	1			the second s

Lowe Aviation Company

Macon, Georgia

Aircraft registration	N8442H	Date
Model	PA-32	Work Order
Serial Number	32-8106098	Hour Meter/Tach

おくかれれ

- 20TO 1

143-222

Serviced left strut, replaced left main tire, replaced left and right brake linings, _____ replaced right landing lite, installed wheel fairings. This aircraft is returned to service. Details are on file under Lowe Aviation Co. work order # 8213 & 8237.

Feb. 07, 2005 8213 / 8237


3427

Nick W. Porcel Repair Station # ETER699D

Description of Inspections, Tests, Repairs and Alterations YEAR: RECORDING TODAY'S TOTAL Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TACH FLIGHT TIME IN 2005 TIME SERVICE Facility. (See back pages for other specific entries.) DATE INSTAlled New united instrument MANIfol 3493.7 7-22 3493.7 Fuel pressure gauge pt No 6331, Ser No 83869 Date 4.00 Serviced (charged Battery AP 1286035 INStalled New/Repaired Auto pilot computer pt. No. 1 D757 61002003 Ser ND. 1959E 7-13 3542.7 performed subopilot static system leave child penainal 3 major leaves in hose connections-Level pate within Limits. Detur. Uto service AD178635

RECORDING **TODAY'S** TOTAL YEAR: **Description of Inspections, Tests, Repairs and Alterations** TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TIME SERVICE 100 Facility. (See back pages for other specific entries.) DATE 3621.4 3.21.4 10-MIL 5606-Serv See Comp Operationer Felt 2006 ree de o NGREG. # NO442 DATE 10 TOTAL A/G-TIME 2/2 I CERTIFY THAT THIS AIG HAS BEEN INSPECTED IN ACCORDANCE WITH AN TOIRCLE ONE ANNUALIDO HR INSPECTION AS PERZEDAL MITTE AND WAS DETERMINED TO BEAN AN AIRWORTHY CONDITION. AD 1766035 TA SIGNATUR CERTIFICATE NO JTYPE

(名書)門



YEAR: 2005 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11-16	3662.7	1009	3662.7	FNSTAlled New Gill 635 MARCRAFT
+-	Warant	fraid	Telefal	BATTER Ser NO G 02192208-
DXAS	I WIE .	282	As pr	INSTATLED New CONDOR 600×6×6pr
N.	17-62	1.22	stant	tire on AT MAIN LAnding Genoz
-	1/29378	die f	1)-).291	Juife Jun Ap 1786035
6 06)	g the	408	3 ,000	B3N36CH33-C Se
3-6	3686.1	E.A.S	3686.1	Removed Eugine # L-21408-48A
Nor	AJELD'FE	holla	They	IN stalled FActory Rebuilt Engine F0-540-KIG5 Ser# RL- 30652-48.A
			1	70-540-KIG5 ser# RL- 30652-48.A
	AFTA-R	MOA	wind.	0.0 total time. Fristalled 2 each Lt 3RT
	1215		N SQUE	overhaulad oil coolers p.N. 20003A and 85292
		Sec. Mar	Stalling .	watalled New Arrwolf vacume pup (wet) per

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	2-ASO:	MAR .	630	IN struction monune AFC Report NO. PIDO
Segar.	-8	220	PISA	Rev. B. MAY 10, 2005, INStalled Airwolf
390	xax	600	51601	Air/oil separater per STC SA 3839 WE ZAW
1	57	Geor	renja	AFC-W315 Arwolf ENstructions. 337 filed
	₽-1-	7:50	SASI	ENStalled McCauley three blade propeller
Ser Ser			Paker	133036 C433-C Serva 040819 thin
R. W.S.	ASt	-80.	115 - 1	date IAW INStall - INstrut TR 863 Feb 24, 97
		J.J.a.	3 th	337 Filzed this Sale, Installed New Brad
14	A-81	-520	130	fund Peservior,
5127.	1 10 ma	(2.	Galle	Quinter ADT 8035
1628	A and	20003	P.N.	prology (19 Delivert reng
1.00 (town n	Ma H	intrai	Discherthe der Alexander

RECORDING TODAY'S TOTAL **Description of Inspections, Tests, Repairs and Alterations** YEAR: TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TIME SERVICE Facility. (See back pages for other specific entries.) DATE and and to be assisted. THE ALTIMETER AND STATIC SYSTEM TESTS REQUIRED BY F.A.R PART 91.411 HAS BEEN PERFORMED THIS DATE 22 DECOS ALTIMETER TESTED IN COMPLIANCE WITH APPENDIX E PART 43 TO SOO FEET. DATE 22 DE COS STATIC SYSTEM CHECK PERFORMED BY RAY ALLEN'S ELECTRONICS, INC. BUTLER, GA. F.A.A.R/S #HS4R243M SIGNED Salla DATE 22 DOCOS DATE <u>22 DOCOS</u>I CERTIFY THIS ATC TRANSPONDER (MAKE) KING (MODEL) KT-764 (SERIAL#) HAS BEEN TESTED, INSPECTED AND FOUND TO COMPLY WITH APPENDIX F OF F.A.R. 43 AND PART 91.413 F.A.A. R/S#HS4R243M SIGNED K Allen DATE 200005 TESTS PERFORMED BY RAY ALLEN'S ELECTRONICS, INC. BUTLER, GA.

YEAR: RECORDING **Description of Inspections, Tests, Repairs and Alterations** TODAY'S TOTAL TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair 2006 TIME SERVICE Facility. (See back pages for other specific entries.) DATE 37219 3721.9 2-01 INStatled Repau instrumente UI, Altimater pt.No. 5934 Ser NO 06827 performed attatic ages level cheels , **CSG AVIATION** DATE: 1/13/2006 A/C Reg #: 8224H A/C Tach: 3711.1 A/C S/N: 32-8106098 Installed new ignition switch p/n 10-357200-1. Ops check good at this time. Tightened flex line connections on air oil seperator and vacuum pump. Washed engine no leaks noted at this time? Rodney Johnson IA255196787

1	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries mus	st be endorsed v	etions, Tests, Re with Name, Rating a pr other specific ent	and Certificate Nu	erations Imber of Technician of	r Repair
	1		the stand	an tai	is 1 al	Int sprin		1 - 1	1
					in our	se line			R.
	R		Dumont Aviati 850 Airport Ro Lawrenceville	d.	inter Trea	1 atranti			
	The Fe		8442H Jork was Perfo	Aircraft S/N ormed:	32-8106098	TACH	HRS		
			-,		and the second	the second		OM KNS 80 TO CDI	WAI
AL SL	I certif	fy that this a	aircraft has be	een inspected in	n accordance v	T KNS80 RACK IA with FAA approved oved for return to s	d regulations and		
		Re	f. Dumont Avi	iation W/O No.	607	For details.			
	Sign	ature:	1ha	471	more	1 March	Date:	1/31/2006	
			-0	Arthur T. Moo	ore	FAA Approved (CRS# UO8R928>	<	
				and and the state of the state					

YEAR: RECORDING **Description of Inspections, Tests, Repairs and Alterations** TODAY'S TOTAL TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TIME SERVICE Facility. (See back pages for other specific entries.) DATE INStalled New condor 500×5×6pr tive 2-17 and 500×5 mitchlin tale on WLG. Eastalled New condoy 600×6×6prtue IT MLG, Forstalled new unsche Droba EGT AP1786035

1	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries		sed with Name			s Technician or Repair
1	19.3			1	Interne	0-11-1			P.
	1				12				
1	JAN CONTRACTOR		Du	mont Aviati	ion Inc				
1		1	850	Airport Ro	d.				
1	2-110	(1		, GA 30045				
-	TOTAL INT		N 844		Aircraft S/N			HRS	3 —
-	N A	ADJU	STED BLIND	TRANSPO	ONDER ENCO	DER TO TO	LERANCE.		
-	325						e with FAA approve		nd —
	1573		letermined to	be in an air	rworthy conditio	on and is app	proved for return to		
			Ref. D	umont Avia	ation W/O No.	671	For details.		
	tran da	Signa	ature:	12	4) Th	In		Date:	3/1/2006
					Arthur T. Moor	re	FAA Approved	d CRS# UO8R92	.8X
			a Brann						and a second sec
				frame and the second					

VEARI 2006 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
3.29				INStalled pitch trun serves ptwo 18373-1-5 Cor NO 8201 overhauld By Autopilots Gutont- INStalled pitch trun Aft CAble prum ptwo 63530-000, INStalled New At field putchtru
				cable pt NO 62701-135. IN Stalled And Rigge the above components PACO the piper MM operation check on fest flight system Normal, July non Api786035TA.
	191716		. 26.43	in the sea of the sea of the
		a water	2427.090	

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	TACH	TACH FLIGHT	TACH FLIGHT TIME IN

			for the second					
	Dumont Aviatio	on, Inc.	1				-	
	850 AIRPORT	RD.						
@	LAWRENCEV	ILLE, GA 3004	15					
	N 8442H	Aircraft S/N	32-8106098	TACH	3824.0	HRS		

REMOVED KNS80, KY197, KLN94 GPS, KA-92 ANTENNA AND MD41 ANNUCIATOR.

INSTALLED GARMIN GNS430 GPS/NAV/COMM UNIT AND GA-54 ANTENNA IAW INSTALLATION MANUAL 190-00140-02 REV Q AND AC20-138A. REF STC SA00705WI, FLIGHT MANUAL SUPPLEMENT DATED 11/21/2002 AND FAA FORM 337 DATED 6/9/2006 P/N: 010-00139-11; S/N: 97134311. AIRCRAFT APPROVED FOR IFR ENROUTE, TERMINAL AND NON-PRECISION APPROACHES. REMOVED TURN AND BANK INDICATOR AND INSTALLED CASTLEBERRY MODEL 2040A STANDBY ELECTRIC ATTITUDE INDICATOR. INSTALLED IAW INSTALLATION DWG 300-14EL REV F AND AC91-75. P/N: 504-0006-954; S/N: 206D03914.

I certify that this aircraft has been inspected in accordance with FAA approved regulations and was determined to be in an airworthy condition and is approved for return to service.

Ref. Dumont Aviation W/O No.

777 For details.

Signature:

Arthur T. Moore

Date: FAA Approved CRS# U08R928X

6/9/2006


YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	3870			REPLACED HEAT ASSY FOR FRECT. ATTUDADE IND.
			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	REPLACED HEAT ASSY FOR FEEL. ATTUDADE IND. 151507478 ASP PHILLE
Reg # W/O # Hobbs Tach TTAF	N8442H 60283 NA 3837.6	AIRFRAI	Removed w & inspected and serviced PN MS2469 performed in ac	wheel pant from LH wheel. Removed brake. Removed LH wheel assembly. Disassembled, cleaned wheel halves. Cleaned, inspected, and repacked wheel bearings. Installed new 600 X 6 X 6 tire d. Reinstalled wheel assembly and wheel pant on aircraft. Replaced rounded out screws with new 03S274.
1		***END**		formed.
abAviat	· · · · · · · · · · · · · · · · · · ·	19 Aviation V inesville, GA		ohn HZ Reiner AP 149426349 h 4
				Sames wanted and the second state of the second state
				Le the H
	1.1.			the water and the particular and the


Description of inspections, Tests, Repairs and Allershand Airframe YEA or Repair Work Order # Hobbs AFTT Registration # Tach 60469 NA 9921.0 N8442H DAT 1. Removed LH and RH brake calipers. Cleaned and replaced seals. Reinstalled calipers. Bled brakes. 2. Replaced LH and RH brake pads with new linings PN 066-06200. **END** All work has been performed in accordance with current FAA regulations. This aircraft is approved for return to service with respect to the work performed. 10/6/2006 Ken Munch AP 1906126 Date ab Aviation uc 1119 Aviation Way Gainesville, GA 30501 MIIISUUIU, UN 9/ 123 (503) 648-0331 FAA/PMA LENS AC NO. STC. NO. SA . 2356-NM PART NORD-6001-R AC S/N PA.32.301 INSTALLATION FOR and the second second

YEAR: RECORDING TODAY'S **Description of Inspections, Tests, Repairs and Alterations** TOTAL TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TIME SERVICE Facility. (See back pages for other specific entries.) DATE we tach untalled Serverde 9-21-6 Rencord 2921.6 Aelsture 3921-L an 3921-6 9905.9 Servir able tach 9905.9 tins RRW AD 1786035 10-12 3938,6 99229 Removed tach westalled New Mitchell OID TACH P/N DI-112-5023 SN 26710 0,0000 New MITCHELL AIRCRAFT PRODUCTS, INC. 3-1/8" CW MECH TACH 2300 RPM D1-112-5023 S/N_26710

Description of Inspections, Tests, Repairs and Alterations TOTAL RECORDING **TODAY'S** VEAR: TIME IN FLIGHT Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TACH 2006 SERVICE TIME Facility. (See back pages for other specific entries.) DATE 3969.0 New tive couclos 600×6×8 30.4 11-3 Brake or for M.L.G. Service - serviced B Con und MIL 5606 AD1786035 I New 1/4" + hick LEE Barley 3976. INSTA 38 11-13 D there date. sealed All cabin windstu woth prokent Ap 1786035

YEAR: RECORDING TODAY'S **Description of Inspections, Tests, Repairs and Alterations** TOTAL TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TIME SERVICE Facility. (See back pages for other specific entries.) DATE 12-22 INSTALLED New Coppertop BUT Next Batteren due 12/8 Twota led veres static wick L.H Freshed New GRD. Loine Lt ileron otba huge Acd INDuction AIT filter Cover with New Door. pt. 38019-008 - Muding Bean struts to proper Cleaned Corrison from Socket tatted new Rt Wing NA and Service AC Battery





REC TAC TIN		TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repa Facility. (See back pages for other specific entries.)					
	Airframe	ration #	Work Order #	Hobbs	Tach	AFTT			
35	N84		70039	NA	67.90	7. TT			
	1. Remo **END**	ved electric fu	uel pump switch. In	nstalled new switch F	PN 587-826. Oper	ational check of fuel	pump OK.		
100	- All work	has been nor	formed in accordan	ce with current FAA	regulations This	aircraft is approved f	or return to service	with respect to t	he work performed.
100	All WORK	nas been pen	orned in accorda			and are to approved t			
				2					
		- A		h	John HZ Reine	AP 149426349		_	12-Jan-200 Date
				h	John HZ Reine				12-Jan-200
		- A		h	John HZ Reine	AP 149426349			12-Jan-200
		- A		h	John HZ Reine	AP 149426349			12-Jan-200
		- A		h	John HZ Reine	AP 149426349		-	12-Jan-200
		- A		h	John HZ Reine	AP 149426349			12-Jan-200
		- A		h	John HZ Reine	AP 149426349			12-Jan-200
		- A		h	John HZ Reine	AP 149426349			12-Jan-200
		- A		h	John HZ Reine	AP 149426349			12-Jan-200

and the second second

and the second sec

YEAR: RECORDING TACH TIME DATE	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, I Entries must be endorsed with Name, Ratin Facility. (See back pages for other specific e	g and Certificat	Alterati te Number	ons r of Technician c	r Repai
			iation Company				
Aircraft regis Model Serial Number Removed fai Details are o	er ulty encod	N8442H PA-32-301 8106098 der and repla	Date Work Order Hour Meter/Hobbs ed with new Transcal Blind Enco ion Co work order # 8914. Ray M Cannon Repair Station # ETER69		4021.		

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	N Entries must be endorsed with Name Bating and Certificate Num				
Airframe	on #Work	< Order #	Hobbs	Tach	AFTT		
N8442		0247	NA	161.80	Unknown		Cessna
3. Reinsta **END**	led pilot window	vlatch.			led new overboard ve s aircraft is approved	P. Land	respect to the work performed.
		N.	cholas	S.Ce	rte		24-Apr-2007
abA	riation uc		11		ter AP 256618370 Gainesville, GA 305	501	Date
	1	and the second		ANTIN			
GENCY	1 257	Long Lange					The second second
			7 7 7 7 7 7 7			1000 1000	
AP2521	6 68812						

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Insp Entries must be endorse Facility. (See back page	ed with Name, Ra	ating and Certif	nd Alteration icate Number o	of Technician or Re
1					and survival and a second state of the second	199 J. 199	-210	1
1	AIRFRAME	Registr N84	ation # Worl 42H 7	Order # Hohbs 0475 -	Tech 260.30	AFTT CINK		
	bled brakes. O	perational che	eck good at this tin	with new PN 066-10500 Remov	ed left and right calip	ers and replaced	packings Reinsta	led calipers and
	- order reference	ed above. This		ed for return to service with respensive of the loss o	ct to the work perform AP 256618370	ned.	Cessna	0n file under work 15-Aug-2007 Date
		ed above. This		ed for return to service with respe	ct to the work perform AP 256618370	ned.		15-Aug-2007
	- order reference	ed above. This		ed for return to service with respe heles S.C. Nicholas S Carter	ct to the work perform AP 256618370	ned.	Cessna	15-Aug-2007
	- order reference	ed above. This		ed for return to service with respe heles S.C. Nicholas S Carter	ct to the work perform AP 256618370	ned.	Cessna	15-Aug-2007
	- order reference	ed above. This		ed for return to service with respe heles S.C. Nicholas S Carter	ct to the work perform AP 256618370	ned.	Cessna	15-Aug-2007

Replaced right main time, PN# 600x6x6

0-1-07

8442H

Tach:

0313

i

Airframe

Log

bearings. Aircraft returned to Service erviced

11-12-2007 8442H Tach: 367.0 Replaced nose tire and tube PN# 500x5/6/120 and PN#

TOTAL

500x5. Repacked wheel bearing. Replaced left wing tip bulb PN# GE4509. Repaired wire to nose landing light. Serviced left brake system. With respect to work performed, this aircraft returned to service.

Description of Inspections, Tests, R

and aread with Name Bating

P

2863

688IA

ay

ne

 \Box

Newton

Wayne C. Newton AP252863688IA

RECORDING

T'

VEAR:

DATE

TODAY'S

DATE 12-19-07 T.T. 4348.0 TACH 409.4 Airframe Inspection Performed I/A/W/ FAR Part 43. Checked Skin for Condition <u>Cleanliness</u> Batteries Seats and Safety Belts ____ Windows & Windshields /- Instruments --Flight Controls <u>Flight Controls</u> Flight Controls <u>Flight Controls</u> Sumps & Fuel Screens - Fuel Systems - Electric Systems Oxygen System NA Oleo Struts Landing Gear Lights Pilot Heat ELT Operation Static System Cables, Pulleys, Fairleads and Torque Tubes Wing Fittings ____ Wing Struts ____ Gear & Stall Warning Devices NA Lubricate Gear Fittings - Performed Landing Gear Retraction Test NA Repacked Wheel Bearings ELT Battery Replacement Due 12 - 2008 A.D. Compliance Record at Rear of Log and Researched Through Issue 2007-24 1. I Certify This Airframe Has Been Inspected I/A/W/ an Annual Inspection and Was Determined to be in an Airworthy Condition at This Time. Wayn C Thewton AP 2528636887A

1s, Tests, Repairs and Alterations Jame, Rating and Certificate Number of Technician or Repair er specific entries.)

ELT TESTED I/A/W FAR 91-207 d

TODAY'S TOTAL Description of Inspections, Tests, Repairs and Alterations RECORDING YEAR: TIME IN FLIGHT Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TACH SERVICE TIME Facility. (See back pages for other encoific entries) D & D AVIONICS SERVICES, INC. D & D AVIONICS SERVICES, INC. 2725A HERBERT SMART AIRPORT RD. 2725A HERBERT SMART AIRPORT RD. MACON, GEORGIA 31217 MACON, GEORGIA 31217 A/C PA32-301 Date: 2-22-08 S/N 32-8106093 184421 A/CTT 461.2 WO # 36126 Date: 2-22-08 A/CPA32-301 S/N 32-8106098 N84421+ A/CTT 461.2 WO# 36126 FAR 91,411 I certify that the altimeter and altitude reporting equipment tests and inspections required by FAR 91.411 have been performed. The FAR 91,413 I certify that the ATC transponder test and inspection required by FAR altimeter P/N 59 34PA-1_S/N_OG827. The static system was 91.413 have been performed on 2-22-08. The integrated tested on 2-22-08 . The automatic pressure reporting syste system test and inspection was performed on 2-22-08 was tested on 2-22-08 #1 Transponder Model: <u>KT=76A</u> S/N: <u>28158</u> #2 Transponder Model: <u>NIA</u> S/N: <u>NIA</u> I have found this aircraft airworthy with respect to the work performe and approved for return to service. I have found this aircraft airworthy with respect to the work performed and approved for return to service. Technici FAA Repair Stati Technician Number DXDR595 FAA Repair Station Number DXDR595X

Description of Inspections, Tests, Repairs and Alterations TOMY'S TOTAL RECORDING YEAR: Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair FLIGHT TIME IN TACH SERVICE TIME Facility. (See back pages for other specific entries.) DATE Replaced Rt MAIN Time AND fibe Assy. PNE 092-315 0 & OTE-3170 AS TO Respect to Work Performed Aircraft Refurned to Service - Wayn Mustin AP252863688374 3-3-08 414.8


RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tes Entries must be endorsed with Name, F Facility. (See back pages for other spec	Rating and Certificate Number of Technician or Repair
TT: <u>513.0</u> Installed loa GA-56 GPS S/N 33770. Performed 1 good. Refe	08 A/C PA aner GNS-4 S antenna a Performed flight test re er to 337 da d this aircra	Arrow P/N 010 Arrow P/N 010 Ar	cs Services, Inc Smart Airport Rd. eorgia 31217 32-8106098 N8442H WO 36148 0-01060-40 S/N 97118969. Removed new GPS antenna P/N 013-00235-00 gramming and ground checks good. tallation manual and system checked installation details. with respect to the work performed and maniel Smith A CRS # DXDR595X	6-2.2008 JUSTALLEP AL Tach: 5585. New Brake Acounty PN# 066-0 b200 With Respect to Work Pertam Anoraft Returned to Service. Ubuyue Mewber AP 52863686 JA 9-26-08 Tach: 619.5. Resaled Att At Brake Calipin Replaces Returned to Service Wayne Chewter AP 752863688 J

YEAR:	Repairs and Alterations
DATE	01-15-2009 N8442H Tach: 737.6 ACTT: 4676.2 TSOH 988.4 g and Certificate Number of Technician or Repair
ji ji	Complied with 100 hour / annual inspection per FAR43(d). Complied with
st the	AD's 76-07-12, 78-09-07, 93-02-05, 99-05-09. AD's checked through 2009-1A AD Tool Box. See AD compliance record for sign off. Replaced
de.	ELT battery, next due 1-2011. ELT tested i/a/w FAR 91-207(d). Replaced pilots left window, pn# 1216-62282. Replaced ventilation blower, assy pn#
- 55	452-935. Replaced induction air filter, pn# BA-3 Removed all inspection
And and	plated. Inspected all cable runs, pulleys and fairleads, lubed entire aircraft. Cleaned & repacked
	All wheel bearings. I certify this airframe has been inspected i/a/w and annual inspection and
	was determined to be in an airworthy condition at this time.
	Wayne C. Newton
and a	AP252863688IA
1	and the second s
	and have the same and the
	A CONTRACT OF THE OWNER
R TRA	When Claude AP352863

RECORDING TACH TIME	TODAY'S Flight	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair
(Fill)		and the second s	I termin from any holder on Annual and
		2725A H	D Avionics Services, Inc Herbert Smart Airport Rd. acon, Georgia 31217
Date : TT: <u>07</u>		A/C PA-32-301	1 S/N 32-8106098 N8442H WO 36330
	overhe origina 2. Remo louver 3. Repla	nead assembly nal interior plasti oved broken cal ers. Painted duo	abin forward and center ducts with new Air ucts to match original interior plastic color. overhead lighting dimmer rheostat piper P/N 456-
		s aircraft airwor eturn to service	orthy with respect to the work performed and
			Daniel Smith FAA &RS # DXDR595X
		A service of the	

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	TIME IN Entries must be endorsed with Name Bating and Certificate Number of Technician or Benair				
	Chemilies AD 3 75-0 - NOSA 1 - A ELT batters 452-935 Re pranto ne pr Cleaned & F Ad wised by reactions with determine Ad 252-945 reactions Ad 252-945 reactions r		Serial Num Terrain Data	gistration: $8 + 4 + 2 + 4$ Date: $1 - 1 + -09$ ber: $32 - 810 & 60 & 98$ Hobbs/Tach: 0737.6 abase 08T2 for TERRAIN/TERRAIN-SVS has been Hobbs/Tach: 0737.6 Babase 08T2 for TERRAIN/TERRAIN-SVS has been Hobbs/Tach: 0737.6 Babase 08T2 for TERRAIN/TERRAIN-SVS has been Hobbs/Tach: 0737.6 Babase 08T2 for TERRAIN/TERRAIN-SVS has been Hobbs/Tach: 0737.6 Signature $DXOR 595 \times$ $000000000000000000000000000000000000$				

	- 1 m	A							
RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Tech Facility. (See back pages for other specific entries.)						
Aircraft Serial N	Registrati umber: 3	on: <u>NS</u> 2-8106	142H Date: 2112/09 098 Hobbs/Tach: 0758.3						
Main So installed	oftware Ve d and teste	ersion 3.20 a d according	and GPS Software Version 3.2 has been to Garmin Service Bulletin 0848 Rev. A						
Author	hut ized Signa	K	DXDR 595X Certificate Number						



		Hobbs	Tach	AFTT		Carles Contraction	*
							sooan daay
I temp sensor wire.		lled new custome Faculty (a	er supplied door seals	stin Nauné, Fial or other apealis st	ing and Cedification (Serings)	livences of Te	inician or Repair
			and analizable maint		Details of work are on	file upder work	
as been performed e. This aircraft is a	approved for return to	b service with res	spect to the work perfo	ormed.	Setairs of work are of	Service Contraction	
- 12	- A				Cessna	13-Mar-2009 Date	
nuc	111	9 Aviation Way	Gainesville, GA 305	01	Service Station		
						1	
S. S. Starle			talk	A. white	1. Maria		
Star Line	2 and and a	Sand S					
	• 1		3-02-27/0			Transal -	
						harrister.	
	5 5 5 M 100	100 C 100 C 100	and the second se				
	N8442H and passenger en I temp sensor wire area and applied v	N8442H 90089 and passenger entry door seals. Instal I temp sensor wire. area and applied wing walk paint. as been performed in accordance with I re. This aircraft is approved for return to	and passenger entry door seals. Installed new custome I temp sensor wire. area and applied wing walk paint. as been performed in accordance with FAA Regulations re. This aircraft is approved for return to service with res Manual Garry D Gree	N8442H 90089 NA 781.30 and passenger entry door seals. Installed new customer supplied door seals. I temp sensor wire. area and applied wing walk paint. as been performed in accordance with FAA Regulations and applicable mainting. This aircraft is approved for return to service with respect to the work performed.	N8442H 90089 NA 781.30 Unk and passenger entry door seals. Installed new customer supplied door seals I I temp sensor wire. area and applied wing walk paint. I I as been performed in accordance with FAA Regulations and applicable maintenance manuals. If the work performed. If the work performed. Magnet Accordance Image: Construction of the work performed. Image: Construction of the work performed. Image: Construction of the work performed. Magnet Accordance Image: Construction of the work performed. Image: Construction of the work performed. Image: Construction of the work performed. Magnet Accordance Image: Construction of the work performed. Image: Construction of the work performed. Magnet Accordance Image: Construction of the work performed. Image: Construction of the work performed. Magnet Accordance Image: Construction of the work performed. Image: Construction of the work performed. Magnet Accordance Image: Construction of the work performed. Image: Construction of the work performed. Magnet Accordance Image: Construction of the work performed. Image: Construction of the work performed. Magnet Accordance Image: Construction of the work performed. Image: Construction of the work pe	N8442H 90089 NA 781.30 Unk and passenger entry door seals. Installed new customer supplied door seals Itemp sensor wire. area and applied wing walk paint. area and applied wing walk paint. Itemp sensor wire. as been performed in accordance with FAA Regulations and applicable maintenance manuals. Details of work are on the work performed. Month Mark Garry D Greene AP 3254638 Garry D Greene AP 3254638	N8442H 90089 NA 781.30 Unk and passenger entry door seals. Installed new customer supplied door seals Itemp sensor wire. area and applied wing walk paint. area and applied wing walk paint. as been performed in accordance with FAA Regulations and applicable maintenance manuals. Details of work are on file under work re. This aircraft is approved for return to service with respect to the work performed. Mar-2009 Garry D Greene AP 3254638

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries n	nust be endors	pections, Tests ed with Name, Ra es for other specific	ting and Certif	nd Alterations icate Number of Te	echnician or Rep
	AIRFRAM	E	stration # W 3442H	Vork Order # 90121	Hobbs NA	Tach 799.50	AFTT	×.	
	2. Removed 3. Removed	and replaced I and replaced I	battery with new	be with serviceab PN G35 SN G02 new bulb PN 45	394362. Serviced	battery with acid and	charged.		EN STR
	I certify that a order referen	II work has be	en performed in his aircraft is app	accordance with proved for return	FAA Regulations to service with res	and applicable mainte pect to the work perfor	nance manuals. med.	Details of work are on	file under work
	I certify that a order referen	II work has be	his aircraft is app	proved for return	to service with res	and applicable mainte pect to the work perfor Aut AP 2887269 Gainesville, GA 3050	med.	Details of work are on the second sec	file under work <u>1-Apr-2009</u> Date
	I certify that a order referen	III work has be ced above. Th	his aircraft is app	proved for return	to service with res	pect to the work perfor	med.	Cessna	1-Apr-2009
	I certify that a order referen	III work has be ced above. Th	his aircraft is app	proved for return	to service with res	pect to the work perfor	med.	Cessna	1-Apr-2009
	I certify that a order referen	III work has be ced above. Th	his aircraft is app	proved for return	to service with res	pect to the work perfor	med.	Cessna	1-Apr-2009

2

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-------	---------------------------	-------------------	-----------------------------	--

DAYTONA AIRCRAFT SERVICES

DATE: 5/21/2009

Tach: 833.3

Installed Vac pump P/N 3P194, S/N A00131, ops check normal. All work was performed in accordance with current regulations of the FAA and is approved for return to service Details on file at this Repair Station under WO# 9384

Daytona Gircraft Services, Inc.

Daytona Aircraft Services CRS DYTR262K

YEAR:	TOTAL TIME IN SERVICE	Reference of Major Repairs and Major Alterations To FAA Form ACA-337 by Date, or to the Work Order by Number and the Approving Agency

DAYTONA AIRCRAFT SERVICES

DATE: 6/5/2009

TACH: 845.9 A/C TT: 4784.2

I certify that this Aircraft has been inspected in accordance with a Annual inspection and was determined to be in airworthy condition. The following work was performed: The ELT was tested I/A/W 91.207 (d) (1-4) and has passed all tests. Repaired Annunciator panel. ELT battery next due Jan 2011. Installed new brake disc's and pads. Installed new central Vac system filter. AD's checked to 2009-11 All work performed in accordance with current regulations of the FAA and is approved for return to service. Details on file at this Repair Station under W/O # 9439

Daytona Aircraft Services, Inc. CRS DYTR262K

Daytona Gircraft Services, Inc.

JATOT A	
18 6 6 1 K	STTP-B
5-1111	

15....

Daytona Aircraft Services, Inc. 561 Pearl Harbor Drive Daytona Beach, FL 32114	OWNER NAME		Maria	DATE 7-22-09	WRITTEN BY	WD# 9741	
386-255-2049 FAX 386-255-6120	ADDRESS		MAKE PIPER		MODEL PH		
FAA Certified Repair Station DYTR 262 K	CITY & STATE		SERIAL #		REG. NO.	REG. NO. N8442H	
09-14	PHONE NO CALL WHEN COMPL					LOG BOOKS RECEIVED () LOG BOOKS RETURNED ()	
DISCREPANCY		CORRECTIVE ACTION					
WEL LEAK R/H S.	1921	2) REA OF TO	AINTE	D BURG BURG GS, WIN = 0 UP W	HINTER HITE	AND	
PAD					LA TO PAJ	TAL 3, 502-00 TAL 183-20 PECTION ARGES	
A/C Total Time Eng. Total Time Eng. T.S.M.O.H Tach Time Prop T.S.M.O.H	I HEREBY AUTHORIZE THE ABO	RE, THEFT OR ANY OTHER U UNDERSTOOD AND AGREEL ES, INC. HAS NO OBLIGATI R FACILITY FOR WEATHER TO DO SO WILL NOT CONST AIRCRAFT SERVICES, INC.	CAUSE D THAT ON TO PERILS TITUTE Date ALONG CAUSE THE ALONG CAUSE THE ALONG CAUSE THE ALONG CAUSE THE ALONG CAUSE THE ALONG CAUSE TERATON THE AIT TERATON TERA	craft (or part) identified a l and inspected in accordan ons of the Federal Aviation pproved for Return to Servic are on file under this order.	Administration e. BAU	иснт 1/3C 40-2 в	
QTS. OIL GALS MS	IAL AND HEREBY GRANT YO SSION TO OPERATE THE A/C I E OF TESTING AND/OR INSPE EN IS HEREBY ACKNOWLED/C THE AMOUNT OF REPAIRS TH	HEREIN CCTION. GED ON GERETO	ate No BOOKS SIGNED OFF (1) FAA CERTIFIED REPAIR DYTR 262 K	TIR FEI OYES ()NO STATION	TIRE WASTE FEE		



Date: 12-03-2009 Make: Piper Model: PA-32-301 S/N: 32-8106098 Tach: 927.8

Removed and replaced left main tire. Installed new Good-Year Flight Custom 3 6.00x6 8-ply tire. Removed and replaced left main wheel outer bearing retainer ring. Serviced left main wheel bearings.

The aircraft listed above has been inspected and repaired IAW manufacturer's maintenance manuals and current FAA regulations and is approved for return to service.

Jeff Huddleston AP2828753

EAR:	TOTAL TIME IN SERVICE	Manufacturers' Mandatory Service Bulletins Chronological Listing of Compliance and Method of Compliance	(14377
ATE		Imm Mthattmets Huthmen Moderne Saut Nonton on Moderne	(CTTTTT)
		DATE: 12/14/2009 TACH: 936.3 Removed Airwolf wet Vac pump. Installed new dry Vac pump P/N RA215CC, S/N A37835. All work was performed in accordance with current regulations of the FAA and is approved for return to service Details on file at this Repair Station under WO# 1519 Daytona Daytona Autor aft Services CRS DYTR262K	
	to terrary of the or	Or hereite and the second and the se	
ind as	interior de la come	A MAN WAR AL	1. Constanting

YEAR:	TOTAL TIME IN SERVICE	1. 1. 1. 2. 1. 1.	nt Addition, Re		xchange	nysilanoù kega	ajneras unave rendogical babi		
DATE		Item N	lanufacturer's Na	me M	odel Se	rial Number			
	AIRFRAME	Registration # N8442H	Work Order # 10170-01-2010	Hobbs NA	Tach 976.00	AFTT		112114	t ∋d for Optio
SN	1 T8949A. Reinsta	Iled HSI. Operation	ficial Horizon. Remove nal check OK. d in accordance with F						it ed for Opti ed for Opti jed for Opti
ord	ber referenced abo	ove. This aircraft is	approved for return to	service with respe Munch Ken Munch A	ect to the work perf	formed.	Cessna Service Station	12-Jan-2010 Date	t nt ed for Opti ged for Opt
	and the	kan ka					Addition of	of Optional Equipme f Required–Exchan of Required–Exchan	ged for Opt
							Removal of Addition of	Optional Equipment f Optional Equipme Required–Exchang Required–Exchang	nt ed for Opt
							Removal of Addition of F	Optional Equipmen Optional Equipmer Required–Exchang Required–Exchang	nt ed for Opti

YEAR:	TOTAL TIME IN	Equipment Addition, Removal or Exchange	And the second s
DATE	SERVICE	Item Manufacturer's Name Model Serial Number	
	Sector Sector		Addition of Optional Equipment Removal of Optional Equipment on of Required–Exchanged for Optional val of Required–Exchanged for Optional
		DAYTONA AIRCRAFT SERVICES	on of Optional Equipment val of Optional Equipment on of Required–Exchanged for Optional val of Required–Exchanged for Optional
	DATE: 2/ Repaired	11/2010TACH: 998.7N8442HRt wheel fairing and painted. Installed new Rt gear fairing. Replaced Rt tire with new,	on of Optional Equipment val of Optional Equipment on of Required–Exchanged for Optional val of Required–Exchanged for Optional
		bearings. All work was performed in accordance with current regulations of the FAA and ed for return to service Details on file at this Repair Station under WO# 1744 Daytona Aircraft Services CRS DVTR262K Gircraft Services, Inc.	on of Optional Equipment val of Optional Equipment on of Required–Exchanged for Optional val of Required–Exchanged for Optional
	Dayton	Aircraft Services CRS DYTR262K Gircraft / Services, Inc.	on of Optional Equipment val of Optional Equipment on of Required–Exchanged for Optional val of Required–Exchanged for Optional
-		Descention of the second of th	 Addition of Optional Equipment Removal of Optional Equipment Addition of Required–Exchanged for Optional Removal of Required–Exchanged for Optional

1.17

YEAR:	TOTAL TIME IN SERVICE	Equipment Addition, Removal or Exchange	Liver diar mgan horrna
DATE		Item Manufacturer's Name Model Serial Number Item Manufacturer's Name Model Serial Number DATE: 3/2/2010 Tach: 1016.8 DATE: 3/2/2010 Tach: 1016.8 Replaced battery with new part# G-35 serial# G02478213 All work was performed in accordance with current regulations of the FAA and is approved for return to service Details on file at this Repair Station under WO# 1890 Waytona Aircraft Services CPS DYTP262K Daytona Gircraft Services, 3nd	quipment Exchanged for Optional -Exchanged for Optional quipment Equipment Exchanged for Optional -Exchanged for Optional Equipment Exchanged for Optional -Exchanged for Optional Equipment Exchanged for Optional -Exchanged for Optional Equipment Exchanged for Optional Exchanged for Optional Exchanged for Optional
	an de color de la color ante de color de la color ante de color de la color ante de la color de la color de la color ante de la color de la color de la color ante de la color de la color de la color ante de la color de la color ante de la color de la co	Removal of Required Addition of Optional E Removal of Optional Addition of Optional Addition of Required	I Equipment -Exchanged for Optional -Exchanged for Optional Equipment

3/26/2010 4701 NE 40th TERACE GAINESVILLE FL 32609

University Air Center

N: 8442H MAKE PIPER MODLE: PA-32-301 S/N AIRCRAFT TT: 1040.5 TACH AIRCRAFT TC:

Notes

 Troubleshot stating problem found starter relay no getting energized removed ignition switch found start wire to switch not connected reinstalled start wire and secured all other connections on switch functional test god

I certify the maintenance and/or alteration described above was accomplished in accordance with the requirements of 14 CFR 43, and with respect to the work performed is airworthy and approved for return to service.

R Scott Lambert AP 3300566

DAYTONA AIRCRAFT SERVICES

DATE: 6/2/2010

S

1-19-2010

Notes

TACH: 1094.8

Installed new nose tire and tube, repacked bearings. Replaced Lt tire with new, repacked bearings. Re-sealed Lt brake caliper, installed new linings and bleed system. All work was performed in accordance with current regulations of the FAA and is approved for return to service Details on file at this Repair Station under WO# 2310

Daytona Aircraft Services CRS DYTR262K

Daytona Gircraft Services, Inc.

ook

