


N755TX

2007 Glasair GS-2

Airworthiness Directives

MSN: 7228



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

AIRWORTHINESS DIRECTIVE COMPLIANCE RECORD (REPETITIVE)

AD No	Date	Method of compliance	Signature *	AME/AMO Number
2008-08-14	22/04/08	7.9 Plug torque checked by aircraft engine fitter	7 name USA Lago	AMP 20360819
	Total time 35 Hrs			
2008-08-14	4/2/09	Plug torque checked by engine fitter	[Signature]	20360819 INSPECTOR No. 9
	Total time 40.5 Hrs			
2008-08-14	26-04-2010	Plug torque checked by engine fitter	[Signature]	20360819 INSPECTOR No. 9
	Total time 50.8 Hrs			
/	10/10/2016	NIL DUE THIS INSPECTION	[Signature]	A.M.O. 1029
	Total time 142.62 Hrs			
/	17/10/2017	NIL DUE THIS INSPECTION	[Signature]	A.M.O. 1029
	Total time 155.92 Hrs			
2008-08-14	23/10/2018	MAGNETO 500HR/4YR INSP	[Signature]	A.M.O. 1029
	Total time 174.9 Hrs			
2008-08-14	23/10/2018	PLUG TORQUE CHECK	[Signature]	A.M.O. 1029
	Total time 174.9 Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			

PLACE (PT) LTD
AMO No 9
INSPECTOR No. 9

AIRCRAFT
No. 2
A.M.O.
1029
AIRCRAFT
No. 2
A.M.O.
1029
AIRCRAFT
No. 2
A.M.O.
1029

* Note: A signature in this column will be taken as certification that the maintenance specified has been carried out and all requirements as laid down in the Civil Aviation Regulations 1997, as amended have been met in every respect.

SERVICE BULLETINS/LETTERS/INSTRUCTIONS (ONE TIME ACTION)

NUMBER	Date	Method of compliance	Signature *	AME/AMO Number
54	4/2/09	Measurement of seat belts		PLACO (PTY) LTD AMO No 9 INSPECTOR No. 9
	Total time 40.5 Hrs	5 3/8 LH + RH		
63	4/2/09	Inspection of cable grips		PLACO (PTY) LTD AMO No 9 INSPECTOR No. 9
	Total time 40.5 Hrs			
66	4/2/09	406 ELT removal Installation		PLACO (PTY) LTD AMO No 9 INSPECTOR No. 9
	Total time 40.5 Hrs			
67	24-04-2010	Elevator of wt. Re-attached as per Bulletin		PLACO (PTY) LTD AMO No 9 INSPECTOR No. 9
	Total time 50.8 Hrs			
70.	3.9.2013	VERTICAL PIN SPAR REINFORCE WENT		AERO CLUB OF S.A. Approved Person 056 No. 2 A.M.O. 1029
	Total time 86.95 Hrs			
/	10/10/2016	NIL DUE THIS INSPECTION		No. 2 A.M.O. 1029
	Total time 142.62 Hrs			
/	23/10/2018	NIL DUE THIS INSPECTION		No. 2 A.M.O. 1029
	Total time 174.9 Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			

* Note: A signature in this column will be taken as certification that the maintenance specified has been carried out and all requirements as laid down in the Civil Aviation Regulations 1997, as amended have been met in every respect.

SERVICE BULLETINS/LETTERS/INSTRUCTIONS (REPETITIVE)

NUMBER	Date	Method of compliance	Signature *	AME/AMO Number
58	4/2/09	Paint at gap fit found installed		PLACO (PTY) LTD AMO No. 9 INSPECTOR No. 9
	Total time 40.5 Hrs			
64	4/2/09	Inspected seat and weld electric		AME/AMO Number PLACO (PTY) LTD AMO No. 9 INSPECTOR No. 9
	Total time 40.5 Hrs			
65	4/2/09	Inspected fuel baffle		AME/AMO Number PLACO (PTY) LTD AMO No. 9 INSPECTOR No. 9
	Total time 40.5 Hrs			
65	24-01-2010	Baffles inspected & found satisfactory		AME/AMO Number PLACO (PTY) LTD AMO No. 9 INSPECTOR No. 9
	Total time 50.87 Hrs			
/	10/10/2016	NIL DUE THIS INSPECTION		AME/AMO Number A.M.O. 1029
	Total time 162.62 Hrs			
/	23/10/2018	NIL DUE THIS INSPECTION		AME/AMO Number A.M.O. 1029
	Total time 176.9 Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			
	Date	Method of compliance	Signature *	AME/AMO Number
	Total time			
	Hrs			

* Note: A signature in this column will be taken as certification that the maintenance specified has been carried out and all requirements as laid down in the Civil Aviation Regulations 1997, as amended have been met in every respect.