N53RD 1981 Cessna Citation I

Aircraft Database Query

MSN: 500-0415



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

Back to Summary Next Page Prior Page

		umber:	53DD
		ıımner•	53KI
_ T _	_ T Z		

N Number: 53RD					
Last Action Date	2023-04-15				
Airworthiness Date	2003-09-26	Expiration Date	2030-04-30		
Manufacturer_Name	CESSNA	Model Name	500		
Registrant Name	TYLER PETROLEUM INC	Street	PO BOX 6543		
Registrant City	TYLER	Registrant State	TX		
Registrant Zip Code	757116543	Country	UNITED STATES		
Region	Southwestern	Registrant Type	Corporation		
Fract Owner		Certificate Issue Date	2023-04-15		
Status	N-Number Assigned and Registered				
Serial Number	500-0415	Aircraft Type	Fixed wing multi engine		
Mode S Code	51527617	Year Mfr	1981		
Aircraft Category	Land	Builder Certification	Type Certificated		
Number Engines	2	Number Seats	8		
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	301		
Airworthiness Classification	Standard	Approved Operation Codes	Transport		
Engine Manufacturer	P&W CANADA				
Engine Model Name	JT15D-1A	Engine Type	Turbine air generator		
Engine Horsepower/Thrust	2200	Fuel Consumed	22.00		
	Histo	ory 1			
Last Action Date	2023-03-10				
Registrant Name	SKYBUS INC	Street	3594 NE		

			167TH ST
Registrant City	FORT LAUDERDALE	Registrant State	FL
Registrant Zip Code	33160	Country	UNITED STATES
Region	Southern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2020-08-12
Status	N-Number Assigned	d and Registered	
		•	
T (A (* D (Histor	y 2	
Last Action Date	2020-08-12	G	2504 NE
Registrant Name	SKYBUS INC	Street	3594 NE 167TH ST
Registrant City	FORT LAUDERDALE	Registrant State	FL
Registrant Zip Code	33160	Country	UNITED STATES
Region	Southern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2020-08-12
Status	N-Number Assigned	d and Registered	
	Histor	у 3	
Last Action Date	2020-01-07		
Registrant Name	SKYS THE LIMIT AVIATION LLC	Street	70 KARAGO AVE
Registrant City	BOARDMAN	Registrant State	ОН
Registrant Zip Code	445125949	Country	UNITED STATES
Region	Great Lakes	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2017-01-24
Status	N-Number Assigned	d and Registered	
	Histor	v 4	
Last Action Date	2017-01-24	<i>y</i> -	
Registrant Name	SKYS THE LIMIT AVIATION LLC	Street	70 KARAGO AVE
Registrant City	BOARDMAN	Registrant State	ОН
Registrant Zip Code	445125949	Country	UNITED STATES
Region	Great Lakes	Registrant Type	LLC

Fract Owner		Certificate Issue Date	2017-01-24
Status	Second Notice for Registration Renewal		
	History	v 5	
Last Action Date	2015-01-20	y	
Registrant Name	KTT INC	Street	308 SANDHILL RD
Registrant City	LA VERGNE	Registrant State	TN
Registrant Zip Code	370862419	Country	UNITED STATES
Region	Central	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2015-01-20
Status	N-Number Assigned	and Registered	
	History	y 6	
Last Action Date	2012-07-18		
Registrant Name	ZEUS LLC	Street	942 WINDEMERE DR NW
Registrant City	SALEM	Registrant State	OR
Registrant Zip Code	973042722	Country	UNITED STATES
Region	Northwest Mountain	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2012-07-18
Status	N-Number Assigned	and Registered	
	History	v 7	
Last Action Date	2012-03-20	, .	
Registrant Name	NEW BRAUNFELS AIRCRAFT SALES INC	Street	402 E RAMSEY RD
Registrant City	SAN ANTONIO	Registrant State	TX
Registrant Zip Code	782164637	Country	UNITED STATES
Region	Southwestern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2012-03-20
Status	N-Number Assigned and Registered		

Last Action Date	2011-04-16			
Registrant Name	CADENCE BANK NA	Street	6075 POPLAR AVE STE 120	
Registrant City	MEMPHIS	Registrant State	TN	
Registrant Zip Code	381190109	Country	UNITED STATES	
Region	Central	Registrant Type	Corporation	
Fract Owner		Certificate Issue Date	2011-04-16	
Status	N-Number Assigned	and Registered		
	History	y 9		
Last Action Date	2011-01-12			
Registrant Name	ENLOW & ASSOCIATES INC	Street	612 PETALUMA AVE	
Registrant City	SEBASTOPOL	Registrant State	CA	
Registrant Zip Code	95472-4217	Country	UNITED STATES	
Region	Western-Pacific	Registrant Type	Corporation	
Fract Owner		Certificate Issue Date	2008-04-01	
Status	N-Number Assigned	and Registered		
	History	10		
Last Action Date	2008-04-01	10		
Registrant Name	ENLOW &	Street	612	
registrant rame	ASSOCIATES INC	Sirect	PETALUMA AVE	
Registrant City	SEBASTOPOL	Registrant State	CA	
Registrant Zip Code	95472-4217	Country	UNITED STATES	
Region	Western-Pacific	Registrant Type	Corporation	
Fract Owner		Certificate Issue Date	2008-04-01	
Status	First Notice for Re- F	Registration/Renewal		
History 11				
Last Action Date	2006-06-20			
Registrant Name	STG REALTY VENTURES INC	Street	1260 N DUTTON AVE STE 270	
Registrant City	SANTA ROSA	Registrant State	CA	
Registrant Zip Code	95401-4673	Country	UNITED STATES	

Region	Western-Pacific	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2006-06-20
Status	N-Number Assigned	and Registered	
	History	12	
Last Action Date	2006-04-27	_	
Registrant Name	SALE REPORTED	Street	1260 N DUTTON AVE STE 270
Registrant City	SANTA ROSA	Registrant State	CA
Registrant Zip Code	95401-4673	Country	UNITED STATES
Region	Western-Pacific	Registrant Type	Individual
Fract Owner		Certificate Issue Date	
Status	Sale reported		
	History	13	
Last Action Date	2005-03-09		
Registrant Name	AFRICANO AIRCRAFT MANAGEMENT LLC	Street	3821 N BIGELOW ST
Registrant City	PEORIA	Registrant State	IL
Registrant Zip Code	61614-7320	Country	UNITED STATES
Region	Great Lakes	Registrant Type	Co-Owned
Fract Owner		Certificate Issue Date	2005-03-09
Status	N-Number Assigned	and Registered	
	History	14	
Last Action Date	2004-01-28		
Registrant Name	AFRICANO AIRCRAFT MANAGEMENT LLC	Street	3821 N BIGELOW ST
Registrant City	PEORIA	Registrant State	IL
Registrant Zip Code	61614-7320	Country	UNITED STATES
Region	Great Lakes	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2003-06-06

N-Number assigned

Status

Experation Notice Date

Ot	ther Aircraft 1 With t	he Same N Number	
Last Action Date	2002-06-04		
Airworthiness Date		Expiration Date	
Manufacturer_Name	BEECH	Model Name	58
Registrant Name	FIRESIDE HOMES INC	Street	59555 COUNTY ROAD 17
Registrant City	GOSHEN	Registrant State	IN
Registrant Zip Code	46528-8408	Country	UNITED STATES
Region	Great Lakes	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2002-06-04
Status	N-Number assigned		
Serial Number	TH-483	Aircraft Type	Fixed wing multi engine
Mode S Code	51527617	Year Mfr	1974
Aircraft Category	Land	Builder Certification	Type Certificated
Number Engines	2	Number Seats	6
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	165
Airworthiness Classification	Standard	Approved Operation Codes	Normal
Engine Manufacturer Engine Model Name Engine Horsonower/Thrust	CONT MOTOR IO 520 SERIES 0	Engine Type Fuel Consumed	Reciprocating 0.00
Engine Horsepower/Thrust	U	ruei Consumed	0.00
	Reserved Ai	ircraft 1	
Registrant	AFRICANO AIRCRAFT MANAGEMENT LLC	Street 1	3821 N BIGELOW ST
Street 2		City	PEORIA
State	IL	Zip Code	61614-7320
Reserved Date	2003-07-17	Reservation Type	N-Number change is in process
T		CI ININI I	COLLD

Changed N Number

50KR

 Reserved	Aircraft	2
 Neserveu	AllCraft	<i>Z</i>

Registrant	OSF AVIATION LLC	Street 1	3821 N BIGELOW ST
Street 2		City	PEORIA
State	IL	Zip Code	61614-7320
Reserved Date	2003-01-07	Reservation Type	Fee paid
Experation Notice Date	2003-11-07	Changed N Number	

----- FAA Accident/Incident 1 -----

Occurrence Date	1996-12-18	Aircraft Make	BEECH
Aircraft Model	58	Damage	MINOR

Document Last Modified 2012-08-08

Narrative MISSED FIRST APPROACH. MADE ANOTHER OPPOSITE

DIRECTION.DISTRACTED BY CHANGE, RAISED GEAR INSTEAD

OF FLAPS ON ROLL.

----- NTBS Accident 1 -----

Event Date	1998-07-17	Aircraft Make	Beech
Aircraft Model	58	Aircraft Serial Number	

Damage NONE

Probably Cause

Prelimenary Narrative

On July 17, 1998, about 1700 eastern daylight time, N53RD, a Beech 58, operated by Allair Air Services Corporation, experienced an overheated electrical component while descending over Toms River, New Jersey. The certificated airline transport pilot, the sole occupant, initiated an uneventful precautionary landing at the Miller Airpark in Toms River. No damage or injuries were reported. Visual meteorological conditions prevailed and no flight plan had been filed. The personal flight was conducted under 14 CFR 91. The flight originated from White Plains, New York, and was destined for Belmar, New Jersey. In a telephone interview with the incident pilot, he stated that he was airborne for about 20 minutes when he smelled "something burning." He stated that it smelled like the burning was from an electrical source. He was descending through 3,000 feet above mean sea level toward the destination airport in Belmar at the time he noticed the smell. He then elected to land at the Miller Airport, where he asked a mechanic to inspect the airplane. The Safety Board interviewed the mechanic who was asked by the pilot to inspect the airplane. According to the mechanic (record of interview attached), a Bob Fields door seal inflation pump system was installed in the airplane. The mechanic stated that he inspected the door seal pump and found that the pump's plastic housing was partially melted. He also noticed that the wiring that connected the two door seal pump resistors was also partially melted. He stated that the resistors were "riveted the instrument panel shelf" which extended into the nose area.

 SDR	1	
 171713		

Date Of Report	1998-08-28	Operator Control Number	98ZZZX3048
Date Of Occurrence	1998-07-17	Aircraft Registration	53RD
Aircraft Manufacturer	BEECH	Aircraft Group Code	58
Aircraft Manufacturer Model	58	Aircraft Make Model Sequence	1152740
Air Carrier Name	Unknown	Air Carrier Operation Code	
Operation Type	G	Stage Of Operation	CRUISE
Severity Factor		Air Transport Association Code	Passenger/Crew Doors
Precautionary Procedures	DEACTIVATE SYST/CIRCUITS	Nature Of Condition	SMOKE, WARNING INDICATION
Segment	AIRFRAME	Descriptive Name Of Part	PUMP
Defective Location On Aircraft	DOOR SEAL	Failed Part Condition	FAILED
Part Total Time		Part Total Time Since Overhaul	
Component Manufacturer		Component Manufacturer Model	[
Component Manufacturer Number	r 28445	Manufacturer Part Number	300024
Ata Code			

Remarks PILOT NOTICED BURNING SMELL IN COCKPIT. TURNED OFF

> AVIONICS AND SMELL CONTINUED. PILOT NOTICED DOOR SEAL LIGHT WAS ILLUMINATED. SHUT OFF DOOR SEAL SYSTEM AND SMELL WENT AWAY. INSPECTION REVEALED PUMP BADLY DISTORTED AND MELTED. DROPPING RESISTOR

WIRING MELTED NEAR RESISTOR.

Custom Reports

Copyright 2001 - 2024 AviationDB.com Corp. All Rights Reserved

Legal Contact Us