N100BG 1975 Cessna T210L

Prop Logbook SNEW 2020 - 2025

MSN: 21060633



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HARTZELL PH3JCYF

PROPELLER S/N _ FP 9560 B

LOGBOOK #_____

Date	Proj TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthi Service Documents, Overhaul, Major or Minor Repa				
			West Ho 18000 (Houst	N100BG TACH: 3216.2				
J certify determi Details Calkins FAA Co	WORK PERFORMED: PROPELLER • C/W STC SA02107AT-D - INSTALLED NEW PROPELLER (HARTZELL PHC- J3YF-IRF/F7691) ASS'Y SER NO. FP9560B • INSTALLED NEW SPINNER BULKHEAD AND SPINNER I certify that the work performed was carried out in accordance with 14 CFR 43 and was determined to be in an airworthy condition. Details on file at Calkins Aero Repair Station under WO# 29279 Calkins Aero Service Inc. FAA Certified Repair Station No. GK2R849K signed							
51	27	120	20	INSpected fach IAW 14CER -43 & WAS	_			
TO	sh	18	hr	determined to be in condition for				
SA	18	hr		return to service.				
- 2/ 4				Deepe Sould P&P I-A #3701197				
1.000	1000 Carlos Carl							

06/03/21 N100BG Cessna T210L S/N 21060633 Hartzell Model PH3JCYF S/N FP9560B Tach 86.7 TTP 86.7

Comply with Annual inspection per scope and details of FAR 43 Appendix D. Inspect spinner/spinner bulkhead for cracks. Inspect blades for condition. Engine ground run with operation of prop cycle normal. AD's checked thru this date and complied with as noted in AD Summary Listing provided. I certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in an Airworthy condition on this date.

AIR PROFESSIONALS

PEARLAND REGIONAL AIRPORT (281) 992-3484 RANDY WAHLBERG A&P 3563642IA

Rondy Wahl

Date	Pro TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
6/13	171.	<i>></i>	39.07	19. Inspected propelloy to ma to be inspected propelloy to ma
				te savice. Dip PDRegots
				962892556
 	Contine Hartzell Perform L15N ar Accordir	ntal IO-5 PH3JCYI ned 100 I nd the sc ng to FAJ	550-P S/I F S/N: FP hour/ an tope and 3/43,156	OL N100BG S/N: 21060633 Tach: 194.9 TTAF:3411.1 owner: Pat A Rogers N: 1038377 TSO: 194.9 P9560B TSN: 194.9 Inual inspection and servicing according to Hartzell Propellor Owners Manual detail of FAR 43 Appendix D. I certify that this propeller has been inspected atta(c)(1)(2) for an annual inspection and was determined to be in airworthy S IA405867971

HARTZELL PROPELLER INC.

One Propeller Place Piqua, Ohio 45356-2634 U.S.A. Telephone: 937.778.4200 Telex: 4332032 Fax: 937.778.4391

.

.