N2130L

1976 Beech 58TC Baron

LH Prop Logbook

Aircraft S/N: TK-25



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

N2130L

HARTZELL

LEFT PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-2UF/FC7663DR

PROPELLER S/N ED 5311B

LOGBOOK #_/

Date	Proj TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
240	0			143 tall new de-Kers dharnoss
	,			Portiont details of the repair are an ille
	-			WORK ORDER NO 15472
				DATED 6-24-00
				SIGNED COLLEGE Service, Inc.
				FAA Hepair Station No. * DIR GAZL
	In	2130L stalled r BTC S/N	new proj LTK25,	Date: 7/8/2008 Tach: 828.2 peller model: PHC J3YF 2UF, S/N ED5311B on N2130L Beech OPS and leak check good, approved for service.
	<u> </u>			
	<u> </u>	<u> </u>		

	Hobbs: 872 SM0 C/W Annual inspection. I certify that this propell	Hartzell PHC-J3YF-2UF/FO S/N: ED5311B OH: 044 Hobbs To Dressed leading edges and p er has been inspected IAW a I to be in an airworthy condit	otal: 044 painted blade faces. n annual inspection,	
05 H	/W Annual inspection. Dressed certify that this propeller has been determined to be in an airwo	S/N: ED MOH: 140 leading edges and painted bl en inspected IAW an annual	Total: 140ade faces.	

SEE OTHER SIDE

Maintenance Release

PartHartzell	
Model PHC-J3YF-2UF	•
The component identified above to the component identified above to the current Federal air regulations are air-worthy for return to service. Per of the repair are on file at this agent order No. ———————————————————————————————————	nd was found rtinent details
Date6_2408	
Signed Authorized Individua	1

PRECISION PROPELLER SERVICE, INC.

Weld County Municipal Airport 631 Buss Ave., Greeley, CO 80631

(970) 352-8578

FAA APPROVED REPAIR STATION NO. UB3R887L

DESCRIPTION OF WORK ACCOMPLISHED

Make <u>Hartzell</u>	Model PHC-J3YF-2UF	
S/N_ED5311B_Blades 1	2 3 4	
OverhauledBlades Rep	oBlade RepairReseal	
RepitchOther	Service Manual	_
Service Letters		
Service Bulletins		_
AD's	Boot P/NSMR1601-7	-
Remarks <u>install new de</u>	e-icers.	-
-		_
Pitch Settings: Low	HighReverse	-
'so π	Featherlatch	_

Date	Prop TSN	rso TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
			06- Ho C/V I ce	At Propeller 03-2011 N2130L Hartzell PHC-J3YF-2UF/FC7663DI S/N: ED5311B bbbs: 1081.7 SMOH: 254 Total: 254 W Annual inspection. Dressed leading edges and painted blade faces. Partify that this propeller has been inspected IAW an annual inspection, and has an determined to be in an airworthy condition. Joseph M Klein Jr 1987406IA	
				•	
	`				
	(e)	UMS,		Clearwater Aircraft Maintenance and Services, Inc. 14421 Airport Parkway • Clearwater, FL 33762 727-507-8881 • Fax 727-507-8887	
	Date: 03		Acc chaf end. requ Che		
	Date: 03 Work O Hobbs:	3/28/2012 rd: 6979 1168.6	Acc chaf end. requ Che beer this	omplished an Annual inspection IAW Maintenance Manual on L/H prop. Installed antife and tie wrapped governor wires as needed. Adjusted and resafetied governor cable rod. Re positioned and resealed de-ice wires as required. Dressed and painted propeller as nired. cked AD's thru 2012-05 T-Data. See AD list in log folder. I certify this propeller has an inspected IAW an annual inspection and was found to be in an airworthy condition on date. Matt Malouf AP/IA 2841230 End of entry	
	Date: 03 Work O Hobbs:	3/28/2012 rd: 6979 1168.6 340.9 P1	Acc chafend. required this	omplished an Annual inspection IAW Maintenance Manual on L/H prop. Installed antife and tie wrapped governor wires as needed. Adjusted and resafetied governor cable rod. Re positioned and resealed de-ice wires as required. Dressed and painted propeller as nired. cked AD's thru 2012-05 T-Data. See AD list in log folder. I certify this propeller has an inspected IAW an annual inspection and was found to be in an airworthy condition on date. Matt Malouf AP/IA 2841230 End of entry PrimePlanes Drive North Suite 102	
	Date: 03 Work O Hobbs: SPOH:	PI 24 Reinstalled	Acc chafend. requested this serving the se	omplished an Annual inspection IAW Maintenance Manual on L/H prop. Installed antife and tie wrapped governor wires as needed. Adjusted and resafetied governor cable rod. Re positioned and resealed de-ice wires as required. Dressed and painted propeller as nired. cked AD's thru 2012-05 T-Data. See AD list in log folder. I certify this propeller has an inspected IAW an annual inspection and was found to be in an airworthy condition on date. Matt Malouf AP/IA 2841230 End of entry PrimePlanes Drive North Suite 102 1 34104 ph. 239-659-4005	

Date	Proj TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives Service Documents, Overhaul, Major or Minor Repair, and Inspecti	ons.
			Date:	Aircraft Propeller Works, Inc.	
			Serial No APW#: This Hart repainted	PHC-J3YF-2UF / FC7663DRB ED5311B APW5141 zell Propeller resealed , leading edge cleaned up, blades and static balanced in accordance with Hartzell manuals 202A, 133C. Approved for return to service. Continue time.	
				Michaud ed Signature FAA Repair Station # T4ZR741Y	
	- 6	AMS	1	Clearwater Aircraft Maintenance and Services, Inc. 4421 Airport Parkway • Clearwater, FL 33762 727-507-8881 • Fax 727-507-888	37
	Date: (Work (Hobbs	N2130L 06/14/201 Ord: 7517 : 1293.4 : 465.7	grop as re Chec pelle	omplished an Annual inspection IAW Maintenance Manual on L/H prop. Removed and sent out for re-seal. Installed propeller after repair. Dressed and painted	ller
		REG.	240 Avia	lanes Aircraft Services Inc. tion Drive North Suite 102 prida 34104 ph. 239-659-4005 TYPE PHC-J3YF-2UF SERIAL ED5311B HOBBS 1298.8	
		Reinsta 61-00-6	ov. Penorme	uled Propeller, IAW Hartzell owners manual, and Beechcraft Baron 58TC MM section do ops check, no discrepancies noted at this time. —END— Date 5/8/2014	

Date	Prop TSN	eller TSO	A/C Hrs	Description Service Do	on of all operations pocuments, Overhaul	pertaining to Air Major or Mino	worthiness Direct r Repair, and Ins	ctives, spections.
			 PROP MODEL (L) PROP SIN (L): REG. NO: 2130; WORK ORDER: 6172-07-2014 		Premier Aircraft Service,. In: 5540 NW 23rd Avenue Henger 14 Fort Lauderdale, FL 33309 Phone: (954) 334-2393	e.	DATE: 7/25/2014 A/C TSN: 4640 PROP TT (J): 1299 HOBBS: 1300	
			Left Prop En (6) C/W ANNU/ CHAPTER 5 IN	L INSPECTION ON THIS I F	FT PROPELLER IAW FAR 43 A A GUIDE, ADS CHECKED THRO	PPENDIX D USING BEE PUGH CURRENT ON AT	ECH 58TC M/M IP.	· · · · · · · · · · · · · · · · · · ·
			THE FEDERAL	ELLER, AND / OR APPLIAN AVIATION ADMINISTRATION AW CURRENT APPLICABLE	E TO THE WORK PERFORME CE WAS REPAIRED AND INSP N AND IS APPROVED FOR RET AIRCRAFT, ENGINE, OR APPI	ECTED IAW CURRENT URN TO SERVICE, ALL IANCE MAINTENANCE	REGULATIONS OF	
			DATE: 7/25/201		4/1/1/W/1/ ULAC Acioso, IA: 3708718		fork Order: 6172-07-2014 EBis 3 (datcomedia.com)	
<u></u>			<u> </u>			······································		()

		MUULILION AUUR®
		GULFPORT-BILOXI 08/27/15 N2130L Hartzell PHC-J3YF-2UF S/N ED5311B Hobbs: 1410.1 Prop SMOH: 1410.1 LH Prop
		 Performed 100 hour inspection. Inspected bulkhead, blades, boots and wiring. Serviced with nitrogen to proper pressure.
		I certify that this propeller has been inspected in accordance with an ANNUAL inspection and is an airworthy condition. Blaine Wills A&P 436983651 IA
	Precisio LOG IDA N2130L	n Avionics Specialists 207 Barry Whatley Way Griffin, GA 30224 2113 12-September-2016 WO# 10823 HOBBS 1440.5 S/N TK-25 BEECH 58TC TSMOH 1440.5
		Pg 1/1 PROPELLER USING CHECKLIST PREPARED IN ACCORDANCE WITH FAR 43 APPENDIX D.I CERTIFY PELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMANED TO IRWORTHY CONDITION AS OF THIS DATE.
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00		Scott Collin
	A&P 274	7448 IA JEFFERY S. COLLINS

Date	Propeller TSN TS		Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
\dashv	1		Hartzell(Left) Model# PHC-J3YF-2UF SER# ED5311B 02/05/2018 SPOH 802
\dashv			This date performed an annual inspection
\rightarrow		-	found to be in a late. Inspected and determined that this prop was
			Tail Soul TA3031511
\dashv			HANTER! (CEST) woodel PHCJ3YFZ-W SEVH ED STAIN
\dashv			10/20/20 South 1683.3
			ele punial Japaiter elketto Beach 5870 mlm
			a beckeel Alp TRes FAd Resura
			greately This prepeller is Ben Ispected Ilolw
			An prival gapetter seel it to sweethy laditor Show Their Atp 17 ls
			Show They AND 14 Lo
-			
			396290
)	396290
1/2/23		229	Annul inspection you Found accessity 7- Sign I 43071998
1/2/23		729	59G 19U
1/2/23		729	
2/2/23		229	
u/2/ ₂₃	FASTT	FXAS FLY	Annual inspection You Found Accounty 7- Sign IA 3071988
2/2/23	EASTT	EXAS FLY	Annul in spectron You Found Accessity 7. 3/1/1988 ING SERVICE INC. 903 571-0116 2130L 1/16/2025 1779 Hobbs.
	EAST T LEFT I CERTIFY	EXAS FLYI PROP N2 THAT I HA	Annul in spectron You Found Riccionty 7. Sin I 4 3071998 ING SERVICE INC. 903 571-0116 2130L 1/16/2025 1779 Hobbs. AVE INSPECTED THIS PROPELLER ETURER'S PERIODIC INSPECTION
u/2/ ₂₃	EAST T LEFT I CERTIFY	EXAS FLYI PROP N2 THAT I HA	Annul in spectron Yw Fund Airworth, 7- Sign I 4 307/998 ING SERVICE INC. 903 571-0116 2130L 1/16/2025 1779 Hobbs. WE INSPECTED THIS PROPELLER
	EAST T LEFT I CERTIFY	EXAS FLYI PROP N2 THAT I HA MANUFAC IDATIONS	Annual inspection of Fermi Accessity 7. Sign TA 3071988 ING SERVICE INC. 903 571-0116 2130L 1/16/2025 1779 Hobbs. AVE INSPECTED THIS PROPELLER ETURER'S PERIODIC INSPECTION AND THAT IT IS IN AN AIRWORTHY CONDITION. ATRICIA BURÇH
	EAST T LEFT I CERTIFY	EXAS FLYI PROP N2 THAT I HA MANUFAC IDATIONS	ING SERVICE INC. 903 571-0116 2130L 1/16/2025 1779 Hobbs. VE INSPECTED THIS PROPELLER ETURER'S PERIODIC INSPECTION AND THAT IT IS IN AN AIRWORTHY CONDITION.
	EAST T LEFT I CERTIFY	EXAS FLYI PROP N2 THAT I HA MANUFAC IDATIONS	Annual inspection of Fermi Accessity 7. Sign TA 3071988 ING SERVICE INC. 903 571-0116 2130L 1/16/2025 1779 Hobbs. AVE INSPECTED THIS PROPELLER ETURER'S PERIODIC INSPECTION AND THAT IT IS IN AN AIRWORTHY CONDITION. ATRICIA BURÇH