Airframe: Hobbs 684/hrs. 6.2.20

4470/hrs. Total time since new. All records since new! Excellent locations NY, OK, TX, since new. Beechcraft East maintained till 1/85!! Useful load: 1112.10 – ELT due: 11/21 – Annual due: 12/20 IFR due: NOW

Engine Specs': Continental IO-470-K Serial # 86759-6-K - 1500/hr. T.B.O. – 225/H.P. 1450/hrs. Since Rebuilt by Western Skyways (6-86) Zero time equivalent! 550/hrs. S.T.O.H. (9/02)

<u>Prop:</u> 2 Bladed McCauley Prop – Model # 2A36C23-CD – Serial #631836 1450/hrs. Since overhaul (6-86)

# **Avionics:**

Avionics Master Switch King KMA-24 Audio Panel (2) King KY-197 Comm King KNS-80 R-nav King KN-53 nav King KR-87 ADF King KT-76 A transponder Britton wing leveler (works)

### **Additional Equipment:**

GEM Engine Monitor
J.P.I. SF-450 Fuel Flow
G.A.M.I Injectors
Horizon digital Tach
Beryl D' Shannon thick Windshield
Beryl D' Shannon thick Windows
Beryl D' Shannon Air/Oil separator
Eagle Fuel Sumps
Brackett Air Filter
Cleveland wheels and brakes
Dual Yoke

# Interior:

This is an example of a Hanger kept aircraft with mostly all original interior. Side panels are in off white and red fabric in really "tidy" condition! The seats are in mostly red multi-colored tweed (has covers)! Carpet is all red in really "tight" condition! Rated 6. +

#### Exterior

Very respectful condition and is mostly original too. Matterhorn white and racing red and Inca black.
Rated 6. +

#### **COMMENTS:**

12/68 – L.H. Leading edge replace with new @ Atlantic Aviation N.J. 03/76 – L.H. Gear failure repaired by Beechcraft East with all new parts.

Aircraft specifications are subject to change at any time. This specification sheet is intended as preliminary information and is subject to verification by the purchaser RidgeAire, Inc. 903-586-1521

