

# N390AA

## 2012 Beech Premier IA

---

# CAMP Due List

**MSN: RB-293**



*Prepared by the worldwide aviation specialists at RidgeAire, Inc.*



DueList Report

PREMIER IA

S/N RB-293 N254BC

OWNER: AIR BC, LLC  
ADDRESS: PO BOX 249  
HEWITT TX 76643

OPERATOR: AIR BC, LLC  
ADDRESS: PO BOX 249  
HEWITT TX 76643

OFFICE:  
FAX:

OFFICE:  
FAX:

ANALYST: WADE HOAGBOON  
EMAIL: WHOAGBOON@CAMPSYSTEMS.COM

1-316-462-2455 (DIRECT)  
+1-631-588-3200 (MAIN)  
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)

PROJECTED: 12 MOS. to 02-DEC-2025

AIRCRAFT SERIAL/REGNO: RB-293/N254BC MODEL: PREMIER IA MANUFACTURER: TEXTRON AVIATION INC.

CERTIFICATION DATE: 27-JUN-2012

LAST ACTUALS:

PROJECTED:

2064.9 A/C HRS as of 19-NOV-2024  
1712 AFL as of 19-NOV-2024  
1637.2 ACH as of 17-JUN-2024

2244.90  
1892  
1817

ENGINE NO. 1 SERIAL/PART: 105499/FJ44-2A MODEL: FJ44-2A MANUFACTURER: WILLIAMS INTERNATIONAL

INSTALLED ON: 27-JUN-2012

LAST ACTUALS:

PROJECTED:

0 ENG. HRS 0 A/C HRS  
0 ENC

2064.9 ENG. HRS as of 19-NOV-2024  
1712 ENC as of 19-NOV-2024

2244.90  
1892

ENGINE NO. 2 SERIAL/PART: 105498/FJ44-2A MODEL: FJ44-2A MANUFACTURER: WILLIAMS INTERNATIONAL

INSTALLED ON: 27-JUN-2012

LAST ACTUALS:

PROJECTED:

0 ENG. HRS 0 A/C HRS  
0 ENC

2064.9 ENG. HRS as of 19-NOV-2024  
1712 ENC as of 19-NOV-2024

2244.90  
1892



# New Requirement/Flagged Items

Operator Review and Action Required

Model: PREMIER IA Serial: RB-293 RegNo: N254BC HRS: 2064.9 AFL: 1712 As Of: 19-Nov-2024 Operator: AIR BC, LLC

Report Date: 02-Dec-2024

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition
				Current	Change To		
SB FJ44-72-098 R01	25-Oct-24	NO. 1 ENGINE - 1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REPLACE, SERVICE BULLETIN	MOS	T:MPI	25-Oct-24		Bulletin ATA:72
		HRS					
		ENC					
NEW REQUIREMENT ADDED ON 28-OCT-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: BULLETINS			
SB FJ44-72-098 R01	25-Oct-24	NO. 2 ENGINE - 1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REPLACE, SERVICE BULLETIN	MOS	T:MPI	25-Oct-24		Bulletin ATA:72
		HRS					
		ENC					
NEW REQUIREMENT ADDED ON 28-OCT-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: BULLETINS			

Name: \_\_\_\_\_ Signature: \_\_\_\_\_ Cert.# \_\_\_\_\_ Date: \_\_\_\_\_

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: PREMIER IA Serial: RB-293 RegNo: N254BC HRS: 2064.9 AFL: 1712 As Of:  
19-Nov-2024 Operator: AIR BC, LLC

Report Date: 02-Dec-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
237017		REPLACE UNDERWATER LOCATOR BEACON BATTERY						Service ATA:23
PN:KD120/90	MOS	84		12-Jan-18	01-Jan-25		30 d	01-Jan-2025
SN:AT101819	HRS			845				
	AFL			866				
Disposition: MANDATORY		REF: GENERIC NO REF						
SPC22		CAPACITY CHECK MAIN BATTERY						Service ATA:24
PN:RG-380E/44	MOS	3		19-Nov-24	19-Feb-25		79 d	19-Feb-2025(4)
SN:41162880	HRS			2064.9				
	AFL			1712				
		REF: GENERIC NO REF						
100E06		INSPECT FRONT AND SIDE WINDSHIELDS						Service ATA:30
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
Disposition: AIRWORTHINESS		REF: AMM 30-40-00						
OPS16		OPERATIONAL TEST TAKE-OFF CONFIGURATION WARNING						Service ATA:27
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20/-20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
Disposition: AIRWORTHINESS		REF: AMM 27-40-00						
OPS31		TEST FLAPS AND SPOILERS TAKEOFF CONFIGURATION WARNING						Service ATA:31
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20/-20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
Disposition: AIRWORTHINESS		REF: AMM 31-50-00						
OPS37		CHECK DCU AURAL WARNING						Service ATA:31
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20/-20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
Disposition: AIRWORTHINESS		REF: AMM 31-40-02						
OPS38		OPERATIONAL TEST REVERSION SWITCHES						Service ATA:34
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20/-20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
Disposition: AIRWORTHINESS		REF: AMM 34-00-01						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: PREMIER IA Serial: RB-293 RegNo: N254BC HRS: 2064.9 AFL: 1712 As Of:  
19-Nov-2024 Operator: AIR BC, LLC

Report Date: 02-Dec-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
SPC17		CHANGE FORWARD ENVIRONMENTAL SYSTEM EVAPORATOR FILTER AND CHECK DRAIN						Service ATA:21
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
REF: GENERIC NO REF								
SPC18		CHANGE AFT ENVIRONMENTAL SYSTEM EVAPORATOR FILTER						Service ATA:21
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
REF: GENERIC NO REF								
SPC19		DRAIN MOISTURE FROM PNEUMATIC DRAIN LINE						Service ATA:36
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
REF: GENERIC NO REF								
SPC20		CHECK LEFT WING LEADING EDGE DRAIN HOLES						Service ATA:57
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
REF: GENERIC NO REF								
SPC20		CHECK RIGHT WING LEADING EDGE DRAIN HOLES						Service ATA:57
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
REF: GENERIC NO REF								
SPC24		200 HOUR LUBRICATION SERVICING						Package ATA:12
	MOS			30-Dec-22				24-Feb-2025
	HRS	200 (+20)		1906.5	2106.5	2126.5	41.6 (+20)	
	AFL			1603				
REF: AMM 12-20-02								
350101		OXYGEN BOTTLE						Component ATA:35
PN:176419-77	MOS	180	TSN:0	20-Aug-16	01-May-25		150 d	01-May-2025
SN:ALT281-24534/2672	HRS			607.7				
	AFL			627				
	ACH							
Disposition: LIFE LIMIT		REF: AMM 35-10-04						



## Due List Report

Model: PREMIER IA Serial: RB-293 RegNo: N254BC HRS: 2064.9 AFL: 1712 As Of:  
19-Nov-2024 Operator: AIR BC, LLC

Report Date: 02-Dec-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
SPC07		CHECK FIRST AID KIT						Service	ATA:25
	MOS	12 (+30d/-30d)		17-Jun-24	17-Jun-25	17-Jul-25	197 d (+30)	17-Jun-2025	
	HRS			2032					
	AFL			1683					
REF: GENERIC NO REF									
SPC13		ENERGY LEVEL TEST STANDBY BATTERY STANDBY POWER SUPPLY BATTERY						Service	ATA:24
PN:390-384027-0001	MOS	12 (+30d/-30d)		17-Jun-24	17-Jun-25	17-Jul-25	197 d (+30)	17-Jun-2025	
SN:1419	HRS			2032					
	AFL			1683					
REF: CMM 24-32-17									
TBO19		STANDBY BATTERY						Component	ATA:24
PN:100-0206-01	MOS	48	TSO:0	29-Jun-21	29-Jun-25		209 d	29-Jun-2025	
SN:1419	HRS			1533.1					
	AFL			1373					
REF: AMM 24-30-05									
SPC16		DRAIN LEFT PITOT/STATIC SYSTEM						Service	ATA:34
	MOS			10-Jul-23				03-Jul-2025	
	HRS	200 (+20)		1970.3	2170.3	2190.3	105.4 (+20)		
	AFL			1639					
REF: AMM 34-12-00									
SPC16		DRAIN RIGHT PITOT/STATIC SYSTEM						Service	ATA:34
	MOS			10-Jul-23				03-Jul-2025	
	HRS	200 (+20)		1970.3	2170.3	2190.3	105.4 (+20)		
	AFL			1639					
REF: AMM 34-12-00									
237016		TEST UNDERWATER LOCATOR BEACON BATTERY AND UNIT						Service	ATA:23
	MOS	24 (+30d/-30d)		10-Jul-23	10-Jul-25	09-Aug-25	220 d (+30)	10-Jul-2025	
	HRS			1970.3					
	AFL			1639					
REF: AMM 23-70-00									
300A05		INSPECT PITCH TRIM ACTUATOR, ATTACHMENT BOLTS, UPPER BUSHING AND STRUCTURE						Service	ATA:27
	MOS			28-Jun-22				11-Jul-2025	
	HRS	400 (+20/-20)		1774.2	2174.2	2194.2	109.3 (+20)		
	AFL			1522					
REF: AMM 27-40-00									
Disposition: AIRWORTHINESS			REF: AMM 27-40-00						



## Due List Report

Model: PREMIER IA Serial: RB-293 RegNo: N254BC HRS: 2064.9 AFL: 1712 As Of:  
19-Nov-2024 Operator: AIR BC, LLC

Report Date: 02-Dec-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
300C03		INSPECT PITCH TRIM ACTUATOR SYSTEM, PITCHTRIM ACTUATOR, ATTACHMENT BOLTS, UPPER BUSHINGS, AND STRUCTURE						Service ATA:27
	MOS			28-Jun-22				11-Jul-2025
	HRS	400 (+20/-20)		1774.2	2174.2	2194.2	109.3 (+20)	
	AFL			1522				
Disposition: AIRWORTHINESS			REF: AMM 27-40-00					
600C07		INSPECT RIGHT AILERON TRIM TAB SYSTEM						Service ATA:27
	MOS			28-Jun-22				11-Jul-2025
	HRS	400 (+20)		1774.2	2174.2	2194.2	109.3 (+20)	
	AFL			1522				
			REF: AMM 27-00-00, AMM 27-10-00					
400A03		INSPECT NO. 1 ENGINE STARTER/GENERATOR BRUSHES						Service ATA:24
PN:390-389001-0001	MOS			23-Nov-20				02-Aug-2025
SN:427AB	HRS	800 (+20)		1384.8	2184.8	2204.8	119.9 (+20)	
	AFL			1293				
			REF: CMM 24-30-00					
400B03		INSPECT NO. 2 ENGINE STARTER/GENERATOR BRUSHES						Service ATA:24
PN:390-389001-0001	MOS			23-Nov-20				02-Aug-2025
SN:743AB	HRS	800 (+20)		1384.8	2184.8	2204.8	119.9 (+20)	
	AFL			1293				
			REF: CMM 24-30-00					
500C15		INSPECT LEFT WING FLAP ACTUATOR ATTACHMENTS - FLAP ACTUATORS						Service ATA:27
	MOS			11-Jun-24				05-Nov-2025
	HRS	200 (+20/-20)		2032	2232	2252	167.1 (+20)	
	AFL			1683				
Disposition: AIRWORTHINESS			REF: AMM 27-50-00					
600C15		INSPECT RIGHT WING FLAP ACTUATOR ATTACHMENTS - FLAP ACTUATORS						Service ATA:27
	MOS			11-Jun-24				05-Nov-2025
	HRS	200 (+20/-20)		2032	2232	2252	167.1 (+20)	
	AFL			1683				
Disposition: AIRWORTHINESS			REF: AMM 27-50-00					
250001 <sup>U</sup>		FIRST KIT AID INSPECTION REPLACEMENT						Component ATA:25
PN:42 KIT	MOS	DUE	TSN:0	10-Jul-23	17-Nov-25 (M)		350 d	17-Nov-2025
SN:UNKNOWN	HRS		TSN:0	1970.3				
	AFL		TSN:0	1639				
			REF:					

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: PREMIER IA Serial: RB-293 RegNo: N254BC HRS: 2064.9 AFL: 1712 As Of:  
19-Nov-2024 Operator: AIR BC, LLC

Report Date: 02-Dec-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
<b>LIMITS01</b>		<b>HYDROSTATIC TEST ENGINE FIRE BOTTLE EXTINGUISHER</b>							Service ATA:26
PN:30400018-1	MOS	60		19-Nov-20	19-Nov-25		352 d	19-Nov-2025	
SN:52054B1	HRS								
	AFL								
Disposition: MANDATORY		REF: GENERIC NO REF							
<b>LIMITS04</b>		<b>INSPECT EMERGENCY EXIT SIGN (SELF-ILLUMINATING)</b>							Service ATA:33
	MOS	12 (+30d/-30d)		19-Nov-24	19-Nov-25	19-Dec-25	352 d (+30)	19-Nov-2025	
	HRS			2064.9					
	AFL			1712					
Disposition: MANDATORY		REF: AMM 33-50-00							
<b>LIMITS04</b>		<b>INSPECT FORWARD PARTITION (SELF-ILLUMINATING ON AFT SIDE)</b>							Service ATA:33
	MOS	12 (+30d/-30d)		19-Nov-24	19-Nov-25	19-Dec-25	352 d (+30)	19-Nov-2025	
	HRS			2064.9					
	AFL			1712					
Disposition: MANDATORY		REF: AMM 33-50-00							
<b>SPC08</b>		<b>WEIGHT CHECK PORTABLE FIRE EXTINGUISHER</b>							Service ATA:26
	MOS	12 (+30d/-30d)		19-Nov-24	19-Nov-25	19-Dec-25	352 d (+30)	19-Nov-2025	
	HRS			2064.9					
	AFL			1712					
Disposition: MANDATORY		REF: AMM 26-20-00							
<b>SPC15</b>		<b>INSPECT EMERGENCY LOCATOR TRANSMITTER EMERGENCY LOCATOR TRANSMITTER FAR 91.207(D)</b>							Service ATA:25
PN:453-5000-(366)	MOS	12 (+30d/-30d)		19-Nov-24	19-Nov-25	19-Dec-25	352 d (+30)	19-Nov-2025	
SN:210-15033	HRS			2064.9					
	AFL			1712					
		REF: GENERIC NO REF, FAR 91-207(D)							
		WO#: MP-7833							