## N100BG 1975 Cessna T210L

# Engine Logbook SMOH 2019 - 2025

MSN: 21060633



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



### ENGINE LOG BOOK



Publication ELB-01

**JUN 2017** 



Consult the Continental Motors web site at continentalmotors aero for engine related news or announcements. Continental Motors Internet Service contains Consult the Continental Motors web site at commentations for Continued Airworthiness useful information for Continental Motors engine owners, including electronic versions of the most current engine Instructions for Continued Airworthiness useful information for Continental Motors engine model and service documents that may be pertinent to your engine model.

If Internet access is not available, contact our Customer Service Department at: 1-888-826-5465 Toll free in the United States or 1-251-436-8299 International

#### **Engine Returns**

Return engines for core credit with this log book to: Continental Motors, Inc. 2039 Broad Street Mobile, AL 36615 USA

Return engines for overhaul with this log book to Continental Motors, Inc. **Factory Service Center** 8600 County Road 32 Fairhope, Alabama 36532 USA



SPECIFIED IN OPERATOR'S E CERTIFICATE DATA SHEET TIVE FUEL IS PROHIBIT



#### **Continental Motors**

**FAA PRODUCTION CERTIFICATE NO. 508** 

Printed: 12/15/2019

Test Date 12/14/2019

This engine model I0550P3B, serial number 1038377 was rebuilt by Continental Motors Inc, in accordance with approved design data and the applicable requirements of 14 CFR, Part 21 and 43 of the Federal Aviation Regulation. The approved design data for this engine incorporates all changes required by applicable Airworthiness Directives and Continental Motors Service Bulletins.

CONTINENTAL MOTORS,

Form 6012-04 (Rev Sept 2014)

#### **Continental Motors**

#### Engine Component Information Sheet

Printed: 12/15/2019

Serial:1038377

Spec:10550P3B

New/Rebuilt: (REBUILT)

Assembled: 12/10/2019

Shipped: / /

Packed: 12/15/2019

Customer Name: Summit Aviation, Inc.
Shipping Address: 4200 Summit Bridge Road

Component	Serial Number	Component	Serial Numb
CAMSHAFT	444069-5	OIL COOLER	K19-15647-3
CRANKSHAFT	N19JA189	CYLINDER-1	AC19JB019
CRANKCASE	R12EA371	CYLINDER - 2	AC19EA669
CONNROD	AE19JA605	CYLINDER - 3	AC19EA668
CONNROD	AE19JA653	CYLINDER - 4	AC19JA707
CONNROD	AE19JA663	CYLINDER - 5	AC19EA671
CONNROD	AE19JA650	CYLINDER - 6	AC19JB017
CONNROD	AE19JA679	NOZZLE - 1	1234
CONNROD	AE19JA678	NOZZLE - 2	2234
L MAGNETO	D19JA459R	NOZZLE - 3	3239
R MAGNETO	D19JA450R	NOZZLE - 4	4239
FUEL PUMP	B19HA207R	NOZZLE - 5	5239
MANIFOLD VALVE	C19JA139R	NOZZLE - 6	6231
METERING UNIT	A19CA081R		
STARTER	H-W-201910		
ALTERNATOR	019JA021R		

Pack Inspection Stamp

All of the information provided herein is subject to verification by the user. Continental Motors, Inc. makes no representation or warranty concerning the accuracy or completeness of the information and assumes no responsibility with respect thereto.



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly.

IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954)

MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

NOTE: The Parts List was created from the Bill of Materials on Instruction 19051001-1.

Section 1 - Drawings and Documents

S/N: 21060633

\*WIO# 103365-000

ITEM NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
STC - SA02107AT-D	STC Document	_	1	0
19093001	Master Drawing List	w	1	(2)
19051001	Engine Buildup Installation Instructions	L	1	(2i)
19051002	Engine Installation Instructions	Q	1	(Z)
19093010	Instructions For Continued Airworthiness	Α	1	(2)
15371001	Wiring Diagram, Throttle Switch Modification	В	1	(Z)
19093100	Supplement, Airplane Flight Manual, (AFM)	Α	. 1	0
19093110	Supplement, Performance Charts	IR	1	8
•				

Update 1.21.18



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly. IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954) MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

#### Section 2 - Parts List

PART NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
	Aft LH Baffle Assembly	D1	1	72
15350004	Alternate Air Assembly	В	1	
15350005	Fwd RH Baffle Assembly	F1	1	(2)
15350009	RH Shelf Baffle Assembly	F1	1	8
15350010	Fwd Shelf Baffle Assembly	C1	1	(A)
15350013	Induction Air Box Assembly	A	1	@ @
15350014	Oil Cooler Baffle Assembly	IR	1	@
15350015	Aft RH Baffle Assembly	D1	1	(2)
15370001	Alternator Wire Harness	н	1	8
15370002	Alternator Ground Wire	D	1	(D)
15370003-1	Alternator F2 Jumper	D	1	(27)
15352016	Oil Check Door Shirm	С	1	0
15352017	Oil Check Door Angle Bracket	E	1	(2)
15352108	Starter Mount Bracket	E	1	(g)
15352121	Hose Retaining Bracket	· c	1	(2)



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly. IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954) MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

PART NUMBER 15352133-7	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
	Heater Duct Pad	В	1	7
15352185-1	Drain Line	С	1	
15352185-2	Drain Line	С	1	<u> </u>
15352185-3	Drain Line	C	-	(3)
15352185-4	Drain Line	C	1	
15352185-5	Drain Line	D	1	10
15352185-6	Drain Line	C	1	100
15352185-7	Drain Line	IR	1	
15352192	Aft Baffle Mount Bracket		1	10
15352193-1	Fuel Mixture Control Bracket	E	+ +	(3)
15352196	Prop Control Cable Slide	F	+ +	(2)   (2)
15352197	Prop Control Cable Bracket	F	1	(2)
15352198	Cowl Modification Plate	С	2	2
15352200	Induction Box Bracket	IR	1	(T)
15352204	Prop Cable Hook	A	1	(2)



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly. IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954)

MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

PART NUMBER 15352205-1	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
13332205-1	Cable Spacer Blocks	A		
15352205-2	Cable Spacer Blocks		1	(2)
15352206	Fwd LH Cylinder Baffle	A	3	(2)
15352207	Cable Extension	A .	1	(2)
15352209	Orifice Fitting	Α.	1	(3)
15352211		Α	1	2
	Plate, Patch	IR	1	(21)
15352211-1	Plate, Doubler	IR	1	2
19050002	Fwd LH Baffle Assembly	D1	1	
19050011	LH Shelf Baffle Assembly	D1	1	3
19052161	Heat Inlet Closeout, LH (For s/n:21060089 thru 21062954)	В	1	(2)
19052162	Heat Inlet Closeout, RH (For s/n:21060089 thru 21062954)	A	1	(3)
19052163	Exhaust, Closeout	В	2	(2)
19052164	Heat Inlet Closeout, (For s/n:21059200 thru 21060088)	IR	2	NIA
19052170-1	Cowl Flaps	В	1	3
19052170-2	Cowl Flaps	В	1	3



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly.

IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954) MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

PART NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
19052171-1	Cowl Flaps	В	1	(D)
19052171-2	Cowl Flaps	В	1	(27)
19052172	Cowl Flaps, Skin	С	2	3
19052173	Cowl Flaps, Doubler	В	2	(27)
19052176	Heater Duct	В	1	(27)
19052177-2	Breather Tube	С	1	1
19052180	Throttle Control Bracket	E	1	<b>3</b>
19052181	Gear Warning Switch Ramp	D	1	3
19052190	Fuel Strainer Bracket	С	1	<b>3</b>
19052191-1	Gear Warning Switch Bracket	Α	1	(2)
19152197-3	Throttle Clamp	Α	2	3
19152197-4	Throttle Clamp	A	2	(2)
9000001	15PA177-V7, Insulator, Switch	Α	1	3
9000009-2	SCEET-8, Duct, (24")	В	2'	(23)
9000009-11	SCAT-12, Duct, (48")	В	4'	(2)



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly. IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954) MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

PART NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
90000012	V3L-3, Switch Gear Warning	IR	1	2
9000014	BA-326, Induction Filter Assy	A	1	8
9000017	PE-000-0460, Tachometer Drive Cable	IR	1	(3)
90000020-1	FLX770124001000, Induction Coupler,	A	1	(D)
90000020-2	FLX770124001200, Induction Coupler,	Α	1	(D)
90000023-1	124J002-8CR0204, Hose Assy	С	1	<b>Ø</b>
90000023-2	124J003-3CR0345, Hose Assy	С	1	(7)
90000023-3	124J001-4CR0180, Hose Assy	С	1	6
90000023-4	124J001-4CR0150, Hose Assy	С	1	(2)
90000023-5	124J001-4CR0262, Hose Assy	С	1	1
90000023-6	124J001-3CR0386, Hose Assy	С	1	(7)
9000026-2	Fresh Air Screen	Α	1	(D)
90000027-1	111417-4S0100, Hose Assy	IR	1	3
90000029	41402-16, Baffle Screw	IR	8	<b>3</b>
9000032	MW-3M-43, Rod End	Α	3	<b>②</b>



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly. IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954)

MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

PART NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
90000033-1	61CL-4, B-Nut	IR	1	
90000033-2	60C-4, 1/4 Sleeve	IR		3
90000034-1	Mixture Control Cable	F	1	3
90000034-2	Propeller Control Cable	F	1	3
90000035 -1	Throttle Control Cable	В	1	3
9000053	Riser, RH	IR	1	3
9000054	Clamp Assy (Riser)	IR	2	N/A
9000055	Collector, RH	IR	1	MA
9000056	Muffler, RH	IR	1	NIA
9000057	Tailpipe, RH	IR	1	(B)
9000058	Clamp Assy (Tailpipe)	IR	2	10
90000059	Riser, LH	IR	1	NIA
9000060	Collector, LH	IR	1	NIA
9000061	Heater-Muffler, LH	IR	1	1
9000062	Shroud Assy, LH	IR	1	1



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly. IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954)

MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

PART NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
9000063	Tailpipe, LH	IR	1	<b>②</b>
90000064	Exhaust Spring	IR	6	NA
8-320559-2	Buttsplice, (equivalent to M7928-5-3)	N/A	3	(2)
AN3-3A	Bolt	N/A	1	2
AN3C-15	Bolt	N/A	6	MA
AN310C-3	Nut	N/A	6	NIA
AN3-7A	Bolt	N/A	2	3
AN4-4A	Bolt	N/A	1	(2)
AN910-1D	Fitting	N/A	1	(27)
AN816-4D	Nipple	N/A	1	1
AN824-4D	Tee Fitting	N/A	2	1
AN837-4D	Fitting	N/A	1	2
DC736	Sealant, (meets MIL-A- 46106)	N/A	1	100
NS15795-846	Washer	N/A	2	(2)
1S20426A4-6	Rivets	N/A	30	(2



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly. IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954) MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

	ziot (Sontinued)			
PART NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
MS20426AD3-3	Rivets	N/A	40	1
MS20426AD3-4	Rivets	N/A	6	1
MS20426AD4-3	Rivets	N/A	30	<b>(2)</b>
MS20426AD4-5	Rivets	N/A	30	W
MS20470AD3-4	Rivets	N/A	37	10
MS20470AD4-5	Rivets	N/A	4	(T)
MS21042-3	Nut	N/A	56	(21)
MS21047-3	Nutplate	N/A	14	(Z)
MS21266-1N	Edge Protector (12")	N/A	1	(B)
MS21919WDG2	Clamp	N/A	2	(D)
MS21919WDG10	Clamp	N/A	1	(3)
MS21919WDG12	Clamp	N/A	1	<b>3</b>
MS21919WDG14	Clamp	N/A	2	7
MS21919WDG32	Clamp	N/A	3	(2)
IS24665-153	Cotter Pin	N/A	6	MA



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly.

IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954) MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

PART NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
MS22759/16/18	(M22759/16-18-9), Wire	N/A	3'	(21)
MS24693-C272	Screw	N/A	2	
MS2494S55	Screw	N/A	4	(D)
MS25036-148	Terminal	N/A	2	<b>多</b>
MS25274-2	Wire Cap	N/A	1	(2)
MS27039-1-10	Screw	N/A	2	3
MS35206-219	Screw	N/A	2	1
MS35207-263	Screw	N/A	55	(D)
MS35265-79	Screw	N/A	6	(D)
MS35338-40	Lock Washer	N/A	2	2
MS35338-44	Lock Washer	N/A	6	3
MS35489-11	Grommet	N/A	1	0
MS35489-134	Grommet	N/A	1	8
MS35649-244	Nut	N/A	2	6
MS35842-11	Clamp	N/A	2	(27)



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly.

IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954)

MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

PART NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
MS35842-12	Clamp	N/A	3	(2)
MS35842-13	Clamp	N/A	4	3
MS35842-14	Clamp	N/A	6	(3)
MS35842-15	Clamp	N/A	2	2
	Washer, Key	N/A	11	22
MS9276-09		N/A	2	22
NAS1149C0332R	Washer	N/A	18	NA
NAS1149C0363R	(AN960C-10), Washer	N/A	118	(2)
NAS1149F0363P	(AN960-10), Washer	N/A	6	6
NAS1149FN416P	(AN9604L), Washer	N/A	6	<b>②</b>
NAS1149F0463P	(AN960-416), Washer	N/A	8	(7)
NAS1149F0563P	(AN960-516), Washer	N/A	3	2
NAS509-3	Nut	N/A	2	2
NAS1169-DD10L	Washer	N/A	1	(2)
16000-12-004	Hose (MIL-H-6000-3/4)			



PICK LIST FOR P/N: 19051001-1, FAA-PMA Assembly. IO550P De-Turbo Engine Kit, (A/C s/n: 21059200 thru 21062954) MODEL: CESSNA T210 with STC STC-SA02107AT-D installed.

#### Section 3 - Convenience Kit

\*\*Note: These parts are not part of our PMA Kit, but are standard parts or OEM parts provided for your convenience. These parts are packaged in a separate box inside of the main box and marked as "Convenience Kit".

ITEM NUMBER	DESCRIPTION	REVISION	QTY. REQ'D.	INITIAL
Placards	Fuel Pump Switch, Fuel Flow & Propeller.	N/A	1	3
627773	Barrel Nut	N/A	4	3
CD-122-4007	Tachometer S/N: 1340	N/A	1	(2)
6331-550	Manifold/Fuel Flow Gauge S/N: 133 2 98	- N/A	1	3
27105	Loctite	N/A	1	1
SL-1	Crate Shipping Leg	N/A	2	<b>②</b>
SL-2	Crate Shipping Leg	N/A	2	(3)
J3F07700	Prop	N/A	1	(2)
C-4582-1P	Spinner	N/A	1	22
1250255-7	Exhaust Shock Mount Assy, (Cessna Aircraft Co.)	N/A	2	(2)



Pat Rogers Galveston Texas May 6, 2019

Q20190506

Ph: 409-939-5933 pappyrogers/a reagan.com

Summit Aviation, Inc. is pleased to provide a quote for a Continental Motors, Inc. (CMI) IO-550-P Tuned Induction Engine Conversion Package for your Cessna T210.

#### Engine Conversion Package Includes:

- Tuned Induction Teledyne Continental Motors IO-550-P Series Engine. A.
- New 78" Diameter Hartzell Super Scimitar Propeller and Polished Spinner B.
- STC and Associated PMA Parts Kit consisting of the following major parts: C.
  - New Cooling Baffles
  - New Induction System and Filters
  - New Alternate Air System
  - New Fluid Carrying Hoses and Flexible Ducts (standard aircraft configuration)
  - New Throttle, Mixture and Propeller Control Cables
  - 6 Point Smooth Ride Mount System STC
  - Engine Mount Brackets STC for IO550N/P Engine
  - Complete Exhaust System
  - Parts to modify cowling and existing cowl flap
  - Drawings. Installation Instructions and Supplemental Type Certificate Paperwork.
- Customer Convenience Package Consisting of the following:
  - New Tachometer and Cable
  - Overhauled Fuel Flow/Manifold Pressure Gauge (Exchange)
  - Laser Printer Placards

	** Option #1 - Tuned Induction Continental Motors, Inc. IO-550-P3 Series Engine (Zero-time, New/Exchange, 2200 Hour TBO). Engine, Prop, Spinner and STC Kit
	Additional Options:
E.	STC 'd / PMA'd Stainless Steel Headers
	Accept Decline
F.	Propeller Governor replacement with new PCU5000 Series Governor
`:	Accept Decline



#### \*\*Please note:

Pricing includes \$2,000 core differential for returning IO520 for a IO550P.

Engine core charges are collected in addition to kit price and refunded upon receipt of acceptable cores.

Note: Acceptable Cores must be returned within 45 (forty-five) days or late charges may apply.

Note: Buyer is responsible for ALL shipping / freight charges, domestic and international.

**Pricing:** Subject to change without notice. The pricing described in Individual work scopes is valid for (30) thirty days from the date of the serial number specific quote. In addition to the quoted prices, Buyer is responsible for ALL shipping / freight charges, domestic and international and tax if applicable.

Note: This STC package is designed to fit an aircraft that has a basic OEM Configuration. Any OEM or aftermarket options, alterations or modifications that affect this STC eligibility will have to be evaluated by engineering. Once the options, alterations or modifications have been evaluated, there may be additional charges for parts, labor and engineering.

#### PAYMENT TERMS

A \$10,000 deposit is required upon acceptance of this proposal. The remaining balance will be due before final release of Engine and Installation Kit by wire transfer or cashier's check

#### Signature and proposal acceptance:

Approved by:

John Ackerman

Customers Name and Title

Date: April 24th, 2019

Date: 9/11/19

Should you have any questions on the above estimate, or if we can be of any assistance, please call John at (336) 497.5517.

Summit Aviation, Inc. 1125 Spectra Ct. Kernersville, NC 27284

AS9100 Certified.

For more information about Summit Aviation, Inc. please visit our web site at http://summitaviationmfg.com/

Please submit all orders to stcinfo@summitaviationmfg.com

	Total	Time	Time Since Last Overhaul	Engine Service and Maintenance Record
Date	Hours	Min	Hours Min	Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	C	Winedo	ry Service Inc	
		West Ho	reston Airport	
		House	m, TX 77064	
	DATE: 02/1		NICORG TACHE	32162
VORK PERFORM	ED: AIRFR	AME		
			OLATOR FWD ENGI LESS STEEL EXHAU	NE MOUNT SYSTEM
· C/W COV	L OIL DOG	MAR ACTU	ATOR	CTTNO ON POOR
· C/W STC	SA02107AT	D - INSTA	I LED NEW ENGINE	
· INSTALL	ED NEW TA	ACH AND 1	P-SSO-P) FACH CARER	
• INSTALL	ED NEW FA	F MANIFO	LD PRESSURE GUAG ND AUX FUEL PUMP	GE
- EGIVIT	LU DIGITA	L TACH S	LV@UD	
LASIALL	LU RADIOS	S – OPS HE	W AND SECURED RO CKED GOOD	
• INSTALL	ED NEW DI ORMAL AN	ODE IN LA	INDING GEAR SWITT	CH. C/W OPS CHECKS
• REPLACI	LD NEW EN LD ENGINE	TO AIRFE	NTROL CABLES LAME CROUNDING S	PTD 4.D
INSTALL     LUBED H	ED NOSE B	OWI. MW	LINC BLOCK OFF B	PLATE
<ul> <li>MODIFEI</li> </ul>	COWL FI	AP		
				rith 14 CFR 43 and was
THE PERSONS AND PARTY OF THE PA	e inc.	lepair Statio	on under WOy 29279	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
AA Certified Rep o. GK2R849K	sir Station signed		TA 11.7	
	-		- pwi	
	4 - ' 1	132.4	Trans.	40
- Z				· · · · · · · · · · · · · · · · · · ·
Cessre	<u>C</u>	alkin	v Aero Servi	ice Inc
		V	Vest Houston Airport 8000 Groeschke R4.	
			Houston, TX 77084	
	DATE	Z: <b>02/10/20</b> 2	0 N100BG 1	TACH: 3216.2
WORK PERI	ORMED: F	NGINE		There sales
• REN	OVED PRO	PELLER	AND ENGINE	
-	- 144	VI SIRA	R-PLI MINERVIAL CHI	RAL OIL AND 3 QTS AERO
• Cw	STC SE025	25AT - IN	STALLED NEW ENG MODIFICATION	EINE MOUNT BRACKETS
• C/W	FUEL PUM OR ALTER	IP ELECTI	RICAL MODIFICATI	ION (NEW WIRE HARNESS
• C/W	ENGINE S	IC DURIN	G ENGINE RUIT IN IT	
• C/W	COWL FLA	<b>LP MODIF</b>	ICATION SCAT VENT HOSE	
• INST	ALLED TA	JLPIPE EX	CHAUST HANCEDS	
• C#	LOST WOR	JITICA I IC	ER COWLING EXHA	N CUPCUPA AVARAGE TO THE TOTAL THE TOTAL TO THE TOTAL TOT
- 11431	ALLED JP	LOGINE	MONITOR F/F TO AN	NSDUCER
• REL	OCATED L	EFT HANT	OLER BAFFLE EXHAUST HANGE	<u></u>
• RESI	IAPED CR. AMPS	ANKCASE	BREATHER AND SE	ECURED WITH ADEL
• C/W	FUEL AND	PRESSUR T MANUA	E CHECKS - CHECK L M-16 8-10PSI)	KED GOOD. (SPECS FOUND IN
• I cer	ify that the	work perfe	r M-10 9-10L2()	lin according to the comment
Details on file a	t Calkins A		in an airworthy condi Station under WO# 2	
Calkins Aero S FAA Certified	ervice Inc.		- Statute Bader WOR 2	

Annual INST Engine Service and Maintenance Record Time Since Last **Total Time** Overhaul Record maintenance actions including engine part removal and Date installation and compliance with inspections, Airworthiness Directives. Min Hours Min Hours Special Inspections, Modifications and Service Bulletins Carried forward induction & exhaust systems performed compression, IAN SFRM up checked mag drop, NO Idaks. Corany una: this ENGINE has been inspected in accordance with an Anmus inspection and was determined to be in an airworthy condition\_Man Access ASPIATE IN LA 3701197 Phanaer oil filter with Phillips 20 mgo 10 ats. Filter Continental # 659755. Paners 20 hrs 1/27/2020 20 his 100 leaks absorved, Return TO GEXVICE. 11/4/12 57 12

2

	_	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record			
	3/28/21	Hours	Min	Hours	Min	Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins			
	Carried forward -		<b>-</b>						
	-Ch	A A	red	0	1 4	1. Ver. with CH48109-1			
-	- chi	(gre	in	P.	(tex	- 100ts Nevo Chell 4/2 20-50			
-	10	40	Ans.	au	mo.	Washed eno KANUA			
-	069	et ve	~ 2	No	100	ss returned to sorvico.			
-									
1						PA Royers			
1				A	50	462872556			
-					• '				
-									

06/03/21 N100BG Cessna T210L S/N 21060633 Continental IO-550-P S/N 1038377 Tach 86.7 TTE 86.7

Comply with 100 Hour/Annual inspection per scope and details of FAR 43 Appendix D. Oil and filter previously changed. Compression checked: #1-70/80 #2-65/80 #3-70/80 #4-66/80 #5-65/80 #6-engine controls. Engine ground run with operations normal and no leaks noted. AD's checked thru date and complied with as noted in AD Summary Listing provided.

I certify that this Engine has been inspected in accordance with a 100 Hour/Annual inspection and was determined to be in an Airworthy condition on this date.

AIR	DD	0	CE (	CI	^	N	A	C
MIL		u		2.71	u	м	-	

PEARLAND REGIONAL AIRPORT (281) 992-3484

RANDY WAHLBERG A&P 3563642IA

1/7/22 1263
Obanges o'il - filter, Installed
Unong # CH48 99-1 - 10 0+4 Phillips
20 450. Ran up ena, observed No lepke
returned to gervice.

PARcageg

Air 94628426566

	Total	Time	Time Sir	nce Last rhaul	Engine Service and Maintenance Record
Date	Hours	Min	Hours	Min	Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
arried forward -		-			
4/29/22	152.0	•			Inatelled Door Stevent
101100					15 BEV. Bote i Rip Starter
					That starter inturned
					TO SON VICE END
					10 PE 462842556
					· Of Regar
460/22	152	6			Ri R Startin AH 646271-1
1104/10	,,,				√ × -139 278 useines
					good chas proches returned
					to Ber DA Paren
					nie 462840556
5/13/22	18.1	10			CR COM DIESSION 1-68/80
71210	1,000				270100 272100 4-70180
					E-109/00 (0-107/00)
					Trace to the same
					10 speer to this end to
	-+				the like word to got
			-+		Air PARODENS
			-		,
1-/10	.00	-		-+	and a life of the
75/22	90	-			Charles of the state of
					INSTALLS TONDEST # AND 48101
					2 10gts phillips 20w50
			-		Chrised oil i filter INSTALLE tempe 52 # AND 48109 and 10gts phillips 20050 pupt of Can grande Romena found kio lepter returned to crevice.
					Romena tour kio leste
					refused to exprice.
					12 146284 2556
					121 46284 2556
					, 1
					ı
	+	_	+	_	

_	Total Time Time Since Last Overhaul			nce Last rhaul	Engine Service and Maintenance Record		
Date	Min	Hours	Min	Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins			
Hartzell Ph Performed engine ma tested spa orifice = 46 this engine	ISJCYF SA ISJCYF SA I 100 hou intenance rk plugs. Spsi. Eng e has bee	FP S/N: FP9! Ir/ annume e and of Compressione rungen inspe	1038377 560B TS Dal inspective thau I in essions control in the co	TSO: 1 N: 194.9 Stion and manual a hecked # rational c ording to	d servicing according to Continental IO550 Permold series and the scope and detail of FAR 43 Appendix D. Cleaned & 1=70, #2=72, #3=71, #4=72, #5=69, #6=66/80 psi. Master checks performed with no discrepancies noted. I certify that FAR 43 15(a)(1)(c)(1)(2) for an annual inspection and was esept G Sills IA405867971		
	1	ı	1 :	,			
Flori							
11/14	24.2				4D. 2023-05-16 is not applicably		
Tach	711.2		-		by engine model. 6 on pression +cst		
TSNOT:	YII.2				1/16 x) 64 3/10 7/6/ 2/6/		
					with him and the line		
					edges Transferrer that this ende		
					was inspected in a scardance		
					with a lookour inspection and		
					was determined airmently.		
					AP3333065 (Nel		
				/			
0/28/	24				Replaced Bottery resident Concord 74V Promise Batt, jep) seed MAIN Contractor, Retierness		
, ,					Conscord 74V Promin		
					Batt, jep/reed MAIN		
					CONTOPITOR, Meternist		
					462842556		
					1 Redice		
					462842556		
1							

